



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : SKB8478L

Date of Accident : 20 April 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Hi Power Pte Ltd

Date : 21 April 2018

Estimate To Repair SLB1774R - Toyota COROLLA ALTIS 1.6 AUTO
Chassis No : MR053REH104546054

66 - Marcus

23/04/18 @ 1045h

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>DO/AC</i>	\$ 486.50
02	2 ps	rear bumper reflectors @ \$58.00 <i>17</i>	\$ 116.00
03	2 ps	rear bumper side retainers @ \$120.00 <i>17</i>	\$ 240.00
04	2 ps	rear bumper side holders @ \$80.00 <i>17</i>	\$ 160.00
05	6 ps	rear bumper clips @ \$4.30 <i>17</i>	\$ 25.80
06	1 pc	rear bumper absorber foam with rod <i>MS</i>	\$ 395.00
07	2 ps	rear bumper brackets @ \$68.00 <i>17</i>	\$ 136.00
08	2 ps	rear lamp lower bracket @ \$38.00 <i>17</i>	\$ 76.00
		Less 25 % <i>Rear bumper reinforcement DO</i>	\$ 1,635.30
			\$ 408.83
			\$ 1,226.47
<u>SPECIAL NETT ITEMS</u>			
09	1 set	rear bumper parking sensor <i>slashed</i>	\$ 450.00
			\$ 450.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To check electrical lighting concerned.	\$ 40.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same and rear end panel.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 600.00
			\$ 1,260.00
		Total	\$ 2,936.48

LKH Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

NOT APPROVED
LKH

take photo separately
23/4/18.

3 sh.

P/P

✓
X
X
✓
X
X

200

50
20
300
450