


FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D



FALCON-AIR

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA


Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	TAILGATE		
2.	1	TAILGATE GLASS		
3.	1	TAILGATE GLASS MOULDING		
4.	1	TAILGATE LOCK - photo		
5.	1	TAILGATE WEATHERSTRIP		
6.	1	TAILGATE CHROME		
7.	1	TAILGATE EMBLEM 'JAZZ'		
8.	1	TAILGATE INNER TRIM BOARD		
9.	2	TAILLAMP LH/RH		
10.	2	TAILGATE GARNISH		
11.	2	REAR FENDER TRIMBOARD		
12.	1	REAR END PANEL - photo		
13.	1	REAR END PANEL TOP GARNISH		
14.	1	SPARE TYRE PANEL BOARD - photo		
15.	1	REAR BUMPER		
16.	2	REAR BUMPER SIDE RETAINER LH/RH		
17.	1	SPARE TYRE PANEL		
18.	1	REAR BUMPER GARNISH		
19.	1	EXHAUST HEAT SHIELD		
20.	1	BONNET		
21.	1	REAR TOP CARGO TRAY		
22.	1	TOOLS COMPARTMENT/ SPONGE photo		

bt	814.00	/
cre	625.60	/
ner	95.00	/
jw	157.10	/
twi	92.30	/
drs	193.80	/
na	33.00	/
ent	62.10	/
214.70 cre	429.40	/
97.80 ?	195.60	/
165.60 > de	331.20	/
bt	314.00	/
de	60.80	/
ch	186.00	/
de	492.60	/
13.00 na	26.00	/
Rx	697.00	/
de	18.00	/
bt	527.00	/
ent	203.50	/
de	101.65	/

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2	BONNET HINGES LH/RH	24.90	49.80 <i>bt</i>
24.	2	HEADLAMP	1,118.60	2,237.20 <i>Cre</i>
25.	1	RADIATOR SUPPORT PANEL		374.30 <i>bt</i>
26.	1	RADIATOR		1,187.40 <i>bt</i>
27.	1	AIRCON CONDENSER		704.40 <i>dd</i>
28.	1	BONNET LOCK		99.70 <i>bt</i>
29.	2	HEADLAMP LOWER BRACKET LH/RH	24.00	48.00 <i>Cre</i>
30.	1	FRONT GRILLE ASSY		288.90 <i>Cre</i>
31.	1	FRONT BUMPER		494.70 <i>de</i>
32.	2	FRONT BUMPER SIDE RETAINER	11.00	22.00 <i>Cre</i>
33.	1	FRONT BUMPER REINFORCEMENT		219.40 <i>bt</i>
34.	1	FRONT BUMPER LOWER GRILLE CENTRE		27.50 <i>de</i>
35.	2	FOG LAMP GARNISH <i>LH-de, RH-XM</i>	23.30	46.60 <i>22-2 de</i>
36.	1	FRONT NUMBER PLATE BASE		50.90 <i>de</i>
37.	2	REAR FENDER	659.30	1,318.60 <i>Rx</i>
38.	2	TAILLAMP PANEL LH/RH	95.30	190.60 <i>2 plus</i>
List TotalS\$:				13,031.65
20.00% Discount S\$:				2,606.33
				10,425.32
1.	3	SPECIAL NETT ITEMS : SEALANT	40.00	120.00 <i>40</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REVERSE SENSOR (4PCS)		250 ✓ 300.00 <i>nm</i>
3.	1	REAR CAMERA, CONNECTION WIRES & INSTALLATION		600.00 <i>500dis</i>
4.	1	FRONT NUMBER PLATE		45.00 <i>6k</i>
5.	20	ASSORTED CLIPS	3.00	60.00 <i>19</i>

Special Nett Total S\$:

1,125.00

LABOUR :

TOWING CHARGE

70.00 *60*

TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS

120.00 *100*

TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM

30.00 *20*

TO TRANSFER TAILGATE PARTS/MECHANISM

50.00 *40*

TO REMOVE/REPLACE REAR WINDSCREEN GLASS

120.00 *100*

TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING

150.00 *100*

TO RUSTPROOF ON ACCIDENT DAMAGE AREAS

150.00 *100*

TO REALIGN EXHAUST BOX / PIPE

80.00 *60*

TO REMOVE / REPLACE REVERSE SENSOR/ CAMERA CHECK WIRING

120.00 *860*

SPRAY PAINTING FRONT PORTION

800.00 *700*

TO CUT/OUT REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT

650

CHASSIS, FRONT FENDERS LHRH INCLUDES KNOCKING &

750.00

REPLACEMENT OF PARTS

1,600.00 *1400*

SPRAY PAINTING REAR ACCIDENT DAMAGED AREAS

80.00 *700*

TO REMOVE/REFIX PETROL TANK TO FACILITATE THE REPAIRS

TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL,

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862


Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D



FALCON-AIR

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REAR FENDER RH/LH, TAIL LAMP PANEL, REPAIR FLOORBOARD
 REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS
 TO REMOVE/ REFIX REAR FENDER GLASS \$80 X2

Repair fender - 1100
Replace fender - 1500
 1,800.00
 160.00
 6,080.00

Labour Total S\$:

*Supplementary.

PASSENGER SEAT FRAME
 PASSENGER SEAT GARNISH SIDE
 PASSENGER SEAT GARNISH COVER A
 PASSENGER SEAT GARNISH COVER B
 PASSENGER SEAT GARNISH LOWER COVER

15.00

bt 928.30
 de 21.00
 de 20.00
 de 15.00
 de 30.00

TO REMOVE/REPLACE LH PASSENGER FRONT SEAT, GARNISHES
 AND TRANSFER LH PASSENGER SEAT CUSHION

✓ 150.00

Taufik 97495747
wp
20/4/18 @ 1530
Resurvey before paint
sent to lkh auto.wm
15 days

E. & O.E.

Total S\$:

17,630.32



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: