



FALCON-AIR

WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department
Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE	bt 814.00	
2.	1	TAILGATE GLASS	cre 625.60	
3.	1	TAILGATE GLASS MOULDING	ner 95.00	
4.	1	TAILGATE LOCK - photo	jur 157.10	
5.	1	TAILGATE WEATHERSTRIP	twi 92.30	
6.	1	TAILGATE CHROME	dis 193.80	
7.	1	TAILGATE EMBLEM 'JAZZ'	na 33.00	
8.	1	TAILGATE INNER TRIM BOARD	ent 62.10	
9.	2	TAILLAMP LH/RH	214.70 cre 429.40	
10.	2	TAILGATE GARNISH	97.80 ? 195.60	
11.	2	REAR FENDER TRIMBOARD	165.60 ? 331.20	
12.	1	REAR END PANEL - photo	bt 314.00	
13.	1	REAR END PANEL TOP GARNISH	de 60.80	
14.	1	SPARE TYRE PANEL BOARD - photo	de ? 186.00	
15.	1	REAR BUMPER	de 492.60	
16.	2	REAR BUMPER SIDE RETAINER LH/RH	13.00 na 26.00	
17.	1	SPARE TYRE PANEL	Rx 697.00	
18.	1	REAR BUMPER GARNISH	de 18.00	
19.	1	EXHAUST HEAT SHIELD	de 16.00	
20.	1	BONNET	bt 527.00	
21.	1	REAR TOP CARGO TRAY	at 203.50	
22.	1	TOOLS COMPARTMENT/ SPONGE photo	de 101.65	

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department
Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2	BONNET HINGES LH/RH	24.90	49.80 <i>bt</i>
24.	2	HEADLAMP	1,118.60	2,237.20 <i>Cra</i>
25.	1	RADIATOR SUPPORT PANEL		374.30 <i>bb</i>
26.	1	RADIATOR		1,187.40 <i>i</i>
27.	1	AIRCON CONDENSER		704.40 <i>dd</i>
28.	1	BONNET LOCK		99.70 <i>bt</i>
29.	2	HEADLAMP LOWER BRACKET LH/RH	24.00	48.00 <i>ava</i>
30.	1	FRONT GRILLE ASSY		288.90 <i>ave</i>
31.	1	FRONT BUMPER		494.70 <i>de</i>
32.	2	FRONT BUMPER SIDE RETAINER	11.00	22.00 <i>ave</i>
33.	1	FRONT BUMPER REINFORCEMENT		219.40 <i>bt</i>
34.	1	FRONT BUMPER LOWER GRILLE CENTRE		27.50 <i>de</i>
35.	2	FOG LAMP GARNISH <i>LH-de, RH-?</i>	23.30	46.60
36.	1	FRONT NUMBER PLATE BASE		50.90 <i>dp</i>
37.	2	REAR FENDER	659.30	1,318.60 <i>Rx</i>
38.	2	TAILLAMP PANEL LH/RH	95.30	190.60 <i>? plus</i>
List TotalS\$:				13,031.65
20.00% Discount S\$:				2,606.33
				10,425.32
1.	3	SPECIAL NETT ITEMS : SEALANT	40.00 <i>40</i>	120.00

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

WYSA CARS

194 WESTWOOD AVE #08-30

WESTWOOD RESIDENCES SINGAPORE 648152

Attention : Motor Claim Department

Contact : 98183836

Estimate : ES003160

Date : 20/04/2018

Vehicle Num. : SLQ9887S

Make/Model : HONDA JAZZ

Chassis/Eng# : JHMGK5850FX202582

Accident Date : 19/04/2018

Claim No. :

Reference : TP NTUC VS AXA

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1	REVERSE SENSOR (4PCS)		250 300.00 <i>nu</i>
3.	1	REAR CAMERA, CONNECTION WIRES & INSTALLATION		600.00 <i>500.00</i>
4.	1	FRONT NUMBER PLATE		45.00 <i>bf</i>
5.	20	ASSORTED CLIPS	3.00	60.00 <i>19</i>
Special Net Total S\$:				1,125.00
LABOUR :				
TOWING CHARGE				70.00 <i>60</i>
TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS				120.00 <i>100</i>
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM				30.00 <i>20</i>
TO TRANSFER TAILGATE PARTS/MECHANISM				50.00 <i>40</i>
TO REMOVE/REPLACE REAR WINDSCREEN GLASS				120.00 <i>100</i>
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING				150.00 <i>100</i>
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS				150.00 <i>100</i>
TO REALIGN EXHAUST BOX / PIPE				80.00 <i>60</i>
TO REMOVE / REPLACE REVERSE SENSOR/ CAMERA CHECK WIRING				120.00 <i>860</i>
SPRAY PAINTING FRONT PORTION				800.00 <i>700</i>
TO CUT/OUT REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS, FRONT FENDERS LH/RH INCLUDES KNOCKING & REPLACEMENT OF PARTS				750.00 <i>650</i>
SPRAY PAINTING REAR ACCIDENT DAMAGED AREAS				1,600.00 <i>1400</i>
TO REMOVE/REFIX PETROL TANK TO FACILITATE THE REPAIRS				80.00 <i>7</i>
TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL,				

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**WYSA CARS
194 WESTWOOD AVE #08-30
WESTWOOD RESIDENCES SINGAPORE 648152Attention : Motor Claim Department
Contact : 98183836

Estimate : ES003160

Date : 20/04/2018
Vehicle Num. : SLQ9887S
Make/Model : HONDA JAZZ
Chassis/Eng# : JHMGK5850FX202582
Accident Date : 19/04/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REAR FENDER RH/LH, TAIL LAMP PANEL, REPAIR FLOORBOARD REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT OF PARTS TO REMOVE/ REFIX REAR FENDER GLASS \$80 X2		
				1,800.00
				160.00
		Labour Total S\$:		6,080.00

*Repair fender - 1100**Replace fender - 1500*

Taufik 97495747
wp
20/4/18 @ 1530
Resurvey before paint
sure@lkkauto.com
15 days

E. & O.E.

Total S\$: 17,630.32

=====



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg