

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

The Manager
Motor Claim Department
AXA Insurance Pte Ltd
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Allowed
nkr
p/p/s
The photo below only
6/2/18
23/4/18

Date of Accident : 19th April 2018
Location : AYE
Third Party Claim Vehicle No : SJX 1933 G
Repair Cost For Vehicle No : SFX 868 R Mazda 2

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>Good</i>	1	911.70	\$ 911.70 ✓
2	Rear boot cover emblem (logo) <i>rec</i>	1	58.00	\$ 58.00 ✓
3	Rear boot cover emblem (mazda 2) <i>rec</i>	1	55.00	\$ 55.00 ✓
4	Rear boot cover emblem (skyactiv) <i>rec</i>	1	64.00	\$ 64.00 ✓
5	Rear boot cover reflector L&RH	2	221.00	\$ 442.00 ?
6	Rear boot lock <i>Two/ym</i>	1	202.00	\$ 202.00 ✓
7	Rear boot cover catch <i>11</i>	1	38.00	\$ 38.00 x
8	Rear boot wiper motor <i>11</i>	1	318.00	\$ 318.00 x
9	Rear windscreen glass with moulding <i>rec</i>	1	878.00	\$ 878.00 ✓
10	Rear lamp assy L&RH	2	728.00	\$ 1,456.00 ?
11	Rear end panel	1	380.00	\$ 380.00 ?
12	Rear lamp panel inner garnish <i>Two</i>	1	74.00	\$ 74.00 ✓
13	Rear lamp panel inner garnish clips <i>11</i>	1set	48.00	\$ 48.00 x
14	Rear bumper fascia <i>D.S</i>	1	850.00	\$ 850.00 ✓
15	Rear bumper clips <i>rec</i>	1set	48.00	\$ 48.00 ✓
16	Rear bumper bracket L&RH <i>Kap</i>	2	18.00	\$ 36.00 ✓
17	Rear bumper side retainer L&RH <i>3000</i>	2	28.00	\$ 56.00 ✓
18	Rear boot floor panel <i>n</i>	1	836.00	\$ 836.00 x
19	Rear tool tray <i>Thin</i>	1	143.00	\$ 143.00 ✓
20	Rear exhaust silencer assy	1	1,053.00	\$ 1,053.00 ?
				\$ 7,946.70
Less			20%	\$ 1,589.34
				\$ 6,357.36

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SFX868R/1804076

20th April 2018

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 6,357.36
21	Rear bumper sensor (s/net) <i>shw 6</i>	1 set	380.00	\$ 380.00 <i>200</i>
22	Rear windscreen sealant (s/net) <i>ner</i>	1	60.00	\$ 60.00 <i>40</i>
23	Rear end panel sealer (s/net) <i>ner</i>	1	80.00	\$ 80.00 <i>50</i>
24	Rear number plate (s/net) <i>bul</i>	1	50.00	\$ 50.00 <i>40</i>
25	Rear boot insulator shield (s/net) <i>u 1</i>	1	380.00	\$ 380.00 <i>X</i>
				<u>\$ 7,307.36</u>

Labour Charges :-

	Amounts
Towing fee	\$ 80.00 <i>60</i>
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, rear fender L&RH, remove & install all damage parts, straighten & re-align body	\$ 1,880.00 <i>800</i>
Remove & install rear windscreen glass	\$ 120.00 <i>✓</i>
Remove & refix rear bumper sensor	\$ 80.00 <i>50</i>
Remove & install rear exhaust silencer to facilitate repairs	\$ 100.00 <i>60</i>
Tuff-kote on damage parts	\$ 120.00 <i>60</i>
Remove & install rear seats, upholstery & etc	\$ 380.00 <i>80</i>
Spray painting on damage parts	\$ 1,800.00 <i>1200</i>
Diagnostic & reset	\$ 320.00 <i>?</i>
Check all lighting after repairs	\$ 40.00 <i>30</i>
Labour Charge	<u>\$ 4,920.00</u>
Total Amount	<u>\$12,227.36</u>

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.