



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT18001620	Page	1
	100 BEACH ROAD	Date	: 19. Apr 2018		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: NG SIN HAI		
Registration No	: SKT8674S	Engine No	: L15Z71000196		
Chassis No	: MRHRU1830FP000169	Date Time	: 19. Apr 2018 2:20:05 PM		
Model	: HRV LX CVT YM 2015	Surveyor Name	:		
Owner's Name	: CHONG PEI LAN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 18/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:CHONG PEI LAN						
	OWNER INSURER:AVIVA LTD						
	ACC DATE:18/04/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:LONPAC INSURANCE BHD						
	TP VEH:SDQ2868M						
71101-T7J-H00ZZ	FACEFR.BUMPER	1	466.20	Repair 25	349.65	24.48	374.13
71102-T7W-A00	FACEFR.BUMPER LOWER	1	133.90	X 25	100.42	7.03	107.45
71103-T7J-H00	GRILLEFR.BUMPER LOWER	1	71.50	X 25	53.62	3.75	57.37
71110-T7A-000	SPOILERFR.BUMPER AIR	1	50.00	X 25	37.50	2.63	40.13
71121-T8N-P50	BASEFR.GRILLE	1	190.00	X 25	142.50	9.98	152.48
71122-T8N-T50	MOLDINGFR.GRILLE	1	130.80	X 25	98.10	6.87	104.97
71123-T8N-T00	BARR.FR.GRILLE MOLDING	1	57.20	X 25	42.90	3.00	45.90
71128-T8N-T00	BARL.FR.GRILLE MOLDING	1	57.20	X 25	42.90	3.00	45.90
75700-TA0-A00	EMBLEMFR.	1	25.90	X 25	19.42	1.36	20.78
71151-T7J-H00	BEAMR.FR.GRILLE SIDE UPPER	1	4.50	? 25	3.37	0.24	3.61
71130-T8N-T00ZZ	BEAM COMPFR.BUMPER	1	249.60	? 25	187.20	13.10	200.30
71140-T7A-000	BEAMR.FR.BUMPER UPPER	1	23.90	?X 25	17.92	1.25	19.17
71193-T7A-000	SPACERR.FR.BUMPER SIDE	1	10.40	ne 25	7.80	0.55	8.35
71198-T7A-000	SPACERL.FR.BUMPER SIDE	1	10.40	X 25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	18	2.00	ne 25	27.00	1.89	28.89
33100-T7S-T51	HEADLIGHT ASSY,R.	1	348.20	? 25	261.15	18.28	279.43
	Sum Item				1399.25	97.96	1,497.21
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00	X	380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	330.00	X	330.00	23.10	353.10

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

Registration No : SKT8674S

Chassis No : MRHRU1830FP000169

Model : HRV LX CVT YM 2015

Owner's Name : CHONG PEI LAN

Ins Policy No. :

Date of Accident : 18/4/2018

Document No. : SQT18001620 Page 2

Date : 19. Apr 2018

Customer No. : WZL009

Svc Advisor : NG SIN HAI

Engine No : L15Z71000196

Date | Time : 19. Apr 2018 2:20:05 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	1500.00		1500.00	105.00	1605.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	1000.00		1000.00	70.00	1070.00
Sum Labor					3490.00	244.30	3,734.30

Survey By

Date & Time

Excess

Status

Signature

Rashid - Hp 90010068

08/05/18 @ 1400

4 days

Reg after repair

Total Amount 4,889.25 342.26 5,231.51

Total (Inclusive of GST) 5,231.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/4/2018 7:40:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)