Not Mahorw		Not phone	
FASTECH AUTO PTE LTD		23/4/18	
1 KAKI BUKI	T AUENUE 6	1 - 1/10 -	16
#01-48 AUTO	DBAY	9/18/480	10
SINGAPORE		- 2 den	,
ontor ii or ii		1.1.0	
VEHCILE NO:S	SKE 1716E	23/4/18.	
QTY	PARTICULAR	AMOUNT	
1 PCS	TAILGATE will		\$1,100.90 🖔
1 PCS	TAILGATE 'VEZAEL' EMBLEM	11	\$56.20 X
1 PCS	TAILGATE WEATHERSTRIP	11	\$135.70 🗶
1 PCS	REAR BUMPER CENTRE		\$762.70 /
2 PCS	REAR BUMPER SIDES@\$230.10		\$460.20 ×
1 SET	REAR BUMPER CLIPS		\$ 50.00
1 PCS	REAR END PANEL	R	8 £17:00 ×
	S.NETT		
1 SET	REAR BUMPER REVERSE SENSOR	Short	\$280.00 20
	REAR WINDSCREEN SEALANT		\$50.00 🗸
	LABOUR CHARGES:		
	TO CHECK WIRING		\$60.00 20
	TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00 50
	TO DISMENTLE & REFIX REAR WINDSCREE		\$120.00 ×
	TO DISMENTLE & REFIX SEAT, CUSHION UP		\$120.00 60
	TO SPRAY RUST PROOFING	٨N	\$50.00 X
	LABOUR FOR PANELBEATING & REPLACING	G PARTS	\$600.00 30
	TO PUTTY & SPRAY PAINTING		\$680.00 200
		TOTAL	\$4,662.50

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal nodification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-812.70 202 650.16 1480.16