

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0495/2018/GW
Date : 26-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kim Choo Han
Address : 5B Balmoral Park
#06-05, Solitaire

Telephone : HP +65 97377958
Type of Claim : Third party claims
Policy No. : 2100381999-03000
Vehicle No : **SKN 6463 D**
Model Code : Audi A4 1.8 TFSI Mu
Model / Year : Jun-14
Engine No : CJE 077447
Chassis No : WAUZZZ8KXEA122273
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Apr-18
Place of Accident : After Turning From Orchard Road To Bideford Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 6463 D.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer lhs rear door's multi-lock system and power window devices.	S/N \$ 280.00 X
2	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
3	To disassemble and renew lhs door and rear bumper. Repair lhs rear fender. Reinstall all parts removed.	\$ 2,100.00 ⁷⁵⁰ 500
4	To respray lhs rear door, lhs rear fender and rear bumper.	\$ 2,300.00 ¹⁶⁵⁰
5	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 5,432.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 6463 D.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR DOOR -LH <i>Regis</i>	\$ 2,509.00	X
2	REAR DOOR ATTACHMENT PARTS-LH	\$ 72.00	X
3	REAR DOOR OUTER DOOR SEAL-LH	\$ 192.00	X
4	BONDING AGENT	\$ 43.00	X
5	CLEANING SOLUTION	\$ 64.00	X
6	REAR DOOR CATCH-LH	\$ 105.00	X
7	REAR BUMPER <i>del d</i>	\$ 2,038.00	✓
8	REAR BUMPER GUIDE SECTION- LH	\$ 37.00	X
9	REAR BUMPER UPPER GUIDE SECTION-LH	\$ 20.00	X
10	REAR ALUMINIUM RIM-LH <i>cat</i>	\$ 659.00	✓
11	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		\$ 5,939.00	:
TOTAL LABOUR CHARGES		\$ 5,432.00	
GRAND TOTAL		\$ 11,371.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian*
Surveyed Date : *26/04/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised*

Auto Consultants hence notify
Repairer of the following:
Resurvey before/after spray painting
To display damaged part(s) during resurvey
Prices are subject to confirmation
Party survey is on a "Without Prejudice" basis
Legal modification(s) is allowed
Accessory item(s) must be resurveyed and
Subject to final approval from Insurance Company

OK

Knownledged by Repairer
Signature:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant