

PDI TUAS

PDI TUAS

LIM TIONG GUAN
(LIN ZHONGYUAN)
635A PUNGGOL DRIVE
#08-617
Singapore, 821635
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV033196
Quote No. SER/QUO/1800702
QuoteDate 23/04/18
Salesperson Ian Lim
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	29,838	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLB1020H	VWVZZZAUZGW053450	28/03/16	Ian Lim
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 053336	5G12BZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	3	UNIT		840 2,520.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				5,680.00
P 5G6807417APGRU	- REAR BUMPER	1	Pieces		Repair 1,149.75
	Predecessor 5G6807417ARGRU				
P 5G6807568B 9B9	RDIFFUSOR REAR SPOILER	1	Pieces		cut 273.07
	Sum Item				1,422.82

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Explanations

P - Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No.:

Sum Labor 5,680.00
Sum Item 1,422.82
Total SGD 7,102.82
7% GST 497.20
Total SGD Incl. GST 7,600.02

Rasul
4p 900/10068
3 days
25/04/18 @ 1225
Resurvey after repair