

Surveyor
Muhd

REF: CS3 / MS6117023597 / G 10-1

Special Instruction:

From (Person): Muhd Ashik of MS16 Date/Time: 19042018
Estimated Cost: Bill to:

US: \$ 35500.00

Third Parties:

Claimant:

Surveyor: Kent Auto

Workshop: PEON Auto

OD / (TP Re-inspection) / Evaluation

To Inspect Vehicle No: SKE 7857S Insured: SJQ 6689R
at Workshop m/s Kent Auto Tel: 6741 2539
of 2 Kaki Bukit Ave 2 #01-21

Policy No: Claim No: 540443

Sum Insured: Excess:

Make of Veh: D.O.A. 09.12.2017
(Client's Record)

24042018 (Tuesday) @ 2pm

Do Not Find
H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 12 days)

Date/Time: Submit Final Fig 20800, 8 days (Red \$ 14700 / 41 %; Original _____ days)

Date/Time	Action/Instruction
	SKE 7857S - CS3 / MS6117023597 / W62J
	SJD 6689R - X
	DA 091217
	MV: \$85K, LTA: \$65,900.00, NR: \$19,100.00
	Submit TP-Reinspection report.
	RECEIVED 23 MAY 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value : _____		Basic & Add	
Nett Value : _____		Transport	
		Photos	
		Others	
		Total	

1) Date/Time by 23/5/18 File Pass to typpast 2) Date/Time File Return to _____
3) Date/Time File Pass to _____ 4) Date/Time File Return to _____
5) Date/Time File Pass to _____ 6) Date/Time File Return to _____

PRS
Wilson

REF: MSIG

ASSIGNMENT

From: _____ Date: 13/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKE7857S

at Workshop m/s Kent Auto Services

of Blk 2 kaki Bukit Ave 2#01-21

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKE7857S Regn: 30/3/2012

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Jaguar No: 2967

Colour: white A/C: Insured / Std / NI / NA

Sp Reading: 138601 T. Radio: Insured / Std / NI / NA

Eng No: _____

C/No: SAJACOSD&CFS39094

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R18
R: 245/45 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Pirelli (LF)

Front: _____ Rear: _____

R/Bal: 4 mm R/Bal: 4 mm

L/Bal: 4 mm L/Bal: 4 mm

D.O.A. 9/12/2017 P.O.I. 13/12/17

Survey held at: As Above @ 10.26am

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Range #17900 - #18900

Healthamp. of 1880 SJW 9521 P SKD 8204A

RECEIVED 09 APR 2018

[Signature]
9/12/2017

Date/Time File Pass to? : Prel. Report

1) 09042018 : Final Report

Date/Time File Return to? _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee	120
Transporter	50
_____	_____
_____	10
_____	_____
_____	180

Add Fee: Site Insp (\$)

Interview (\$)

Tech Insp (\$)

Weekend (\$)

Report Format: PRS.

Lump Sum / I.B.I: (\$)

Catherine Chong (LKK Auto)

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Thursday, 19 April, 2018 3:09 PM
To: Muhd Ashik B Madi; SUR; assignments
Cc: Daniel Poon & Co.
Subject: RE: URGENT Our Ref: DP.10268.17.KAS Your Ref: 540443

Dear Muhd Ashik,

Thank you for the assignment.

Dear Catherine,

FYNA.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhd Ashik B Madi [mailto:ashik_madi@sg.msig-asia.com]
Sent: Thursday, 19 April 2018 3:05 PM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Daniel Poon & Co. <law@dpco.com.sg>
Subject: FW: URGENT Our Ref: DP.10268.17.KAS Your Ref: 540443

Dear Shiau Chan,

Please refer to the email below for a re-inspection assignment.

We will be assigning via Merimen shortly.

Dear Sirs,

Thank you for your email of even date.

We will arrange for our surveyor, M/s LKK Auto Consultants to attend to the re-inspection.

Ashik Madi
Executive, Claims Services (Motor)
D: +65 6594 2548 | F: +65 6225 7402 | ashik_madi@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg   

From: Daniel Poon & Co. [mailto:law@dpcoco.com.sg]
Sent: Thursday, 19 April, 2018 2:38 PM
To: Muhd Ashik B Madi <ashik_madi@sg.msig-asia.com>
Subject: URGENT Our Ref: DP.10268.17.KAS Your Ref: 540443

"without prejudice"

ACCIDENT ON 09 DECEMBER 2017 INVOLVING SKE 7857S AND SJQ 6689R ALONG 369 TELOK KURAU ROAD

Dear Sirs,

We refer to your letter dated 10 April 2018.

We have our client instruction to rearrange the resurvey on:

Date: 24 April 2018, Tuesday
Time: 2pm
Location: Kent Auto Services
Kakit Bukit Auto Hub
2 Kaki Bukit Avenue
#01-21
Singapore 417921

Kindly let have your confirmation and your appointed surveyor by Monday 23 April 2018 2pm. .

Yours faithfully,

Daniel C. K. Poon
Advocate & Solicitor

DANIEL POON & CO.
Advocates & Solicitors
Commissioners for Oaths
Notary Public

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227 2469
Fax: +65 6225 2579
E-mail: law@dpcoco.com.sg

Note: We do not accept service of Court documents via email

This email is confidential. If you are not the intended recipient, please inform us and then delete it from your system; you should not copy, disclose, or distribute its contents to anyone nor act in reliance on this email, as this is prohibited and may be unlawful.



This email has been checked for viruses by Avast antivirus software.
www.avast.com

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		12 Dec 2017 16:25 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	KHUA SOH KHIM, ID: S1683286C, Tel: +6596821515								
Main Claimant:	LIAN HOE LEONG & BROTHERS PTE LTD, Co. Reg. No.: 198202357C								
Vehicle Reg. No.:	SKE7857S	Date of Loss:	09/12/2017 16:00 - :59 [68 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 540443	Policy/Cover Note No.:	B27497548SMP (Comprehensive) Coverage: 19/04/2017 - 18/04/2018						
Vehicle Reg. No. (Insured):	SJQ6689R	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 23/04/2018]								
Driver/Custodian (Insured):	LIM KAY WEE ELVIS (), NRIC: S9313683G, Tel: +6582826148								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
● MSIG_SG (19/04/2018): Report Send Back Alerts - SKE7857S (TP)									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 11:25
Date Of Accident	09/12/2017 17:00
Exact Location Of Accident	369 TELOK KURAU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE7857S
Insured/Policyholder	
Name Of Registered Owner	LIAN HOE LEONG & BROTHERS PTE LTD
Co Reg No	198202357C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97622202

Vehicle Particulars

Manufacturer	JAGUAR
Model	XF-3.0 V6 LUXURY (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC17A00087501
Cover Note Number	

Driver

Name of Driver	LIM SIOW LONG, LOUIS (LIN XIAOLONG, LOUIS)
NRIC No	S8031696H
Date Of Birth	15/10/1980
Occupation	INDOOR
Date Of Driving Pass	20/02/2006
Driving Experience	11 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97622202
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 18 FLORA DRIVE #01-32
SINGAPORE

Postcode 506946

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name MARINE PARADE NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4428999 - FAX NO: 62447678

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJQ6689R

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver LIM KAY WEE ELVIS

NRIC/Passport Number S9313683G

Contact Number 82826148

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time: 11/12/17 7pm


Reporting Centre Personnel's Signature
Name: REITHAN
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against own policy must be made within the stipulated time frame from the date of occurrence. Kindly check your policy for more details.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 11/12/17 2pm


Reporting Centre Personnel's Signature
Name: PRTWON
NRIC/FIN No.:

POLICE REPORT PAGE 1 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171210/2002

1 of 3

Report No. T/20171210/2002

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/12/2017 01:08	Vide Report No.:	Station Diary No.: 8
--	------------------	-------------------------

Informant's Particulars			
Name of Informant: LIM SIOW LONG, LOUIS		Address: 18 FLORA DRIVE #01-32 SINGAPORE 506946	
ID Type / ID No.: NRIC NO / S8031696H		Contact No.: Home/Office: Mobile: 97622202	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 37	Date of Birth: 15/10/1980	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Sales and marketing manager		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 09/12/2017 17:00	Type of Location: Straight Road
Location: Along Road 1 TELOK KURAU ROAD Along 369 Telok Kurau Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJQ6689R	Car	BMW		White	Slightly Damaged	0
SKE7857S	Car	JAGUAR		White	Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT PAGE 2 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171210/2002

2 of 3

Report No. T/20171210/2002

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

CONTINUATION OF REPORT

Driver			
Name	Lim Kay Wee Elvis	ID No.	S9313683G
Related Vehicle	SJQ6689R (Car)	Contact No.	82826148
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM SIOW LONG, LOUIS	ID No.	S8031696H
Related Vehicle	SKE7857S (Car)	Contact No.	97622202
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/12/2017 at about 1700hrs, I was driving along Telok Kurau Road heading towards Lorong M Telok Kurau Road. I was driving on the right side of the two lane road. As I was driving, there was another vehicle (SJQ6689R) driving beside me on the left side of the two lane road. As I was driving, suddenly the said vehicle turned right and cut in front of me. However, I managed to swerve to the right to prevent direct impact. As a result of that, the said vehicle collided onto my vehicle on the front left bumper. Thereafter, both drivers exchanged contact details.

The other vehicle sustained damage on the front right bumper. No one was injured. No ambulance and no Police Officers came down to accident location. I do not have any in-car camera in my vehicle.

My wife was with me at the point of accident whom currently complains of giddiness after the accident. However, have yet to seek medical treatment.

My wife's particulars are as follows:

Name: Wei Shu Ting
Passport Number: 306865448



SINGAPORE
POLICE FORCE



T/20171210/2002

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

3 of 3
Report No. T/20171210/2002



CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

POLICE REPORT PAGE 3

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 JEREMY GOH ZEN KIAT 
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430
Authentication Stamp NP168  Singapore Police Force

Signature Of Informant: 
Date/Time: 10/12/2017 01:08
Classification Of Case:



INVOICE

TO : LIAN HOE LEONG & BROTHERS PTE
LTD
C/O: KENT AUTO SERVICES
KAKI BUKIT AUTO HUB
2 KAKI BUKIT AVE 2 #01-21
SINGAPORE 417921

Invoice No.: 1217/KA441
Date: 30 JANUARY 2018

PARTICULARS

Vehicle Registration No.: SKE 7857 S
Date of Loss: 09 DECEMBER 2017
Date of Assessment: 14 DECEMBER 2017

SERVICES

FEES

1. Assessment with report Photographs - Including
films, developing, storage and Transport. \$700.00

TOTAL \$700.00

SINGAPORE DOLLARS SEVEN HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of
the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP
50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: LIAN HOE LEONG & BROTHERS PTE LTD
C/O: KENT AUTO SERVICES
KAKI BUKIT AUTO HUB
2 KAKI BUKIT AVE 2 #01-21
SINGAPORE 417921

Our Reference: 1217/KA441
Date: 30 JANUARY 2018

ASSESSMENT OF VEHICLE NO. SKE 7857 S DATE OF LOSS: 09/12/2017

We have carried out a physical assessment of SKE7857S at **KENT AUTO SERVICES**, KAKI BUKIT AUTO HUB 2 Kaki Bukit Ave 2 #01-21 Singapore 417921, according to your instruction on **14 DECEMBER 2017** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SKE 7857 S
Make & Model: JAGUAR XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR
Year of Registration: 2012
Engine Capacity: 2967
Chassis No.: SAJAC05D8CFS39094
Engine No.: 603786334FC
Colour: WHITE
Mileage (km): 138601

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front


RH Make/Size/Thread: PIRELLI 245/45 R18 - 70%
LH Make/Size/Thread: PIRELLI 245/45 R18 - 70%

Rear

RH Make/Size/Thread: PIRELLI 245/45 R18 - 70%
LH Make/Size/Thread: PIRELLI 245/45 R18 - 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.



5. REMARKS

Market Value: Na
Salvage Value: Na
Repair Limit: Na

Estimated Amount: \$ 46,830.98
Adjusted Amount: \$ 44,897.98 (Lump Sum of \$35,500.00)
Estimated Repair Days: 12 days

Pursuant to your instruction, we have **NOT AUTHORISED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SKE 7857 S

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET	Bent	2,750.00	2,750.00
1	FRONT BONNET 'JAGUAR' EMBLEM	Bent	182.00	182.00
2	FRONT BONNET DAMPER L/R	Bent	260.00	260.00
2	FRONT BONNET HINGES L/R	Bent	170.00	170.00
1	FRONT BONNET INNER LOCK HANDLE	Cracked	55.00	55.00
1	FRONT BONNET INSULATOR MAT	Cracked	285.00	285.00
2	FRONT BONNET LOCK STRIKER L/R	Bent	1,401.00	1,401.00 220.8
2	FRONT BONNET MECHANISM LOCK L/R	Bent	440.00	440.00
4	FRONT BONNET RUBBER GUIDE STOPPER L/R	Bent	80.00	80.00
1	FRONT BONNET WEATHER STRIP	Cut	35.00	35.00
2	FRONT BONNET AIRBAG ACTUATOR BDS L/R	Damaged	1,982.00	1,982.00
1	FRONT GRILLE	Cracked	1,200.00	1,200.00 1042.6
1	FRONT GRILLE 'LOGO' EMBLEM	Necessary	75.00	75.00
2	FRONT HEADLAMP L/R	Cut	8,276.00	8,276.00 5637.2
2	FRONT HEADLAMP BALAST L/R	Faulty	2,260.00	2,260.00 298.2
2	FRONT HEADLAMP BRACKET L/R	Bent	570.00	570.00 290
1	FRONT BUMPER	Cracked	1,828.60	1,828.60
2	FRONT BUMPER FOGLAMP CHROME MOULDING L/R	Cracked	704.00	704.00 352
2	FRONT BUMPER FOGLAMP COVER L/R	Cracked	540.00	540.00 270
1	FRONT BUMPER INNER CENTRE SPONGE	Cracked	260.00	260.00
1	FRONT BUMPER LOWER COVER	Cracked	394.00	394.00 275.2
1	FRONT BUMPER LOWER GRILLE	Cracked	120.00	120.00
2	FRONT BUMPER INNER SPONGE L/R	Cracked	140.00	140.00
4	FRONT BUMPER PARKING SENSOR 'O' RING L/R	Necessary	160.00	160.00
4	FRONT BUMPER PARKING SENSOR HOLDER BRACKET L/R	Necessary	480.00	480.00
4	FRONT BUMPER PARKING SENSOR L/R	Cracked	3,338.08	3,338.08 834.5
1	FRONT BUMPER REINFORCEMENT	Bent	320.00	320.00
1	FRONT HEADLAMP NOZZLE HOSE - SET	Cracked	47.00	47.00
2	FRONT HEADLAMP NOZZLE L/R	Cracked	270.00	270.00
2	FRONT BUMPER NOZZLE COVER L/R	Cracked	110.00	110.00
1	FRONT SUPPORT PANEL TOP GARNISH	Cracked	180.00	180.00
1	FRONT SUPPORT PANEL	Bent	1,320.00	1,320.00 Repair

ASSESSMENT REPORT FOR VEHICLE NO. SKE 7857 S

1	FRONT LH FENDER	Cracked	1,644.30	1,644.30	1366.2
1	FRONT LH FENDER 'JAGUAR' EMBLEM	Necessary	190.00	190.00	84
1	FRONT LH FENDER INNER SPONGE	Cracked	120.00	120.00	
1	FRONT LH FENDER INNER WEATHER STRIP	Cracked	40.00	40.00	
1	FRONT LH FENDER INNER SHIELD	Cracked	550.00	550.00	429.5
1	FRONT LH FENDER OUTER GARNISH	Cracked	310.00	310.00	280
1	FRONT LH FENDER STAY BRACKET	Bent	78.00	78.00	
1	FRONT LH KNUCKLE ARM BEARING	Jammed	480.00	480.00	
1	FRONT LH KNUCKLE ARM	Bent	478.00	478.00	
1	FRONT LH LOWER ARM	Bent	585.00	585.00	
1	FRONT LH SHOCK ABSORBER	Bent	1,700.00	1,700.00	942.3
1	FRONT LH SHOCK ABSORBER TOP MOUNTING	Bent	120.00	120.00	
1	FRONT STABILIZER BAR	Repair	395.00	-	
1	FRONT LH STABILIZER BAR LINK	Repair	48.00	-	
1	FRONT LH STEERING RACK END	Bent	290.00	290.00	
1	FRONT LH STEERING RACK END TIE ROD	Bent	290.00	290.00	
1	FRONT LH THRUST ARM	Repair	510.00	-	
1	FRONT LH UPPER ARM	Repair	470.00	-	
1	FRONT LH ABS SENSOR	Faulty	155.00	X 155.00	NN
			38,685.98	37,262.98	25139.6
Less 0% discount			0.00	0.00	
Parts Total:			38,685.98	37,262.98	109%: 22625.2

SPECIAL NETT ITEMS

1	FRONT BONNET INSULATOR MAT CLIPS - SET	Necessary	30.00	30.00	✓
1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00	✓
1	FRONT BUMPER NUMBER PLATE	Bent	25.00	X 25.00	NN
1	FRONT BUMPER NUMBER PLATE HOLDER	Cracked	50.00	X 50.00	800
1	FRONT LH 18" SPORT RIM 'ORIGINAL'	Bent	2,200.00	2,200.00	150
1	FRONT LH 245/45 R18 SPORT TYRE	Cut	680.00	680.00	
1	FRONT LH FENDER INNER SHIELD CLIPS - SET	Necessary	30.00	30.00	1040
Special Nett Total :			3,045.00	3,045.00	

ASSESSMENT REPORT FOR VEHICLE NO. SKE 7857 S

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To provide towing charge.	150.00	150.00 <i>120</i>
2	To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	200.00	180.00 <i>60</i>
3	To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	450.00	400.00 <i>250</i>
4	To road test driving, check and resetting wheel alignments system.	180.00	160.00 <i>60</i>
5	To reset system after repair works.	800.00	700.00 <i>100</i>
6	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	1,250.00 <i>1000</i>
7	To provide labour, workmanship to change the above damaged bodyparts, repair damaged consistent to the accident.	1,800.00	1,650.00 <i>800</i>
8	To apply anti-rust chemical on repaired and replaced panel.	120.00	100.00 <i>80</i>
Labour Total :		5,100.00	4,590.00 <i>2470</i>
TOTAL (PARTS & LABOUR) \$		46,830.98	44,897.98

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is **\$35,500.00** (SINGAPORE DOLLARS THIRTY-FIVE THOUSAND FIVE HUNDRED ONLY)



Amas Ong
Automobile Assessor

26135.2
20% 20900

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2357C
Vehicle Details	
Vehicle No.:	SKE7857S
Vehicle to be Exported:	No
Intended De-registration Date:	23 May 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XF 3.0 V6 LUXURY AT ABS D\AB HID 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	603786334FC
Chassis No.:	SAJAC05D8CFS39094
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$53,948.00
Original Registration Date:	30 Mar 2012
First Registration Date:	30 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$53,948.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Mar 2022
PARF Rebate Amount:	\$35,066.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$80,101.00
COE Rebate Amount:	\$30,834.00
Total Rebate Amount:	\$65,900.00

The information contained herein is correct as at 23 May 2018

OK

▶ Jaguar XF Used Vehicle List (8 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Jaguar XF 3.0A Premium Luxury	\$83,800	\$14,920 /yr	16-Feb-2012	2,967 cc	104,000 km	Wearnes Automotive Pte Ltd	Availat
Facelifted Premium Luxury Edition. 1 Owner. Luxury Beige Exterior Paintwork. Black Interior Leather Seats. Call Now For A Test Drive On This Legendary Producing 234 Bhp. Office No. - - Alice - 96377619 Shawn - 85882222 Zann - 88207774							
Jaguar XF 3.0A Luxury	\$82,800	\$14,570 /yr	23-Feb-2012	2,967 cc	47,200 km	RNJ Motoring	Availat
New Arrival, 1 Owner, Very Low Mileage Of Only 47,000km, Fully Maintained By Wearnes, Come With Very Nice And Auspicious Number Worth \$5,000. Loans Are Available, Trade In Are Welcomes. Call Now! Office No. - - Mr Lim - 97666881 Ronnie - 93838402							
Jaguar XF 3.0A Luxury	\$73,000	\$12,110 /yr	27-Feb-2012	2,967 cc	110,000 km		Availat
Facelift Jaguar XF Luxury Edition Selling Cheap As New Car Coming! Luxury Sedan, Accident Free, New Tyres And Car Servicing Just Done, Road Tax Till August. Office No. - - Mr Phua - 98553895							
Jaguar XF 3.0A Luxury	\$92,800	\$16,110 /yr	30-May-2012	2,967 cc	-	360 VR Cars	Availat
Excellent Condition, See To Believe, Viewing By Appointment. Office No. - 69310005 James Tan - 90700005 Eddy Teo - 88161181							
Jaguar XF 3.0A Luxury	\$86,800	\$14,530 /yr	29-Jun-2012	2,967 cc	-	Classic Credit Pte Ltd	Availat
Fall In Love With Facelift Jaguar XF Luxury Edition With Enormous Power Yet Luxurious! Only \$8,680 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In... Office No. - 68412076 / 68481203 / 68410680 / 68417082 / 68414849 Mr Chen - 90044461 Roland - 97479331							
Jaguar XF 3.0A Luxury	\$88,800	\$14,680 /yr	31-Jul-2012	2,967 cc	99,569 km	Classic Credit Pte Ltd	Availat
Facelift Jaguar XF Luxury Edition With Enormous Power Yet Luxurious! Only \$8,880 Down Payment. Up To 90% Flexible Loan. Look No Further! We Provide Lowest Interest Rate. Flexible Loan And High Trade In... Office No. - 68412076 / 68481203 / 68410680 / 68417082 / 68414849 Wyne - 82980773 Roland - 97479331 Mr Chen - 90044461							
Jaguar XF 3.0A Luxury	\$87,500	\$13,860 /yr	28-Sep-2012	2,967 cc	63,000 km		Availat
Best Used Jaguar XF You'll Ever Find. 100% Accident Free. Pristine White In Immaculate Condition Handled With Tender Loving Care. Seldom Used, Low Mileage Of 63,000 Km. Road Tax Till Sep 2018. Parked ... Office No. - - Mr Yong - 96775545							
Jaguar XF 3.0A Supercharged	\$109,800	\$16,610 /yr	26-Dec-2012	2,995 cc	-	Motor-East Pte Ltd	Availat
Facelifted Model, LTA Rebate + Body = \$104k, In-House Loan And Balloon Scheme Available, Mileage Done 19000Km Yearly, Full Wearnes Service Record. No Gimmick! Down Payment \$10980 With Monthly \$1721, Ro... Office No. - 67772200 Cynthia Tian - 91193219 Vincent Lim - 86872202 Alvin Neo - 81886100 Henry Ong - 98516566							

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for C cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brand carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job

...CLAIM SUBFOLDER...(Pending for Survey Report)

Reinspection

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	
Main	11 Dec 2017		12 Dec 2017 16:25 Edit Adj Rpt	S\$20,800.00 Edit Estimates	S\$20,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KHUA SOH KHIM , ID: S1683286C, Tel: +6596821515								
Main Claimant:	LIAN HOE LEONG & BROTHERS PTE LTD , Co. Reg. No.: 198202357C								
Vehicle Reg. No.:	SKE7857S	Date of Loss:	09/12/2017 16:00 - :59 [68 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 540443	Policy/Cover Note No.:	B27497548SMP (Comprehensive) Coverage: 19/04/2017 - 18/04/2018						
Vehicle Reg. No. (Insured):	SJQ6689R	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 23/04/2018]								
Driver/Custodian (Insured):	LIM KAY WEE ELVIS (), NRIC: S9313683G, Tel: +6582826148								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> MSIG_SG (19/04/2018): Report Send Back Alerts - SKE7857S (TP) 									
ALL ASSOCIATED TASKS <input type="checkbox"/>									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE7857S (540443)
[SJQ6689R]

TP

LIAN HOE LEONG & BROTHERS PTE LTD

Dec 9 2017 4:00PM

[KHUA SOH KHIM]

Kent Auto Services - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	12/12/17 16:13	Accident Statement From:GD - Reg. No: SJQ6689R, Claimant: KHUA SOH KHIM	 Load HTM <input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	20/01/18 12:07	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>
2	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
3	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
4	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
5	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
6	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
7	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
8	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
9	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
10	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
11	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
12	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
13	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
14	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
15	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
16	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
17	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
18	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
19	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
20	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
21	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
22	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
23	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
24	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
25	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
26	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
27	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
28	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
29	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
30	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
31	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
32	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>
33	20/01/18 12:07	General View	 Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	20/01/18 12:07	General View	Load JPG	<input checked="" type="checkbox"/>
35	20/01/18 12:07	General View	Load JPG	<input checked="" type="checkbox"/>
36	20/01/18 12:07	General View	Load JPG	<input checked="" type="checkbox"/>
37	20/01/18 12:07	General View	Load JPG	<input checked="" type="checkbox"/>
38	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
50	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
51	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
52	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
53	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
54	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
55	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
56	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
57	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
58	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
59	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
60	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
61	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
62	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
63	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
64	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
65	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
66	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
67	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
68	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
69	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
70	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
71	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
72	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
73	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
74	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
75	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
76	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
77	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
78	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
79	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
80	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
81	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
82	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
83	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
94	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
95	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
96	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
97	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
98	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
99	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
100	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
102	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
103	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
104	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
105	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
106	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
107	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
108	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
109	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
110	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
111	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
112	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
113	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
114	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
115	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
116	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
117	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
118	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
119	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
120	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
121	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
122	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
123	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
124	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
125	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
126	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
127	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
128	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
129	20/01/18 12:09	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
130	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
131	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
132	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
133	20/01/18 12:09	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
135	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
136	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
137	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
138	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
139	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
140	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
141	20/01/18 12:10	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/12/17 16:20	SKE7857S E-FILE, POLICE REPORT & IC	Load PDF	
2	10/04/18 09:49	FINAL REPAIR BILL	Load PDF	
3	10/04/18 09:49	SURVEY REPORT & PHOTOS	Load PDF	
4	19/04/18 15:05	Email to confirm on reinspection	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/18 08:32	PRS Invoice	Load PDF	
2	24/05/18 08:34	COLOUR PHOTO	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023597/GRBE2-1
Date: 24/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27497548SMP
Claimant Vehicle No : SKE7857S	Insured Vehicle No :	SJQ6689R
Date of Loss: 09/12/2017	Nature of Claim:	TP
		Claim No: 540443

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE7857S	
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Engine No: 603786334FC
Reg. Date:	30/03/2012 (Man. Year: 2012)	Chassis No: SAJAC05D8CFS39094
Colour:	White	Odometer: 148274 km
Engine Capacity:	2967 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,730.98	23,569.81	18,161.17	43.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	2,470.00	2,630.00	51.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,830.98	26,039.81	20,791.17	44.40
Approved Total (Overridden) (S\$)		20,800.00		
Nett Amount (S\$)	46,830.98	20,800.00	26,030.98	55.58

INSPECTION

Date of Assignment:	12/12/2017	
Date Inspected:	24/04/2018 Inspected At:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	8.0 days	

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$85,000.00(EST)-LTA REIMBURSEMENT VALUE: \$65,900.00=NETT VALUE: \$19,100.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2018)
Parts: 143	JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE7857S)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Replaced	2,750.00 F	*2,750.00 FL
2	1		*FRONT BONNET JAGUAR EMBLEM	Replaced	182.00 F	*182.00 FL
3	2		*FRONT BONNET DAMPER L/R	Replaced	260.00 F	*260.00 FL
4	2		*FRONT BONNET HINGES L/R	Replaced	170.00 F	*170.00 FL
5	1		*FRONT BONNET INNER LOCK HANDLE	Replaced	55.00 F	*55.00 FL
6	1		*FRONT BONNET INSULATOR MAT	Replaced	285.00 F	*285.00 FL
7	2		*FRONT BONNET LOCK STRIKER L/R	Replaced	1,401.00 F	*220.80 FL
8	2		*FRONT BONNET MECHANISM LOCK L/R	Replaced	440.00 F	*440.00 FL
9	4		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Replaced	80.00 F	*80.00 FL
10	1		*FRONT BONNET WEATHER STRIP	Replaced	35.00 F	*35.00 FL
11	2		*FRONT BONNET AIRBAG ACTUATOR BDS L/R	Replaced	1,982.00 F	*1,982.00 FL
12	1		*FRONT GRILLE	Replaced	1,200.00 F	*1,042.60 FL
13	1		*FRONT GRILLE LOGO EMBLEM	Replaced	75.00 F	*75.00 FL
14	2		*FRONT HEADLAMP L/R	Replaced	8,276.00 F	*5,637.20 FL
15	1		*FRONT HEADLAMP BALLAST L/R	N/S Not Necessary/O/S Replaced	2,260.00 F	*298.20 FL
16	2		*FRONT HEADLAMP BRACKET L/R	Replaced	570.00 F	*290.00 FL
17	1		*FRONT BUMPER	Replaced	1,828.60 F	*1,828.60 FL
18	1		*FRONT BUMPER FOGLAMP CHROME MOULDING L/R	N/S Replaced/O/S Not Necessary	704.00 F	*352.00 FL
19	1		*FRONT BUMPER FOGLAMP COVER L/R	N/S Replaced/O/S Not Necessary	540.00 F	*270.00 FL
20	1		*FRONT BUMPER INNER CENTRE SPONGE	Replaced	260.00 F	*260.00 FL
21	1		*FRONT BUMPER LOWER COVER	Replaced	394.00 F	*275.20 FL
22	1		*FRONT BUMPER LOWER GRILLE	Replaced	120.00 F	*120.00 FL
23	2		*FRONT BUMPER INNER SPONGE L/R	Replaced	140.00 F	*140.00 FL
24	4		*FRONT BUMPER PARKING SENSOR O RING L/R	Replaced	160.00 F	*160.00 FL
25	4		*FRONT BUMPER PARKING SENSOR HOLDER BRACKET L/R	Replaced	480.00 F	*480.00 FL
26	1		*FRONT BUMPER PARKING SENSOR L/R (4 PCS)	Replaced-only 1 pc	3,338.08 F	*834.52 FL
27	1		*FRONT BUMPER REINFORCEMENT	Replaced	320.00 F	*320.00 FL
28	1		*SET FRONT HEADLAMP NOZZLE HOSE	Replaced	47.00 F	*47.00 FL
29	2		*FRONT HEADLAMP NOZZLE L/R	Replaced	270.00 F	*270.00 FL
30	2		*FRONT BUMPER NOZZLE COVER L/R	Replaced	110.00 F	*110.00 FL
31	1		*FRONT SUPPORT PANEL TOP GARNISH	Replaced	180.00 F	*180.00 FL
32	1		*FRONT SUPPORT PANEL	Repaired	1,320.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*FRONT LH FENDER	Replaced	1,644.30 F	*1,366.20 FL
34	1		*FRONT LH FENDER JAGUAR EMBLEM	Replaced	190.00 F	*84.00 FL
35	1		*FRONT LH FENDER INNER SPONGE	Replaced	120.00 F	*120.00 FL
36	1		*FRONT LH FENDER INNER WEATHER STRIP	Replaced	40.00 F	*40.00 FL
37	1		*FRONT LH FENDER INNER SHIELD	Replaced	550.00 F	*429.50 FL
38	1		*FRONT LH FENDER OUTER GARNISH	Replaced	310.00 F	*280.00 FL
39	1		*FRONT LH FENDER STAY BRACKET	Replaced	78.00 F	*78.00 FL
40	1		*FRONT LH KNUCKLE ARM BEARING	Replaced	480.00 F	*480.00 FL
41	1		*FRONT LH KNUCKLE ARM	Replaced	478.00 F	*478.00 FL
42	1		*FRONT LH LOWER ARM	Replaced	585.00 F	*585.00 FL
43	1		*FRONT LH SHOCK ABSORBER	Replaced	1,700.00 F	*942.30 FL
44	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Replaced	120.00 F	*120.00 FL
45	1		*FRONT STABILIZER BAR	Repaired	395.00 F	*- FL
46	1		*FRONT LH STABILIZER BAR LINK	Repaired	48.00 F	*- FL
47	1		*FRONT LH STEERING RACK END	Replaced	290.00 F	*290.00 FL
48	1		*FRONT LH STEERING RACK END TIE ROD	Replaced	290.00 F	*290.00 FL
49	1		*FRONT LH THRUST ARM	Repaired	510.00 F	*- FL
50	1		*FRONT LH UPPER ARM	Repaired	470.00 F	*- FL
51	1		*FRONT LH ABS SENSOR	Not Necessary	155.00 F	*- FL
52	1		*SSET FRONT BONNET INSULATOR MAT CLIPS	Replaced	30.00 FS	*30.00 FS
53	1		*SET FRONT BUMPER CLIPS	Replaced	30.00 FS	*30.00 FS
54	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	25.00 FS	*- FS
55	1		*FRONT BUMPER NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
56	1		*FRONT LH 18 SPORT RIM ORIGINAL	Replaced	2,200.00 FS	*800.00 FS
57	1		*FRONT LH 245/45 R18 SPORT TYRE	Replaced	680.00 FS	*150.00 FS
58	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Replaced	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	41,730.98	26,073.12
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	2,503.31
Total Parts (S\$)	41,730.98	23,569.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGE	New	150.00	120.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	200.00	60.00
3	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	450.00	250.00
4	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	180.00	60.00
5	TO RESET SYSTEM AFTER REPAIR WORKS	New	800.00	100.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,400.00	1,000.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (S\$)			5,100.00	2,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >