

CASE OWNER:

Joel Goh

CC 4/EQ1800

7510, A

2/1/19

LKK:

IDAC:

Surveyor:

Adrian

DOI:

2/5/18

Date / Time:

24/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKD 3299J

Name of Insured:

SHAN V RAMU

Insured Tel No.:

HP:

83266085

Excess Sec II :S\$

D.O.A:

27/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

DMPPH 217-001V69

Make / Model:

Audi

Place of Accident:

NEWTON HYDER

If NO, Driver Name / Age:

Driver Tel No.:

(V/L-YES/NO)

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

Final ? Yes / No

SJT 990T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Borneo



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

24/4/18

Boran

26/4/18

2/1/19

2/3/19

SJT 990T - V

SKD 3299J - 7

Call 01

File -> type mandate

rate pass to shuan to do

TA pda difference, EQ (Joel) just proceed to settle.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

16262.58

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

1000.00 (\$ 100 x 10 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

17290.03

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

17290.03

Name 1:

Borneo Motors (S) Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

EQ1

M

ASSIGNMENT

From: Date 02082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SJT 990T

at Workshop m/s: Borneo Motor.

of 17 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Thomas

after 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJT990T. Yr Regn: 2012, May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphard C.C. 2362

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 16/606 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTEG021H808216694.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17.

R: 215/60R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 06 mm

L/Bal: 06 mm

D.O.A.

Rear

R/Bal: 06 mm

L/Bal: 06 mm

D.O.I. 02/05/18.

Survey held at: Borneo (ubi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP EQ.

PIP \$ 15198.67 (Red \$ 6836.10 / 37%).

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

) \$ + R5. 10

) Photo

) Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ118007510/Amb3

Date: 03.05.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJT990T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.05.2018 at the premises of M/s Borneo Motors (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	22,034.77
Revised Estimate Amount	: S\$	15,160.27
"Check" Items Amount	: S\$	4,123.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18007510/mb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 24-04-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKD 3299J	Veh. Inspected	SJT 990T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/03/2018	Inspection Date	
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
BQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110		S1000021/ICEQI1	M/s Bone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970	
		Document No		
		Document Date		
		0		
		27/04/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK F2	ANH20R	03/05/2012	SJT0990T	158570	16333	7DS/SJT0990T/23031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Joi	12/04/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKD3299J ACC DATE:23/03/2018 DRIVE IN:11/04/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				✓ 169.50
3	S	BP-SUBLET SEALANT - TAILGATE, REAR END PANEL				✓ 160.00
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 169.50
5	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				✓ 339.00
6	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				✓ 339.00
7	S	BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ 436.00
8	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM				✓ 400.00
9	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER				✓ 127.13
10	S	BP-SUBLET REMOVE & INSTALL SEAT, CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				✓ 678.00
11	B	BP-MECH RESET ECU AND REPROGRAMME				✓ 402.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639973

TO SECURITY GUARD

3639973

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 27/04/2018
TIME 13:17

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021/ICEQI1	M/s Eone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No	
	Document Date	
	0	
	27/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK	F2	ANH20R	03/05/2012	SJT0990T	158570	16333 .7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Joi	12/04/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE REAR BUMPER, REAR TAILGATE, ETC				2712 4068.00
		STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR				2780 3336.00
		EAS				
14	1	T52159-58916 COVER, RR BUMPER <i>Delid</i>	1.00	614.80		✓ 614.80
15	2	T52153-58020 BAR, RR BUMPER, LH <i>He ne .</i>	1.00	57.20		* 57.20
16	3	T52156-58020 L/R SIDE BPR SUPPORT, <i>plan</i>	1.00	78.00		✓ 78.00
17	4	T52152-58010 R/R BUMPER EXTENSION, <i>plan</i>	1.00	57.30		* 57.30
18	5	T52155-58030 R/R SIDE BPR SUPPORT, <i>plan</i>	1.00	78.00		✓ 78.00
19	6	T52165-58020 E1 COVER, RR BUMPER <i>Delid</i>	1.00	198.40		✓ 198.40
20	7	S52161-0K040 CLIPS <i>He ne</i>	10.00	3.90		✓ 39.00
21	8	T52162-58010 E1 PLATE, RR BUMPER <i>Delid</i>	1.00	15.20		✓ 15.20
22	9	T81910-13022 R/REAR BPR REFLECTOR, <i>plan</i>	1.00	58.00		* 58.00
23	0	T58307-58038 PANEL SUB-ASSY, BODY <i>Delid</i>	1.00	1019.20		✓ 1019.20
24	1	T57081-58020 R/REAR BUMPER BRACKET, <i>plan</i>	1.00	106.30		* 106.30
25	2	T67005-58120 REAR BACK DOOR PANEL, <i>Delid</i>	1.00	1869.50		✓ 1869.50
26	3	T67881-58020 RR BACK DOOR W/STRIP, <i>plan</i>	1.00	395.10		✓ 395.10
27	4	T68105-58091 REAR BACK DOOR GLASS, <i>He ne</i>	1.00	1168.50		✓ 1168.50
28	5	T76801-58110 E0 GARNISH SUB-ASSY, <i>plan</i>	1.00	1994.60		* 1994.60
29	6	T67750-58061 A0 BOARD ASSY, BACK <i>He ne</i>	1.00	684.60		* 684.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639974

TO SECURITY GUARD

3639974

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 27/04/2018
TIME 13:17

VEHICLE NO. SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD.**Borneo Motors**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021/ICEQ11	M/s Bone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No 0	
	Document Date 27/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK F2	ANH20R	03/05/2012	SJT0990T	158570	16333	7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2A2H860320	30	Sam San Joi		12/04/2018	8.00 --/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T67750-58061 A0 BOARD ASSY, BACK <i>Replaced</i>	1.00	684.60		* 684.60
31	8	T69350-28161 REAR BACK DR LOCK ASSY (W/PWR D <i>Replaced</i>	1.00	475.10		* 475.10
32	9	T69430-28050 STRIKER ASSY, BACK <i>Replaced</i>	1.00	39.60		* 39.60
33	0	T90975-02066 TOYOTA SYMBOL EMBLEM, <i>Replaced</i>	1.00	72.20		* 72.20
34	1	T75441-58030 "ALPHARD" EMBLEM, <i>Replaced</i>	1.00	66.20		* 66.20
35	2	T89348-64030 E1 RETAINER, ULTRASONIC <i>Replaced</i>	1.00	17.10		* 17.10
36	3	T89341-76010 E2 SENSOR, ULTRASONIC <i>Replaced</i>	1.00	385.50		* 385.50
37	4	T89348-30030 E3 RETAINER, ULTRASONIC <i>Replaced</i>	1.00	17.10		* 17.10
38	5	T89341-76010 E2 SENSOR, ULTRASONIC <i>Replaced</i>	1.00	385.50		* 385.50
39	6	T67935-58022 A0 PLATE, BACK DOOR <i>Replaced</i>	1.00	176.00		* 176.00
40	7	T04562-12010 FRT W/SCREEN DAM KIT, <i>Replaced</i>	1.00	101.00		* 101.00
41	8	T08826-08609 SUPER FAST URETHANE BLACK <i>Replaced</i>	2.00	90.08		* 180.16
42	9	T08826-08682 SINGLE STEP PRIMER <i>Replaced</i>	2.00	173.44		* 346.88

Adrian King
P/P 02/03/18
09:20

Look Auto Consultants hence notify
Repairer of the following:
To resurvey before/after spray painting
To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.
Supplementary items must be resurveyed and is subject to final approval from Insurance Company

For & on behalf of
Borneo Motors

Accepted by Repairer

Signature: _____
Date: _____

Parts: 11,380.64
Labour: 432.00
Materials: 10,222.13
Others: 0.00
0.00

Total	22,034.77
GST 7.00%	1,542.43
Less	0.00
Amount Due	23,577.20

PLEASE TEAR ALONG PERFORATED LINE

3639975

3639975

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 27/04/2018
TIME 13:17

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 ■ Road Transport Act. 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE NO. : VPA/P1928141 Account No. : 11511
Coverage : Comprehensive
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : EONE DIESEL PTE. LTD.
Vehicle Registration No. : SJT990T
Period of Insurance : From 03/05/2017 To 02/05/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business
The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

(03)

Basic Own Damage Excess : SGD 400.00

An Additional Excess is applicable as follows:

S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.

S\$5,000.00 for Undeclared Young and Inexperienced Driver.

(Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOSP on 04/05/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

7P

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1601716G



NG SOO KIN
黃仕錦
CHINESE
Date of Birth 03-06-1963
Country of Birth SINGAPORE

1222826



NRIC No. S1601716G



03-10-1963

280 DUNEARN ROAD
SINGAPORE 2905601

NRIC No. S1601716G

REPUBLIC OF SINGAPORE DRIVING LICENCE



NRIC No. S1601716G

NG SOO KIN

17 MAR 1967



1222826

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CATEGORIES

Class 3 Motor Cars and Motor Tractors the weight of which when does not exceed 3500 kilograms

17 Mar 1967

License No. S1601716G



Catherine Chong (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 23 April, 2018 4:50 PM
To: assignments
Subject: FW: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 23/03/2018 (DM18HO00872-JG)
Attachments: SKD3299J.pdf; SJT990T 23032018_Est Inv.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

24042018 @ 10.21am
Sam veh not in.

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Monday, 23 April 2018 4:06 PM
To: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 23/03/2018 (DM18HO00872-JG)

Dear LKK

Attached our insured's accident report and estimates for your attention.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Joel Goh
Sent: Monday, April 23, 2018 4:05 PM
To: 'Siti Nabilah PTCBC'
Cc: 甯琨 @
Subject: RE: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 23/03/2018

Without Prejudice

Dear Siti

We will appoint LKK to take over this direct settlement.
Kindly liaise with them directly.

Dear LKK

Kindly assist on the following direct settlement.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify i

From: Siti Nabilah PTCBC [<mailto:Siti.Nabilah@inchcape.com.sg>]

Sent: Wednesday, April 18, 2018 2:29 PM

To: Joel Goh

Cc: Siti Nabilah PTCBC

Subject: RE: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 23/03/2018

Hi Joel,

It should be 23.03.2018.

Sorry and thanks.

Regards,

Nabilah

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Monday, 16 April 2018 1:18 PM

To: Siti Nabilah PTCBC <Siti.Nabilah@inchcape.com.sg>

Subject: RE: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 11/04/2018

Without Prejudice

Dear Siti

Kindly confirm the date of accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: Siti Nabilah PTCBC [<mailto:Siti.Nabilah@inchcape.com.sg>]
Sent: Thursday, April 12, 2018 4:52 PM
To: Joel Goh; Janet Tan; Tan Wei Yin
Cc: Siti Nabilah PTCBC
Subject: Direct Settlement(SAM) - Accident Involving SJT990T and SKD3299J DOA 11/04/2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos, Police Report & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SKD3299J thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$150 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Sam Joi @ 9847 6209 / 6631 1687** is located at **17 Ubi Road 4** for an appointment to inspect our client's vehicle.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you

Best Regards,

Nabilah

TPR Team (Claims Accident Recovery Dpt)

DID 6631 1874 | FAX 6872 7260

Inchcape - Borneo Motors (S) Pte Ltd

Office Address: 2 Pandan Crescent, Inchcape Centre Level 4, Singapore 128462

www.borneomotors.com.sg | www.toyotasingapore.com.sg



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Borneo Motors

Co Reg No: 196730086Z

Borneo Motors (Singapore) Pte Ltd
Inchcape Bodycare Centre
Level 4, Inchcape Centre
2 Pandan Crescent
Singapore 128462
Tel: +65 6631 1855/1500
Fax: +65 6872 7260
www.borneomotors.com.sg

Our Ref: BMS2018/07/PD8570/DS(SM)

Your Ref: CC4/EQ118007510/mb3

20 Jul 2018

BY HAND (INS COPY)

M/S. EQ INSURANCE COMPANY LIMITED C/O LKK AUTO CONSULTANTS PTE LTD

Attn : Bevan Lim

Dept : Motor Claims

RE : ACCIDENT INVOLVING SJT990T AND SKD3299J ON 23 Mar 2018

Dear Officer,

We refer to the above captioned.

The accident was caused by the negligence of your insured and as a result, our client has incurred the following losses:

A. Repair Cost - \$16,262.58	B. LTA Search - \$7.45
C. Excess -	D. Loss of Use - \$1,000.00(\$100x10days)
E. Loss of Rental -	F. Others -
G. Medical Claims - -Undertake By Claimant ☐	Total Claim - \$17,270.03

We would appreciate if you could revert to us with an offer to settlement within **8 working weeks** as required under NIMA Protocol.

Enclosed are the following documents for your kind perusal:

- | | |
|--|--|
| (✓) Original Tax Invoice | (X) Vehicle Registration Card |
| (X) Car Rental Invoice/Agreement/Medical Receipt | (✓) Driver's driving license / Identity card |
| (✓) GIAS/Police Report/s | (X) Original Photograph X _____ |
| (✓) Certificate of Insurance | (X) Original/Photocopy Survey |
| (✓) Letter of Authority | (✓) LTA Search Fees |

*Cheque is to be made payable to **BORNEO MOTORS (SINGAPORE) PTE LTD** & mail it to, Inchcape Bodycare Centre Level 4, Inchcape Centre, 2 Pandan Crescent, Singapore 128462, Attn: TPR Department*

Yours faithfully,

TPR Team

Claims Service Department

F:68727260 E: claimstatusenquiry@borneomotors.com.sg

(As this is a computer generated letter, no signature is required.)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: **CC4/EQI18007510/Amb3**

27 APRIL 2018

SUGU V RAMU
BLK 541 SERANGOON NORTH AVE 4
#02-127
SINGAPORE 550541

Dear Sir/Madam,

ACCIDENT INVOLVING SKD 3299J AND SJT 990T ON 23/03/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: bevanlim@lkkauto.com

c.c. **EQ INSURANCE COMPANY LIMITED**
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING

SJT990T and

SKD3299J on

22.3.18

Own vehicle's number

Other vehicle's number

Date of accident

along

Mawton Flyover to CTR

Accident location

BY THE LETTER OF AUTHORITY, I/we,

Eone Diesel Pte Ltd

Name of Policy Holder & (IC/Passport/Company Registration) number

of

Address of Policy Holder

owner of Vehicle Registration No. SJT990T hereby appoint **BORNEO MOTORS (SINGAPORE) PTE LTD** (hereinafter refers to **BMS**), a company incorporated in Singapore and having its registered office at 33 Leng Kee Road, Singapore 159102, to do all or any of the following:

1. To submit, resolve and make any claims which *I/we may have against the other *party/parties to the Accident and under the insurance *policy/policies taken up by such *party/parties or alternatively under Insurance Policy number VP1212141 taken up by *me/us and pay the compulsory excess in respect of the cost of repairs suffered by *me/us arising from the Accident (loss and damage).
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favour of **BORNEO MOTORS (SINGAPORE) PTE LTD** and give a valid receipt and discharge therefore.
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever in relation thereto.
4. Generally do all such acts as it shall deem necessary for the purpose of settling such claim.

*I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on *my/our behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by *me/us in *my/our own proper person(s) and *I/we hereby ratify and confirm, all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

*I/We hereby further declare that the letter of authority hereby conferred shall remain irrevocable.

*I/We further confirm that the acceptance by **BMS** of the settlement amount in respect of such constitute the full discharge of *my/our claim(s) in respect of such loss and damage.

IN WITNESS WHEREOF, *I/we have hereunto to set *my/our hand and sign this 16 of the month May Year 20 18.

Signed & Delivered By:



(To be sign by the policy holder only)

**Please stamp the company chop for vehicle registered under a company's name

Witness By:

*delete as appropriate



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631-1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**TAX INVOICE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021/ICEQI1	M/s Eone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No 39006711	
	Document Date 07/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFQK	F2	ANH20R	03/05/2012	SJT0990T	161610	16333 7DS/SJT0990T/230311
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Jo1	12/04/2018 13.30	08/05/2018 15.04		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKD3299J ACC DATE:23/03/2018 DRIVE IN:11/04/2018 DATE-IN:02/05/2018 DATE SURVEY:02/05/2018 NO OF REPAIR DAYS:9 DAYS BY:ADRIAN LING(LKK)				30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR A45				169.50
3	S	BP-SUBLET SEALANT - TAILGATE, REAR END PANEL A45				160.00
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST A45				169.50
5	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAI A45 LGATE				339.00
6	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA A45				339.00
7	S	BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS A45				436.00
8	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLA M30 R FILM				400.00
9	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER A45				127.13
10	S	BP-SUBLET REMOVE & INSTALL SEAT, CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				678.00
11	B	BP-MECH RESET ECU AND REPROGRAMME	18			402.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3691506

TO SECURITY GUARD

3691506

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/06/2018
TIME 08:18

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking
www.toyotasingapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**TAX INVOICE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
BQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQ11	M/s Bone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No 39006711	
	Document Date 07/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK F2	ANH20R	03/05/2012	SJT0990T	161610	16333	7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Jo1		12/04/2018 13.30	08/05/2018 15.04	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE REAR BUMPER, REAR TAILGATE, ETC A45				2712.00
13	S	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
13	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREA A45				2780.00
		EAS				
14	1	T52159-58916 COVER, RR BUMPER	1.00	614.80		614.80
15	2	T52156-58020 SUPPORT RR BUMPER LH	1.00	78.00		78.00
16	3	T52155-58030 SUPPORT RR BUMPER RH	1.00	78.00		78.00
17	4	S52161-0K040 PIECE, RR BUMPER	10.00	3.90		✓39.00
18	5	T58307-58038 PANEL SUB-ASSY, BODY	1.00	1019.20		1019.20
19	6	T67005-58120 PANEL ASSY, BACK DOOR	1.00	1869.50		1869.50
20	7	T67881-58020 WEATHERSTRIP, BACK DR	1.00	395.10		395.10
21	8	T68105-58091 GLASS, BACK DOOR	1.00	1168.50		1168.50
22	9	T90975-02066 EMBLEM, SYMBOL	1.00	72.20		72.20
23	0	T75441-58030 PLATE, LUGGAGE DOOR	1.00	66.20		66.20
24	1	T67935-58022 AO PLATE, BACK DOOR	1.00	176.00		176.00
25	2	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00		101.00
26	3	T08826-08609 SUPER FAST URETHANE BLACK	2.00	90.08		180.16
27	4	T08826-08682 SINGLE STEP PRIMER	2.00	173.44		346.88
28	5	T89348-64030 AO RETAINER, ULTRASONIC	1.00	17.10		17.10
29	6	L89348-30030 AO RETAINER, ULTRASONIC	1.00	21.30		21.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3691507

TO SECURITY GUARD

3691507

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/06/2018
TIME 08:18

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE

Online Service Booking
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021/ICEQ11	M/s Eone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No 39006711	
	Document Date 07/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK F2	ANH20R	03/05/2012	SJT0990T	161610	16333	7DS/SJT0990T/23031
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H806216694	2AZH860320	30	Sam San Joi	12/04/2018 13.30	08/05/2018 15.04		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T52165-58020 A0 COVER RR BUMPER RH	1.00	198.40		198.40
31	8	T52162-58010 C0 PLATE, RR BUMPER	1.00	15.20		15.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,456.54	15,198.67
		Labour 432.00	GST 7.00% 1,063.91
		Materials 8,310.13	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 16,262.58

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

3691508

TO SECURITY GUARD

3691508

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 07/06/2018
TIME 08:18

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Apr 2018 / 16:44:20

Receipt Date/Time : 12 Apr 2018 / 16:44:20

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180412-001628

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SKD3299J				
As at 11 Apr 2018/00:00:01				
Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - SKD3299J Enquiry Fee 20180412164329446398	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180412164342583	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Hsiao Tong (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 28 February 2019 3:51 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: <Seek Mandate> EQ ref : DM18HO00872-JG *LKK ref : CC4/EQI18007510/Amb3q2 [ACCIDENT INVOLVING SKD3299J(EQ-OI) AND SJT990T(TP) ON 23/03/2018]

Dear Hsiao Tong

Please proceed to resolve this matter up to S\$17,270.03.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, February 4, 2019 10:13 AM
To: Joel Goh
Cc: Admin A
Subject: <Seek Mandate> EQ ref : DM18HO00872-JG *LKK ref : CC4/EQI18007510/Amb3q2 [ACCIDENT INVOLVING SKD3299J(EQ-OI) AND SJT990T(TP) ON 23/03/2018]

EQ ref : **DM18HO00872-JG**
LKK ref : CC4/EQI18007510/Amb3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING SKD3299J(EQ-OI) AND SJT990T(TP) ON 23/03/2018

We refer to the above matter.

This is a head-to-rear collision.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "BORNEO MOTORS (S) PTE LTD" at S\$17,270.03(all-in).

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 23,581.70	\$ 16,262.58
2. Loss of Use (10days x \$100.00)	\$ 1,000.00	\$ 1,000.00 (10days x \$100.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 24,589.15	\$ 17,270.03

**9days recommendation for repair + 1Sunday = 10days

Enclosed here with all the relevant documents for your perusal.

Kindly let us have your approval/instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 14/03/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SKD 3299J (Insd Veh)	Your Ref. No. : DM18HO00872-JG
	SJT 990T (TP Veh)	Our Ref. No. : CC4/EQI18007510/Apb3q2
Date of Accident	23/3/2018	

Liability	100%	
Final Repair Cost	: \$ 16,262.58	
Loss of Use	: \$ 1,000.00	10 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	17,270.03	
Final Settlement Sum	: \$ 17,270.03	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	BORNEO MOTORS (SINGAPORE) PTE LTD	: \$ 17,270.03
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18007510/Apb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 14-03-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKD 3299J	Veh. Inspected	SJT 990T
Policy No.	DMPPHQ17-002289	Coverage (\$)	0.00
Claim No.	DM18HO00872-JG	Excess (\$)	0.00
Assign From	JOEL	Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALPHARD	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTEGD21H808216694	Colour	WHITE
Odometer	161606	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	TOYO	6 mm
L/H Front Tyre	215/60 R17	TOYO	6 mm
R/H Rear Tyre	215/60 R17	TOYO	6 mm
L/H Rear Tyre	215/60 R17	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/03/2018	Inspection Date	02/05/2018
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR		9 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 990T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER,RR BUMPER (SN)	DEFORMED	614.80	614.80
1	BAR,RR BUMPER,LH (SN)	NOT NECESSARY	57.20	-
1	L/R SIDE BPR SUPPORT (SN)	NECESSARY	78.00	78.00
1	R/R BUMPER EXTENSION (SN)	NOT NECESSARY	57.30	-
1	R/R SIDE BPR SUPPORT (SN)	NECESSARY	78.00	78.00
1	COVER,RR BUMPER (SN)	DEFORMED	198.40	198.40
10	CLIPS (SN)	NECESSARY	39.00	39.00
1	PLATE,RR BUMPER (SN)	DEFORMED	15.20	15.20
1	R/REAR BPR REFLECTOR (SN)	NOT NECESSARY	58.00	-
1	PANEL SUB-ASSY,BODY (SN)	CRACKED	1,019.20	1,019.20
1	R/REAR BUMPER BRACKET (SN)	NOT NECESSARY	106.30	-
1	REAR BACK DOOR PANEL (SN)	DENTED	1,869.50	1,869.50
1	RR BACK DOOR W/STRIP (SN)	NECESSARY	395.10	395.10
1	REAR BACK DOOR GLASS (SN)	NECESSARY	1,168.50	1,168.50
1	GARNISH SUB-ASSY (SN)	NOT NECESSARY	1,994.60	-
1	BOARD ASSY,BACK (SN)	NOT NECESSARY	684.60	-
1	BOARD ASSY,BACK (SN)	REPEATED	684.60	-
1	REAR BACK DR LOCK ASSY (W/PWR D)(SN)	NOT NECESSARY	475.10	-
1	STRIKER ASSY,BACK (SN)	NOT NECESSARY	39.60	-
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	72.20
1	"ALPHARD" EMBLEM (SN)	NECESSARY	66.20	66.20
1	RETAINER,ULTRASONIC (SN)	NECESSARY	17.10	17.10
1	SENSOR,ULTRASONIC (SN)	NOT NECESSARY	385.50	-
1	RETAINER,ULTRASONIC (SN)	NECESSARY	21.30	21.30
1	SENSOR,ULTRASONIC (SN)	NOT NECESSARY	385.50	-
1	PLATE,BACK DOOR (SN)	DEFORMED	176.00	176.00
1	FRT W/SCREEN DAM KIT (SN)	NECESSARY	101.00	101.00
2	SUPER FAST URETHANE BLACK (SN)	NECESSARY	180.16	180.16
2	SINGLE STEP PRIMER (SN)	NECESSARY	346.88	346.88

Report Ref No. CC4/EQI18007510/Apb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
			11,414.84	6,486.54
	LABOUR			
	DRILL HOLE & INSTALL REVERSE SENSOR.		169.50	169.50
	SEALANT-TAILGATE,REAR END PANEL.		160.00	160.00
	CHECK LIGHTING & CONDUCT WATER LEAK TEST.		169.50	169.50
	TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE.		339.00	339.00
	REMOVE & INSTALL REAR REVERSE CAMERA.		339.00	339.00
	REPLACE & INSTALL REAR WINDSCREEN GLASS.		436.00	436.00
	SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM.		400.00	400.00
	REMOVE & INSTALL TAILGATE TOP SPOILER.		127.13	127.13
	REMOVE & INSTALL SEAT,CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR.		678.00	678.00
	RESET ECU AND REPROGRAMME.		402.00	402.00
	REPLACE REAR BUMPER,REAR TAILGATE,ETC.STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS.		4,068.00	2,712.00
	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS.		3,336.00	2,780.00
			10,624.13	8,712.13
GRAND TOTAL			22,038.97	15,198.67
RECOMMENDED COST OF REPAIRS				15,198.67

Report Ref No. CC4/EQ18007510/Apb3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 15 March 2019 3:00 PM
To: 'Joel Goh'
Subject: TP Direct Settlement - Accident Involving SKD 3299J (OI) and SJT 990T (TP) on 23/03/2018
Attachments: LKK REPORT & PHOTO.pdf; TO DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933