

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021/ICEQI1	M/s Eone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No	
	Document Date	
	0	
	27/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK	F2	ANH2OR	03/05/2012	SJT0990T	158570	16333 :7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Joi	12/04/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKD3299J ACC DATE:23/03/2018 DRIVE IN:11/04/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓ 30.00
2	S	BP-SUBLET DRILL HOLE & INSTALL REVERSE SENSOR				✓ 169.50
3	S	BP-SUBLET SEALANT - TAILGATE, REAR END PANEL				✓ 160.00
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 169.50
5	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				✓ 339.00
6	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				✓ 339.00
7	S	BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ 436.00
8	S	BP-SUBLET SUPPLY & INSTALL REAR WINDSCREEN 3M SOLAR FILM				✓ 400.00
9	S	BP-SUBLET REMOVE & INSTALL TAILGATE TOP SPOILER				✓ 127.13
10	S	BP-SUBLET REMOVE & INSTALL SEAT, CARPET, GARNISH AND TRIMMING TO ASSIST REPAIR				✓ 678.00
11	B	BP-MECH RESET ECU AND REPROGRAMME				✓ 402.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639973

TO SECURITY GUARD

3639973

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 27/04/2018
TIME 13:17

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte L

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	M/s Bone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No 0	
	Document Date 27/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFXQK	F2	ANH2OR	03/05/2012	SJT0990T	158570	16333 :7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Joi	12/04/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE REAR BUMPER, REAR TAILGATE, ETC				2712 4068.00
13	S	STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				2780 3336.00
		BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR				
		EAS				
14	1	T52159-58916 COVER, RR BUMPER <i>Delid</i>	1.00	614.80		✓ 614.80
15	2	T52153-58020 BAR, RR BUMPER, LH ?	1.00	57.20		? 57.20
16	3	T52156-58020 L/R SIDE BPR SUPPORT, <i>new</i>	1.00	78.00		✓ 78.00
17	4	T52152-58010 R/R BUMPER EXTENSION, <i>new</i>	1.00	57.30		✓ 57.30
18	5	T52155-58030 R/R SIDE BPR SUPPORT, <i>new</i>	1.00	78.00		✓ 78.00
19	6	T52165-58020 E1 COVER, RR BUMPER <i>Delid</i>	1.00	198.40		✓ 198.40
20	7	S52161-0K040 CLIPS <i>new</i>	10.00	3.90		✓ 39.00
21	8	T52162-58010 E1 PLATE, RR BUMPER <i>Delid</i>	1.00	15.20		✓ 15.20
22	9	T81910-13022 R/REAR BPR REFLECTOR, <i>new</i>	1.00	58.00		✓ 58.00
23	0	T58307-58038 PANEL SUB-ASSY, BODY <i>Delid.</i>	1.00	1019.20		✓ 1019.20
24	1	T57081-58020 R/REAR BUMPER BRACKET, ?	1.00	106.30		? 106.30
25	2	T67005-58120 REAR BACK DOOR PANEL, <i>Delid.</i>	1.00	1869.50		✓ 1869.50
26	3	T67881-58020 RR BACK DOOR W/STRIP, <i>new</i>	1.00	395.10		✓ 395.10
27	4	T68105-58091 REAR BACK DOOR GLASS, <i>NEC</i>	1.00	1168.50		✓ 1168.50
28	5	T76801-58110 E0 GARNISH SUB-ASSY, ?	1.00	1994.60		? 1994.60
29	6	T67750-58061 A0 BOARD ASSY, BACK ?	1.00	684.60		? 684.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639974

TO SECURITY GUARD

3639974

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 27/04/2018
TIME 13:17

VEHICLE NO SJT0990T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!


Account Detail	Account No	Customer Detail
EQ Insurance Company Ltd 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110	S1000021 / ICEQI1	M/s Eone Diesel Pte Ltd 31 Bukit Batok Crescent #01-26 The Splendour Singapore 658070 Work: 66439970
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
12	PFQK	F2	ANH2OR	03/05/2012	SJT0990T	158570	16333 :7DS/SJT0990T/23031:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTEGD21H808216694	2AZH860320	30	Sam San Joi	12/04/2018	8.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	7	T67750-58061 AO BOARD ASSY, BACK <i>Repaired</i>	1.00	684.60		* 684.60
31	8	T69350-28161 REAR BACK DR LOCK ASSY (W/PWR D ?	1.00	475.10		? 475.10
32	9	T69430-28050 STRIKER ASSY, BACK <i>new</i>	1.00	39.60		* 39.60
33	0	T90975-02066 TOYOTA SYMBOL EMBLEM, <i>new</i>	1.00	72.20		✓ 72.20
34	1	T75441-58030 " ALPHARD" EMBLEM, <i>new</i>	1.00	66.20		✓ 66.20
35	2	T89348-64030 E1 RETAINER, ULTRASONIC ?	1.00	17.10		? 17.10
36	3	T89341-76010 E2 SENSOR, ULTRASONIC ?	1.00	385.50		? 385.50
37	4	T89348-30030 E3 RETAINER, ULTRASONIC ?	1.00	17.10		? 17.10
38	5	T89341-76010 E2 SENSOR, ULTRASONIC ?	1.00	385.50		? 385.50
39	6	T67935-58022 AO PLATE, BACK DOOR <i>new</i>	1.00	176.00		✓ 176.00
40	7	T04562-12010 FRT W/SCREEN DAM KIT, <i>new</i>	1.00	101.00		✓ 101.00
41	8	T08826-08609 SUPER FAST URETHANE BLACK <i>new</i>	2.00	90.08		✓ 180.16
42	9	T08826-08682 SINGLE STEP PRIMER	2.00	173.44		✓ 346.88

Adrian King
P/P 02/05/18
09 Day

Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• Any modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

For & on behalf of Borneo Motors	Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Customer's Signature	Signature Summary	Total	22,034.77
	Please acknowledge receipt of vehicle		Parts	11,380.64	GST 7.00%	1,542.43
	Acknowledged by Repairer		Labour	432.00		
	Signature:		Materials	10,222.13	Less	0.00
	Date:		Lubrication/Fluid	0.00		
			Others	0.00	Amount Due	23,577.20

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SJT0990T

CUSTOMER

DATE 27/04/2018
TIME 13:17SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors