

(08/11/13)

Surveyor: Puan

REF:

NS/INC 18007511 / Rlg0n2

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_


Insured: FBF 3280HPolicy No. 5083277708-01 23.11.17 - 22.11.18Claims No. MT/0992468-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHB 532B Yr Regn: 2014 / JunType: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: TOYOTA PRINS c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp.Reading: 665016 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: 3TDKN 364865746527Gen. Cond: Good / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nif / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 21/04/18 D.O.I. 23/04/18Survey held at SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SHB 532B - NS/INC 15005448 / Kibb3DA: 20031504/18/2013FBF 3280H - X24/5/10:26am Confirmed LE \$1500f and 3 days with Peh Swan.Lead \$4819.70, 2672.)NTAL

RECEIVED 25 MAY 2018

FBF 3280H

Date/Time, File Pass to?

11/25/15 Puan

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)Survey Fee: 160Transportation: 35

\$ + RS, \$ SI

Photos

Others

TOTAL

195Report Format: TPLump Sum / I.B.I: (\$ 1500f)



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007511/R1qb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-04-2018  
189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBF 3280H	Veh. Inspected	SHB 532B
Policy No.	5083277708-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	21/04/2018	Inspection Date	23/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# TP Claims against NTUC Income: Follow-Through Survey

Date : 25/05/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/0992468-002	SMRT TAXIS PTE LTD	SHB 532B	FBF 3280H	21/04/2018	8:50	\$ 6,319.70	\$ 1,500.00
2	NOT INSURED	SMRT BUSES LTD	SMB 5013R	PC 2533K	26/02/2018	10:30	\$ 25,129.10	\$ 20,973.28

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="21/04/2018 13:10"/>						
Vehicle No.(For Motor)	<input type="text" value="FBF3280H"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5083277708-01	SURAJ DUBEY S/O HRIDAI NARAIN DUBEY	S90008571	GMC	Third Party, Fire & Theft	FBF3280H	FBF3280H	23/11/2017	22/11/2018
<input type="button" value="Continue"/>									

## Celine Fong (LKKAUTO)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Thursday, 24 May 2018 10:28 AM  
**To:** Celine Fong (LKKAUTO)  
**Cc:** SUR; CS A Team; Rasul (LKKAUTO)  
**Subject:** RE: SHB532B

Hi

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Celine Fong (LKKAUTO) [mailto:celinefong@lkkauto.com]  
**Sent:** Thursday, 24 May 2018 10:26 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Cc:** SUR; CS A Team; Rasul (LKKAUTO)  
**Subject:** RE: SHB532B

Dear Poh Suan,

Confirmed lump sum \$1,500.00, 3 days.

Best Regards,  
Celine Fong  
LKK Auto Consultants Pte Ltd  
phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,  
#02-25 | S(408933)

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Saturday, 5 May 2018 11:26 AM  
**To:** Rasul (LKKAUTO) <Rasul@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; 'Leong Chee kwong' <cheekwongwega@gmail.com>  
**Subject:** SHB532B

Hi Rasul,

Attached herewith the repair estimate of SHB 532B having Case No: TAX/04/18/2103.

There is no change to the approved amount of \$1,500 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

## Celine Fong (LKKAuto)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Saturday, 5 May 2018 11:26 AM  
**To:** Rasul (LKKAuto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** SHB532B  
**Attachments:** img-505112504-0001.pdf

Hi Rasul,

Attached herewith the repair estimate of SHB 532B having Case No: TAX/04/18/2103.

There is no change to the approved amount of \$1,500 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards

Poh Suan

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Sent:** Saturday, 5 May 2018 11:25 AM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
**Subject:** Scan Data from FX-D421D6

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/04/2018 11:09
Date Of Accident	21/04/2018 08:50
Exact Location Of Accident	MANDAI ROAD /MANDAI LAKE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB532B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	SEE CHOR HEE
NRIC No	S0556940J
Date Of Birth	09/12/1945
Occupation	OUTDOOR
Date Of Driving Pass	13/04/1967
Driving Experience	51 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 04-53  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : UNKNOWN  
 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20180421/2030 ON 21/04/2018, 0850HRS, I BRAKED AND STOPPED MY VEHICLE, BEARING VEHICLE PLATE NUMBER SHB532B, AS THE TRAFFIC LIGHT WAS TURNING RED, SUDDENLY A MOTORCYCLE, BEARING VEHICLE PLATE NUMBER FBF3280H, KNOCKED MY VEHICLE IN THE REAR. THE MOTORCYLIST WAS CONVEYED TO THE HOSPITAL BY AN AMBULANCE AND I WAS ADVISED BY THE POLICE AT THE SCENE TO LODGE A REPORT.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBF3280H  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category MOTORCYCLE  
 Name of Driver UNKNOWN  
 NRIC/Passport Number



Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	UNKNOWN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBF3280H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	





**SINGAPORE  
POLICE FORCE**



T/20180421/2030

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

1 of 3

Report No. T/20180421/2030

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/04/2018 10:02		Vide Report No.:		Station Diary No.: 41	
<b>Informant's Particulars</b>					
Name of Informant: SEE CHOR HEE			Address: APT BLK 298 YISHUN STREET 20 #04-53 SINGAPORE 760298		
ID Type / ID No.: NRIC NO / S0556940J			Contact No.: Home/Office: Mobile: 91389878		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 72	Date of Birth: 09/12/1945	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/04/2018 08:50	Type of Location: T-Junction
Location: Along Road 1 MANDAI ROAD MANDAI LAKE ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBF3280H	Motorcycle	SUZUKI	GSX1300RL 0	Blue	Slightly Damaged	0 <sup>12</sup>
SHB532B	Car	TOYOTA	PRIUS TAXI (SMRT)	Maroon	Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180421/2030

2 of 3

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20180421/2030

## CONTINUATION OF REPORT

Driver			
Name	SEE CHOR HEE		ID No. S0556940J
Related Vehicle	SHB532B (Car)		Contact No. 91389878
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL

**Brief Details.**

On 21/04/2018, 0850hrs, I braked and stopped my vehicle, bearing vehicle plate number SHB532B, as the traffic light was turning red. Suddenly a motorcycle, bearing vehicle plate number FBF3280H, knocked my vehicle in the rear. The motorcyclist was conveyed to the hospital by an ambulance and I was advised by the Police on scene to lodge a report.



**SINGAPORE  
POLICE FORCE**



T/20180421/2030

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

3 of 3

Report No. T/20180421/2030

## CONTINUATION OF REPORT


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 LOW WEI DE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/04/2018 10:02
Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216	Classification Of Case:

Authentication Stamp  
NP158



## Enquire Transfer Fee

### Vehicle Details

Vehicle No.:	SHB532B
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Chassis No.:	JTDKN36U805746527
Propellant:	Petrol-Electric
Engine No.:	2ZR1327172
Motor No.:	3JM6084468
Engine Capacity:	1798 cc
Power Rating:	60.0 kW
Maximum Power Output:	100.0 kW ( 134 bhp)
Maximum Laden Weight:	1805 kg
Unladen Weight:	1370 kg
Year Of Manufacture:	2014
Original Registration Date:	25 Jun 2014
Lifespan Expiry Date:	24 Jun 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid:	\$57,338.00
COE Expiry Date:	24 Jun 2022
Road Tax Expiry Date:	24 Jun 2018
PARF Eligibility Expiry Date:	24 Jun 2022
Inspection Due Date:	24 Dec 2018
Intended Transfer Date:	24 May 2018
CO2 Emission:	92.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$30,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 24 Jun 2018. You may renew the road tax from 25 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 24 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.  
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 25 Jun 2018 to 24 Dec 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
<b>Sub Total:</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment):	510.00	-	510.00
<b>Total Amount Payable:</b>			<b>535.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB532B  
Ref. No : TAX/04/18/2103  
Reg. Date : 25/06/2014  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : SEE CHOR HEE  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 21/04/2018 08:50:00 AM  
Accident Reported Date / Time : 21/04/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095669  
Special Instruction to ARC, if any :  
FBF3280H / *NOTE / Resurvey after repair*  
Prepared Date : 21/04/2018 11:20:16 AM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No. : JTDKN36U805746527

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,233.88	2,279.47
Other Charges	: 705.00	0.00
<b>TOTAL</b>	<b>: 4,888.88</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 4,900.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	0.00 <i>3 days - Lump sum</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 21/04/2018 01:50:31 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/04/2018 01:50:31 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No. :

Invoice No. :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hereby notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to change
- Third party survey is on a "No Win - No Fee" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval

Acknowledged by Repairer

Signature:

Date:



## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 300
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 <del>200</del> 100
TO RESPRAY REAR FENDER LH	378.00	0.00 X
<b>Total Spray Painting &amp; Panel Beating</b>	<b>936.00</b>	<b>0.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 20
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 60
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
<b>Total Other Costs</b>	<b>705.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>Sur</i> ✓	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace <i>B</i> ✓	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace X	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace <i>DE</i> ✓	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace X	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>Sur</i> ✓	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>ne</i> ✓	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace X	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>ne</i> ✓	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace <i>Repair</i> ✓	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace X	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace X	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace X	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace X	No
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace X	No
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace X	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace ?	No
<b>TOTAL MATERIALS</b>							<b>2,849.38</b>	<b>2,849.34</b>		
<b>TOTAL MATERIALS(Discounted)</b>							<b>2,233.88</b>	<b>2,279.47</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

### REQUEST FOR SUPPLYMENT PARTS

[illegible]

• Please submit photographs for damaged parts •

1. (Name) Guan

(Position)

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration \_\_\_\_\_

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff	
Acknowledge By	ARC Executive Supervisor SA
Approval By	Surveyor / In-house Staff
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES NO Date of submission



Attached  
Supplementary  
Guan

26-4-18 / 11.32  
26-4-18 / 15.32

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

23-4-18 / 15.32

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB532B  
Ref. No : TAX/04/18/2103  
Reg. Date : 25/06/2014  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : SEE CHOR HEE  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 21/04/2018 08:50:00 AM  
Accident Reported Date / Time : 21/04/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Rasul  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024095669  
Special Instruction to ARC, if any :  
FBF3280H NEW 45  
Resurvey After repair, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001  
0068. email: rasul@lkkauto.com  
Prepared Date : 21/04/2018 11:20:16 AM



Vehicle to Wega Date In: 24/04 Towing: \_\_\_\_\_  
Time In: 1200 Driver: Guan.  
Wega Job No: 04/0263  
Vehicle sent to SMRT Date In: 26/4/18 Towing: \_\_\_\_\_  
Time In: 11.30 Driver: Chin  
Received by (SMRT): \_\_\_\_\_

Recording Camera ☒ ☐

Radio Antenna ☒ ☐

1st witness \_\_\_\_\_ Date 23-4-18

2nd witness \_\_\_\_\_ Date \_\_\_\_\_

E 1/2 F  
KM 665015

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U805746527

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	300.00
Total Spray Painting Charges	: 936.00	300.00
Total Material Charges	: 782.63	1,199.84
Other Charges	: 705.00	-299.84
<b>TOTAL</b>	<b>: 3,437.63</b>	<b>1,500.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	3.00
Prepared / Adjusted By	:	RASUL
Arc / Surveyor Sing Off Date	: 21/04/2018 01:50:31 PM	23/04/2018 03:32:58 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/04/2018 01:50:31 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1805-0025

Invoice No :

Quotation Date : 3/5

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	300.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>300.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR FENDER LH	378.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>936.00</b>	<b>300.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-379.84
<b>Total Other Costs</b>	<b>705.00</b>	<b>-299.84</b>



# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>TORN</i>
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No <i>BT</i>
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace <i>S</i>	No <i>BT</i>
52015-47050			ARM SUB-ASSY, RR BUMPER RH	0	139.60	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>S</i>	No <i>CRA</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>DE</i>
76087-47020		6505618	BUMPER LIP COVER RR/RH	0	118.10	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No <i>SCR</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>NEC</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	0	94.80	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>NEC</i>
58307-47060		6505522	END PANEL	1	602.10	100.00	0.00	Replace	Repair	No <i>R</i>
	COMMON	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
61602-47091		6505476	FENDER RR/LH	0	766.80	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
	COMMON		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
	COMMON		STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
62720-47031			QUARTER GLASS RR/LH	0	168.10	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
65638-47021		6505477	FENDER LINER RR/LH	0	141.30	25.00	0.00	Replace	Not given	No <i>X</i> <i>SVC</i>
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.03	Replace	Check	No <i>X</i> <i>SVC</i>
TOTAL MATERIALS							1,222.88	1,199.84		
TOTAL MATERIALS(Discounted)							782.63	1,199.84		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1199.84  
+ 300.00  
+ 380.00  


---

1879.84  
- 202  


---

1503.87

45 \$1500/-  
639.70



Thatcham escribe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007511/R1qbn2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 28-05-2018	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBF 3280H	Veh. Inspected	SHB 532B
Policy No.	5083277708-01	Coverage (\$)	0.00
Claim No.	MT/0992468-002	Excess (\$)	0.00
Assign From		Assign Date	23/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U805746527	Colour	MAROON
Odometer	665016	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/04/2018	Inspection Date	23/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 532B**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER REAR (DISC 25%)	TORN	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY,RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER LIP REAR (DISC 25%)	SCRATCHED	228.90	171.67
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	SENSOR REVERSE (SN)	CRACKED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SOLAR FILM	NOT NECESSARY	125.00	-
1	ARM SUB-ASSY,RR BUMPER RH	SERVICEABLE	139.60	-
1	BUMPER LIP COVER RR/RH	SERVICEABLE	118.10	-
1	BUMPER SIDE RETAINER RR/RH	SERVICEABLE	94.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	FENDER RR/LH	SERVICEABLE	766.80	-
1	SMRT LOGO	SERVICEABLE	7.80	-
1	STICKER DECAL 65558888	SERVICEABLE	21.60	-
1	QUARTER GLASS RR/LH	SERVICEABLE	168.10	-
1	SEALANT W/SCREEN	SERVICEABLE	37.00	-
1	FENDER LINER RR/LH	SERVICEABLE	141.30	-
1	TAIL LAMP BRACKET,LH	SERVICEABLE	30.70	-
1	END PANEL	TO REPAIR	602.10	-
			<b>3,789.70</b>	<b>1,199.84</b>
<b>LABOUR</b>				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,334.00	360.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,036.00	320.00
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			<b>2,530.00</b>	<b>680.00</b>
<b>GRAND TOTAL</b>			<b>6,319.70</b>	<b>1,879.84</b>

Report Ref No. NS/INC18007511/R1qbn2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,500.00
--	--	--	----------

Report Ref No. NS/INC18007511/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.