

10/15/11
SERVING

Paran

REF:

NS/INC18007512/Rlvbnz

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SLG 31367
 Policy No: 5034763561-01 08.10.17 - 07.10.18
 Claims No: MT/0991252-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 1399M Yr Regn: 2016 / 1st
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Car / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA PRIMS c.c. 1798
 Colour: MAROON A/C: Insured / Std / NI / NA
 Sp. Reading: 221056 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STDKN36405768305
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Mod: Nil / SR / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front _____ Rear _____
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 20/04/18 D.O.I. 23/04/18
 Survey held at SMRT
 Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	DA: 78072019	04/18/2104
	SHB 1399M - NJM / INC09016204 / Tly	DA: 190317	NJM
	SLG 34367 - C04 / 17015579 / 000352		
9/5/18	Final fig \$ 7891.32 confirmed by email (Ref 8558-46, 529)		SLH 3436
	RECEIVED 03 MAY 2018		
			OR per 09/05/18

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 9/5 - typist
 Report Format: TP
 Lump Sum / I.B.I. (\$) 7891.32

Days Of Repair: 6
 Resurvey No. of Trip: 2
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
 Survey Fee: 160
 Transportation: 35
) S+RS, SI
) Photos
) Others
) :
 TOTAL 195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC18007512/R1vb
73 BRAS BASAH ROAD		
#05-01 NTUC TRADE UNION HOUSESINGAPORE	Date: 24-04-2018	
189556	Code: INC4	

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 343G	Veh. Inspected	SHB 1399M
Policy No.	5084763561-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/04/2018	Inspection Date	23/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Veron Chen (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Wednesday, 9 May 2018 1:56 PM
To: Veron Chen (LKKAuto)
Subject: REQUEST FOR CLAIM NUMBER

Hi,

claim created.

With Regards

Samsia
Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, May 09, 2018 11:21 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Please provides us claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0991252-002	SMRT TAXIS PTE LTD	SHB 1399M	SLG 343G

D.O.A	Time of Accident	Estimate	Tentative repair cost
20/4/2018	17:55	\$16,449.78	\$7,891.32

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

Change Language

Change Password

Log Out

My Desktop
Notice of Loss

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5084763561-01	HY INVESTMENTS PTE. LTD.	201107460R	GPC	drive CLASSIC	SLG343G	SLG343G	08/10/2017	07/10/2018

Continue

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Wednesday, 9 May 2018 11:25 AM
To: Veron Chen (LKKAuto); Rasul (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB1399M

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 9 May 2018 11:15 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB1399M

Dear Poh Suan

WITHOUT PREJUDICE

Confirmed amount of \$7,891.32 @ 6 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 5 May 2018 11:31 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB1399M

Hi Rasul,

Attached herewith the repair estimate of SHB 1399M having Case No: TAX/04/18/2104.

There is no change to the approved amount of \$7,891.32 @ 6 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Saturday, 5 May 2018 11:10 AM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 9 May 2018 11:15 AM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Rasul (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB1399M

Dear Poh Suan

WITHOUT PREJUDICE

Confirmed amount of \$7,891.32 @ 6 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Saturday, 5 May 2018 11:31 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB1399M

Hi Rasul,

Attached herewith the repair estimate of SHB 1399M having Case No: TAX/04/18/2104.

There is no change to the approved amount of \$7,891.32 @ 6 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Saturday, 5 May 2018 11:10 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/04/2018 10:31
Date Of Accident	20/04/2018 17:55
Exact Location Of Accident	ARCHITECTURE DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1399M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	GULAM HUSSAIN GULAM YUSUF
NRIC No	S8138969A
Date Of Birth	20/12/1981
Occupation	OUTDOOR
Date Of Driving Pass	31/07/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	424
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAIN STOPPED
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ALONG ARCHITECTURE DRIVE WITH A PASSENGER ON BOARD AND WHILE NEGOTIATING A BEND, SUDDENLY THE VEHICLE SLG343G FROM THE OPPOSITE DIRECTION LANE ENCROACHED INTO MY LANE AND COLLIDED HEAD ON INTO MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG343G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ZHU ZHIHAI
NRIC/Passport Number	S7174850B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	GULAM HUSSAIN GULAM YUSUF
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB1399M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> **Back to OneMotoring**

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHB1399M
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1 :	Air-Con (Taxi)
Vehicle Scheme :	Taxi (Company)
Vehicle Make :	TOYOTA
Vehicle Model :	PRIUS TAXI (SMRT)
Chassis No. :	JTDKN36U105768305
Propellant :	Petrol-Electric
Engine No. :	2ZR1683379
Motor No. :	3JM1683379
Engine Capacity :	1798 cc
Power Rating :	60.0 kW
Maximum Power Output :	100.0 kW (134 bhp)
Maximum Laden Weight :	1805 kg
Unladen Weight :	1370 kg
Year Of Manufacture :	2015
Original Registration Date :	28 Jun 2016
Lifespan Expiry Date :	27 Jun 2024
COE Category :	A - Car up to 1600cc & 97kW (130bhp)
PQP Paid :	\$37,164.00
COE Expiry Date :	27 Jun 2024
Road Tax Expiry Date :	27 Jun 2018
PARF Eligibility Expiry Date :	27 Jun 2024
Inspection Due Date :	27 Dec 2018
Intended Transfer Date :	14 May 2018
CO2 Emission :	92.00 (g/km)
CEV/MES Rebate Utilised Amount :	\$28,312.00
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 27 Jun 2018. You may renew the road tax from 28 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 27 Jun 2018, late renewal fee(s) will be imposed. Please use [Enquire Road Tax Payable](#) to check on the late fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 28 Jun 2018 to 27 Dec 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
Total Amount Payable :			535.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1399M
 Ref. No : TAX/04/18/2104
 Reg. Date : 28/06/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : GULAM HUSSAIN GULAM YUSUF
 Type of Accident : HEAD-ON
 Date / Time of Accident : 20/04/2018 05:55:00 PM
 Accident Reported Date / Time : 21/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 20/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095668
 Special Instruction to ARC, if any :
 TOWED \$60 / SLG343G / NMC / Repair by part
 Prepared Date : 21/04/2018 10:51:04 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105768305

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	936.00	0.00
Total Material Charges :	8,661.81	10,827.26
Other Charges :	944.00	0.00
TOTAL :	11,555.81	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	<i>4</i>
Prepared / Adjusted By :		<i>3 days - p/p</i>
Arc / Surveyor Sing Off Date :	23/04/2018 08:58:14 AM	01/01/1900 12:00:00 AM



Per 23/04/18 @ 1430

Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/04/2018 08:58:14 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
 Quotation Date : Invoice Date :
 Invoice Amount : Prepared Date :

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 150
TO REPSRAY FRONT HOOD	378.00	0.00 200
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X
TO TOP UP A/C GAS	120.00	0.00 80
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 X
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	150.00	0.00 100 X
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	944.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>DE</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>BA</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>NE</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>NE</i>	No
52128-47903			COVER, FR BUMPER HOLE LH	1	18.50	25.00	13.87	Replace	Replace <i>X</i>	No
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace <i>X</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>CRA</i>	No
81220-12230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Replace ?	No
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace ?	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace ?	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
53113 - 47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace <i>DE</i>	No
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace ?	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>NE</i>	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace <i>BA</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>CRA</i>	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace <i>NE</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace <i>DE</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace ?	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace ?	No
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace ?	No
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace ?	No
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.67	Replace	Replace ?	No
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Replace ?	No
16711-37040			FAN SHROUD	1	244.50	25.00	183.37	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
16361-37010			FAN BLADE	1	158.60	25.00	118.95	Replace	Replace ?	No
16361-28360			FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Replace ?	No
16363-37010			FAN MOTOR NO 1	1	538.30	25.00	403.72	Replace	Replace X ?	No
16363-37020			FAN MOTOR NO 2	1	538.30	25.00	403.72	Replace	Replace X ?	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace Repair	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace X	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace X	No
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace X	No
TOTAL MATERIALS							10,609.53	10,609.46		
TOTAL MATERIALS(Discounted)							8,661.81	10,827.26		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



27.4.18/11.52
27.4.18/15.52

23.4.18/15.52


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SHB1399M
 Ref. No : TAX/04/18/2104
 Reg. Date : 28/06/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : GULAM HUSSAIN GULAM YUSUF
 Type of Accident : HEAD-ON
 Date / Time of Accident : 20/04/2018 05:55:00 PM
 Accident Reported Date / Time : 21/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Rasul
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 20/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095668
 Special Instruction to ARC, if any :
 TOWED \$60 / SLG343G NTUL P/P
 Resurvey Before paint, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com
 Prepared Date : 21/04/2018 10:51:04 AM

for 28/4

Uh stall



Resurvey Before paint, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com



Recording Camera
 Radio Antenna
 1st witness [Signature] Date 23.4.18
 2nd witness _____ Date _____

QC 28-4-18 8:55 Reject
 FR + Problem check
 Body wash
 11:00 pass

Supplementary 221057
 to Refer to the Supplementary part 11/12/18

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 27-4-2018
 Vehicle Return Time: 16:15

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105768305

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	550.00
Total Spray Painting Charges	: 936.00	500.00
Total Material Charges	: 8,960.87	6,621.32
Other Charges	: 860.00	220.00
TOTAL	: 11,770.87 <i>K, 449.78</i>	7,891.32
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	6.00
Prepared / Adjusted By	:	RASUL
Arc / Surveyor Sing Off Date	: 23/04/2018 08:58:14 AM	23/04/2018 03:52:55 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/04/2018 08:58:14 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : *QIN-1805-0023*

Invoice No :

Quotation Date : *3/5*

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	550.00
Total Labour	1,014.00	550.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00
TO REPSRAY FRONT HOOD	378.00	200.00
Total Spray Painting & Panel Beating	936.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00
TO TOP UP A/C GAS	120.00	80.00
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	150.00	100.00
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	860.00	220.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace DE	No ✓
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace BT	No ✓
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace BT S	No ✓
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace BT S	No ✓
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace CHA S	No ✓
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace NEW	No ✓
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace NEW	No ✓
52128-47903			COVER, FR BUMPER HOLE LH	0	18.50	25.00	0.00	Replace	Not given SW	No X
52127-47903			COVER, FR BUMPER HOLE RH	0	18.50	25.00	0.00	Replace	Not given SW	No X
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace CRA	No ✓
81220-12230		6505438	FOG LAMP LH	1	280.10	10.00	252.09	Replace	Check SW	No X
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Check SW	No X
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Check SW	No X
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78 45.77	Replace	Replace S CRA	No ✓
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace CRA	No ✓
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.23	Replace	Check SW	No X
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace NEW	No ✓
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace RA	No ✓
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace CRA	No ✓
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace NEW	No ✓
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace DE	No ✓
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace SPT	No ✓
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace S CRA	No ✓
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Check SW	No X
G9010-47031			RADIATOR ASSY, UPPER	1	679.60	25.00	509.70	Replace	Replace SPT	No ✓
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.43 886.43	Replace	Replace SPT	No ✓
16400-37230		6505302	RADIATOR ASSY	1	1,496.90	25.00	1,122.68	Replace	Replace SPT	No ✓
16712-37030			FAN SHROUD TOP	1	99.60	25.00	74.70	Replace	Check SW	No X
16711-37040			FAN SHROUD	1	244.50	25.00	183.38	Replace	Check SW	No X

11,049.20

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
16361-37010			FAN BLADE	1	158.60	25.00	118.95	Replace	Check <i>see</i>	No <input checked="" type="checkbox"/>
16361-28360			FAN BLADE NO 2	1	204.20	25.00	153.15	Replace	Check <i>see</i>	No <input checked="" type="checkbox"/>
16363-37010			FAN MOTOR NO 1	0	538.30	25.00	0.00	Replace	Not given <i>see</i>	No <input checked="" type="checkbox"/>
16363-37020			FAN MOTOR NO 2	0	538.30	25.00	0.00	Replace	Not given <i>see</i>	No <input checked="" type="checkbox"/>
53301-47060		6505555	HOOD PANEL	1	748.10	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
53420-47070			HOOD HINGE LH	0	55.90	25.00	0.00	Replace	Not given <i>see</i>	No <input checked="" type="checkbox"/>
53410-47070			HOOD HINGE RH	0	55.90	25.00	0.00	Replace	Not given <i>see</i>	No <input checked="" type="checkbox"/>
82113-47180			WIRE, ENGINE ROOM, NO.3	0	242.00	10.00	0.00	Replace	Not given <i>see</i>	No <input checked="" type="checkbox"/>
	COMMO N		COOLANT	4	12.32 <i>49.28</i>	0.00	49.28	Replace	Replace <i>see</i>	No <input checked="" type="checkbox"/>
TOTAL MATERIALS								8,960.89	6,621.33	
TOTAL MATERIALS(Discounted)					2590.58			8,960.87	6,621.32	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	COMMO N	COOLANT	4	12.32	0.00	49.28	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						49.28			

6621.32
 + 550.00
 + 720.00

 7891.32



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18007512/R1vbn2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-05-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 343G	Veh. Inspected	SHB 1399M
Policy No.	5084763561-01	Coverage (\$)	0.00
Claim No.	MT/0991252-002	Excess (\$)	0.00
Assign From		Assign Date	23/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U105768305	Colour	MAROON
Odometer	221056	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/04/2018	Inspection Date	23/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1399M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
1	BUMPER REINFORCEMENT FRT (DISC 25%)	BENT	498.40	373.80
1	ARM SUB-ASSY,FR BUMPER LH (DISC 25%)	BENT	250.40	187.80
1	ARM SUB-ASSY,FR BUMPER RH (DISC 25%)	BENT	250.40	187.80
1	BUMPER ENERGY ABSORBER FRT (DISC 25%)	CRACKED	78.80	59.10
1	BUMPER SUPPORT F/LH (DISC 25%)	NECESSARY	76.40	57.30
1	BUMPER SUPPORT F/RH (DISC 25%)	NECESSARY	76.40	57.30
1	BUMPER GRILLE SUB-ASSY,LOWER (DISC 25%)	CRACKED	311.10	233.32
1	BUMPER FRT ABSORBER LOWER (DISC 25%)	CRACKED	127.70	95.77
1	GRILLE RADIATOR LOWER NO 2 (DISC 25%)	CRACKED	94.60	70.95
1	BRACKET,FR BUMPER (DISC 25%)	NECESSARY	110.40	82.80
1	EMBLEM FRONT (DISC 25%)	NECESSARY	86.50	64.87
1	GRILLE,RADIATOR (DISC 25%)	DEFORMED	310.60	232.95
1	SUPPORT SUB-ASSY (DISC 25%)	BENT	1,460.40	1,095.30
1	RADIATOR ASSY,UPPER (DISC 25%)	BENT	679.60	509.70
1	A/C CONDENSER (DISC 25%)	BENT	1,181.90	886.42
1	RADIATOR ASSY (DISC 25%)	BENT	1,496.90	1,122.68
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68
1	NUMBER PLATE (SN)	BENT	30.00	30.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
4	SOOLANT @\$12.32 (SN)	NECESSARY	49.28	49.28
1	COVER.FR BUMPER HOLE LH	SERVICEABLE	18.50	-
1	COVER.FR BUMPER HOLE RH	SERVICEABLE	18.50	-
1	FOG LAMP LH	SERVICEABLE	280.10	-
1	FOG LAMP RH	SERVICEABLE	295.20	-
1	BUMPER LIP FRT	SERVICEABLE	139.60	-
1	UNDER COVER CENTER	SERVICEABLE	448.30	-
1	HEAD LAMP RH	SERVICEABLE	945.20	-
1	FAN SHROUD TOP	SERVICEABLE	99.60	-
1	FAN SHROUD	SERVICEABLE	244.50	-

Report Ref No. NS/INC18007512/R1vbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN BLADE	SERVICEABLE	158.60	-
1	FAN BLADE NO 2	SERVICEABLE	204.20	-
1	FAN MOTOR NO 1	SERVICEABLE	538.30	-
1	FAN MOTOR NO 2	SERVICEABLE	538.30	-
1	HOOD HINGE LH	SERVICEABLE	55.90	-
1	HOOD HINGE RH	SERVICEABLE	55.90	-
1	WIRE, ENGINE ROOM, NO 3	SERVICEABLE	242.00	-
1	HOOD PANEL	TO REPAIR	748.10	-
			13,639.78	6,621.32
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,614.00	770.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,036.00	500.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,810.00	1,270.00
	GRAND TOTAL		16,449.78	7,891.32
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			7,891.32

Report Ref No. NS/INC18007512/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.