



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

yet survey, call 288 1111 11
arrange)

GOLDBELL ENGINEERING PTE LTD
Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676
Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

DATE : 18/04/2018

TO : QI FU ENTERPRISE CO PTE LTD

ATTN : -

OFFICE / MOBILE : -

EMAIL ADDRESS : -

FROM : GOLDBELL ENGINEERING P/L

ATTN : MR LI LEWEI

OFFICE / MOBILE : 6864-0637 / 9755-7336

FAX NO. : 6863-0425

VEHICLE NO. : YP6747J

MODEL NO. : MITSUBISHI FEB21ER4SDEB

CHASSIS NO. : FEB21EA21315

ENGINE NO. : 4P10C48676

REG. DATE : 29/06/2017

REF. NO. : GBE/SVC/SALES-4624/180418

D.O.A. : 16/03/2018

POLICY NO. : DMCPhQ17-003395

CLAIM TYPE : TP CLAIM - EQ

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	MX908802	FRONT WINDSCREEN WEATHERSTRIP <i>re</i> ✓	1	\$ 477.20
2	ML230271	FRONT PANEL <i>BT</i> ✓	1	\$ 2,320.79
3	MC978995	FRONT PANEL GARNISH <i>DE</i> ✓	1	\$ 365.77
4	MK546617	"FUSO" MARK <i>re</i> ✓	1	\$ 147.63
5	MC978571	RADIATOR GRILLE <i>CRA</i> ✓	1	\$ 1,053.14
6	MK675497	"CANTER" MARK <i>re</i> ✓	1	\$ 74.70
7	MK546616	"THREE-DIA" MARK <i>X</i>	1	\$ 78.66
8	MK614805	RADIATOR GRILLE BRACKET <i>X</i>	1	\$ 24.96
9	MC978516	FRONT BUMPER <i>BT</i> ✓	1	\$ 929.76
10	MK618510	FRONT BUMPER STAY LHS <i>?</i>	1	\$ 186.95
11	MK618511	FRONT BUMPER STAY RHS <i>BT</i> ✓	1	\$ 186.95
12	MK618527	FRONT BUMPER COVER LHS <i>me</i> ✓	1	\$ 325.54
13	MK618528	FRONT BUMPER COVER RHS <i>DE</i> ✓	1	\$ 325.54
14	MK580551	HEADLAMP LHS <i>?</i>	1	\$ 461.45
15	MK580552	HEADLAMP RHS <i>BT</i> ✓	1	\$ 461.45
16	MK580527	TURN SIGNAL LAMP LHS <i>CRA</i> ✓	1	\$ 245.15
17	MK580528	TURN SIGNAL LAMP RHS <i>BR</i> ✓	1	\$ 245.15
18	MK583365	HEATER ASSY <i>?</i>	1	\$ 2,337.68
19	MK583357	AIR INTAKE DUCT ASSY <i>?</i>	1	\$ 829.06
20	MK648573	HORN <i>?</i>	1	\$ 124.36
21	MK649126	HORN COVER <i>?</i>	1	\$ 108.32
22	MK580948	REAR VIEW MIRROR LHS <i>?</i>	1	\$ 93.59
23	MK580523	REAR VIEW MIRROR STAY LHS <i>see</i> ✓	1	\$ 437.17
24	MK580752	FRONT UNDER VIEW MIRROR LHS <i>me</i> ✓	1	\$ 54.09

SUB-TOTAL : \$ 11,895.06
LESS 25% : \$ 2,973.77
BALANCE : \$ 8,921.30

SPECIAL-NETT ITEMS

1	FRONT NUMBER PLATE <i>BT</i> ✓	1	\$ 20.00
2	SEALANT <i>?</i>	1	\$ 40.00
3	CARGOBOX REAR DOOR LHS/RHS <i>BT</i> <i>BT LH? / RH-BT</i> ✓	2	\$ 3,600.00
4	CARGOBOX REAR DOOR LOCK LHS/RHS <i>X</i>	2	\$ 2,600.00
5	CARGOBOX WOODEN LOWER RAIL <i>CRA</i> ✓	1	\$ 450.00
6	CARGOBOX WOODEN STEP <i>X</i>	1	\$ 400.00
7	CARGOBOX METAL STEP <i>BT</i> ✓	1	\$ 500.00
8	CARGOBOX METAL STEP STAY <i>BT</i> ✓	1	\$ 150.00



STAR

Certificate No: AJA(S)01Q1243

Certificate No: AJA(S)01Q1243



GOLDBELL ENGINEERING

GOLDBELL ENGINEERING PTE LTD

Main Office: 10 Tuas Avenue 18 Singapore 638894 Tel: 6861 0007 Fax: 6861 3676

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Industrial Vehicles.

20,000 Served. And Counting. ?

9	U-BOLT	6	\$	1,080.00
10	BOLT & NUT SET	4	\$	140.00
11	REAR BUMPER	1	\$	850.00
12	REAR BUMPER BRACKET RHS	1	\$	180.00
13	COMPANY LOGO ON CARGOBOX	1	\$	750.00
14	"60 KM/H" STICKER	1	\$	20.00

PARTS TOTAL :

\$ 19,701.30

LABOUR CHARGES

1 TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	\$ 3,000.00
2 TO CHECK FOR & RECTIFY WIRING FAULTS, ETC. TO CARRY OUT DIAGNOSTICS CHECK.	\$ 150.00
3 TO REMOVE & REFIX FRONT WINDSCREEN.	\$ 180.00
4 TO REMOVE & REFIX DASHBOARD ASSY.	\$ 700.00
5 TO REMOVE & REFIX AIRCOND SYSTEM AND TOP UP GAS. TO CHECK FUNCTION.	\$ 700.00
6 TO REMOVE, REFIX & REALIGN REAR CARGOBOX. TO REPLACE ALL DAMAGED PARTS.	\$ 3,000.00
7 TO PUTTY, CLEAN, SPRAY PAINT & POLISH, ETC.	\$ 2,800.00
8 SUNDRIES	\$ 50.00

LABOUR TOTAL :

\$ 11,210.00

GRAND TOTAL :

\$ 30,911.30

PREPARED BY : LI LEWEI

DATE / TIME : 15/11/18 @ 1430
 SURVEYOR : Rasul
 MOBILE NO. : 90010068
 OFFICE FAX NO. :
 EMAIL ADDRESS : rasul@lkkauto.com
 RE-SURVEY : BEFORE PAINT / AFTER PAINT
 NO. OF DAYS : 12-15 days
 REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



ST R

Certificate No: AJA(S)/101243

Certificate No: AJA(S)101243