

INS. CASE OWNER:

Richard JB

CC 4 / ASM1800

7518

, U jabsz

LKK:

IDAC:

41542

Surveyor:

Uls

DOI:

ASSIGNMENT

KSK/18

Date / Time:

24/04/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 8948 T

Name of Insured:

Gim Gionh Pools Supply

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

21/04/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

JIN SHAN

Driver Tel No.:

826907401 / 62621328

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S6X71257



INSRS:

WSP:

Tel:

Liability:

RMKS:

Uls



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

S6X71257 - x ; YN8948T - x

* To check OUI's PL. to get LOR.

@ 109 PM

CALLED OI: NO ANSWER.

@ 130 PM

W/OI CO. CONFIRMED ACC.
WILL CHECK LOR &
PL W/ THEIR BOSS.In amount & different in settlement
amount.

RECEIVED 10 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

23-7-18 JUY

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup) X

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice: X

Towing Invoice: X

LTA / GIA:

Medical Bill: X

PIR: X

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days)

Reduction: %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No. : 27

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

2,033. x x

Loss of Rental (LOR):

S\$

days)

Loss of Use (LOU):

S\$

250 (550 x 5

days)

Loss of Income (LOI):

S\$

(S x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

2,290.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

2,290.45

Name 1:

TAN LIM MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

Name 3:

X

C90/10/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF: ASM (AXA)

7578/4ja3

-j

ASSIGNMENT

From: Date: 15-05-2018

Estimated Cost:

OD / TP / WS / TP RES / OD-RES / EVA / INV / MV

To Inspect Vehicle No: SHX 7125T

at Workshop m/s

Tan Lim

of:

51 Dehu Lane 10

Insured:

1/N 89487

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

Bal. or Market Value:

74k

IDAC Accident Rpt:

Consistent? : Yes or No

Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SGX7125T

Yr Regn: 5-16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make:

Honda vazel

c.c. 1496

Colour:

3 blue

A/C: Insured / Std / NI / NA

Sp Reading:

034051

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU 11114319

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod:

Nil S/Rim / STD A/Rim or

Tyre Size:

F:

2.5/60R16

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal:

mm

R/Bal:

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

21/4/18

D.O.I:

15/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L7A 44587

Bye. 20796.

L/S \$1,900

R (\$4,025.84/68%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$+R\$ \$

Photos

Emails

TOTAL

Report Format:

Lump Sum / I.B.I. / \$

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18007518/ja3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 24-04-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 8948T	Veh. Inspected	SGX 7125T
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00EXT	Excess (\$)	0.00
Assign From		Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/04/2018	Inspection Date	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

AXA Insured's Veh No : YN8948T
Date of Accident : 21 April 2018

1pc commo
not Authorized
LAL
2/5/1900.00
Police photo after repair
15/5/18
4dy.



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Miss Lim Bee Hiang

Date : 23 April 2018

Estimate To Repair SGX7125T - Honda VEZEL 1.5X CVT
Chassis No : RU11114319

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid	\$ 953.30
02	1 pc	tailgate lid vezel badge	\$ 45.80
03	1 pc	tailgate lid weatherstrip	\$ 104.40
04	1 pc	tailgate lid lock	\$ 76.60
05	1 pc	tailgate lid lock striker	\$ 24.70
06	2 pc	tailgate lid reflector @ \$264.60	\$ 529.20
07	1 pc	rear end panel	\$ 415.60
08	1 pc	rear end panel inner trim	\$ 98.00
09	1 pc	rear bumper centre	\$ 508.50
10	1 pc	rear bumper clips	\$ 3.50
11	1 pc	rear bumper reflector	\$ 151.10
12	1 pc	rear bumper lower diffuser	\$ 190.00
13	1 pc	rear bumper lower diffuser clips	\$ 3.50
14	2 pc	rear bumper side @ \$148.50	\$ 297.00
15	2 pc	rear bumper side retainer @ \$27.50	\$ 55.00
16	1 ps	rear windshield glass weaterstrip	\$ 138.60
		Less 20 %	\$ 3,594.80 \$ 718.96 \$ 2,875.84
<u>SPECIAL NETT ITEMS</u>			
17	1 pc	rear bumper parking sensor	\$ 450.00
18	1 pc	rear windshield glass sealant	\$ 150.00
19	1 pc	rear windshield glass sponge seal	\$ 100.00
			\$ 700.00
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		To rust-proofing of the affected areas.	\$ 150.00
05		To remove and refit rear windscreen glass.	\$ 160.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00

1642.7
1319.76

40
30

50
60
60
30
120
300

AXA Insured's Veh No : YN8948T

Date of Accident : 21 April 2018



陳林峰摩托有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS

Miss Lim Bee Hiang

Date : 23 April 2018

Estimate To Repair SGX7125T - Honda VEZEL 1.5X CVT

Chassis No : RU11114319

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,350.00
			2,459.76
		Total	\$ 5,925.84
			1,927.81

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



陳林澤哆私人有限公司
TAN LIM MOTOR PTE LTD

AXA Insured's Veh No : YN8948T

Date of Accident : 21 April 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Lim Bee Hiang

Date : 23 April 2018

Estimate To Repair SGX7125T - Honda VEZEL 1.5X CVT
Chassis No : RU11114319

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>20/suc</i>	\$ 953.30
02	1 pc	tailgate lid vezel badge <i>nu</i>	\$ 45.80
03	1 pc	tailgate lid weatherstrip <i>11</i>	\$ 104.40
04	1 pc	tailgate lid lock <i>11</i>	\$ 76.60
05	1 pc	tailgate lid lock striker <i>11</i>	\$ 24.70
06	2 pc	tailgate lid reflector @ \$264.60 <i>11</i>	\$ 529.20
07	1 pc	rear end panel <i>1</i>	\$ 415.60
08	1 pc	rear end panel inner trim <i>11</i>	\$ 98.00
09	1 pc	rear bumper centre <i>20/nu</i>	\$ 508.50
10	1 pc	rear bumper clips <i>nu</i>	\$ 3.50
11	1 pc	rear bumper reflector <i>11</i>	\$ 151.10
12	1 pc	rear bumper lower diffuser <i>11</i>	\$ 190.00
13	1 pc	rear bumper lower diffuser clips <i>11</i>	\$ 3.50
14	2 pc	rear bumper side @ \$148.50 <i>11</i>	\$ 297.00
15	2 pc	rear bumper side retainer @ \$27.50 <i>11</i>	\$ 55.00
16	1 ps	rear windshield glass weaterstrip <i>nu</i>	\$ 138.60
			\$ 3,594.80
		Less 20 %	\$ 718.96
			\$ 2,875.84
		<u>SPECIAL NETT ITEMS</u>	
17	1 pc	rear bumper parking sensor <i>suc</i>	\$ 450.00
18	1 pc	rear windsheild glass sealant <i>nu</i>	\$ 150.00
19	1 pc	rear windshield glass sponge seal <i>nu</i>	\$ 100.00
			\$ 700.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		To rust-proofing of the affected areas.	\$ 150.00
05		To remove and refit rear windscreen glass.	\$ 160.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : YN8948T

Date of Accident : 21 April 2018

no

Miss Lim Bee Hiang

Date : 23 April 2018

Estimate To Repair SGX7125T - Honda VEZEL 1.5X CVT
Chassis No : RU11114319

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,350.00
		Total	\$ 5,925.84

400

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To do (larger part) during resurvey
- Putty prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M00EXT

Reference

None 

Loss Date

April 21, 2018

Request Date

April 24, 2018

LKK AUTO CONSULTANTS PTE LTD (TP) ▼

Due Date

April 24, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▼

Vehicle Information

Incident Vehicle Registration #

SGX7125T

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

GIM SIONG FOODS SUPPLY

15 JALAN TEPONG, #06-13 JURONG FOOD HUB, 619336, Singapore

98367506

MOTOR@TONGHIN.COM.SG

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

 Re:RE: FOR QUANTUM MANDATE-IA UPLOADED

Type

 Question

Message

Hi LKK, please proceed as per the mandate except for LOU, please offer \$50/- per day. Thank you.

[Reply](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 7/9/2018

Survey Details:

Date of loss	21-Apr-18
Date of appointment	24-Apr-18
Date of survey	15-May-18
Location of survey	TAN LIM MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SGX 7125T
Make and Model	HONDA VEZEL 1496
Date of registration	23-May-16
Excess	
Market Value	\$ 74,000.00
Parf Rebate	\$ 44,587.00
Nett Loss	\$ 29,413.00

Repair details:

Initial Estimate	\$ 5,925.84
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,900.00
Check items (estimate)	
Labour	
Total	
Lump Sum(if applicable)	1900

Number of days for repair	<u>4</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

HEAD-TO-REAR- (BOLA 27) 100% ; ID FROM REAR.

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 2,033.00	GST included
Loss of use	\$ 300.00	(\$60 x 5 days)
Loss of rental		
Loss of income		
LTA search fees	\$ 7.49	
Others		
Proposed Total	\$ 2,340.49	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YN 8948T (Insd veh)	Model:	HONDA
	SGX 7125T (TP veh)		VEZEL 1.5X CVT
Date of Accident:	21/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,340.65
Final Repair Cost	:	\$	2,033.00
Loss of Use	:	\$	250.00
Rental (if any)	:	\$	5 days at \$50.00 per day
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 2,290.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	TAN LIM MOTOR PTE LTD	:	\$ 2,290.45

NUR SHAQILAH BTE ABDOL
WAHAB

11/10/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007518/Uja3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 11-10-2018



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 8948T	Veh. Inspected	SGX 7125T
Policy No.	VCB/P1806391	Coverage (\$)	0.00
Claim No.	S8M00EXT	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	24/04/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11114319	Colour	BLUE
Odometer	034651	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	DUNLOP	8 mm
L/H Front Tyre	215/60R16	DUNLOP	8 mm
R/H Rear Tyre	215/60R16	DUNLOP	8 mm
L/H Rear Tyre	215/60R16	DUNLOP	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/04/2018	Inspection Date	15/05/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGX 7125T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE LID (CONSISTENT)	DENTED / BUCKLED	953.30	953.30
1	TAILGATE LID VEZEL BADGE (CONSISTENT)	NECESSARY	45.80	45.80
1	TAILGATE LID WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	104.40	-
1	TAILGATE LID LOCK (CONSISTENT)	NOT NECESSARY	76.60	-
1	TAILGATE LID LOCK STRIKER (CONSISTENT)	NOT NECESSARY	24.70	-
2	TAILGATE LID REFLECTOR @ \$264.60 (CONSISTENT)	NOT NECESSARY	529.20	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	415.60	-
1	REAR END PANEL INNER TRIM (CONSISTENT)	NOT NECESSARY	98.00	-
1	REAR BUMPER CENTRE (CONSISTENT)	DENTED / DEFORMED	508.50	508.50
1	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	3.50	3.50
1	REAR BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	151.10	-
1	REAR BUMPER LOWER DIFFUSER (CONSISTENT)	NOT NECESSARY	190.00	-
1	REAR BUMPER LOWER DIFFUSER CLIPS (CONSISTENT)	NOT NECESSARY	3.50	-
2	REAR BUMPER SIDE @ \$148.50 (CONSISTENT)	NOT NECESSARY	297.00	-
2	REAR BUMPER SIDE RETAINER @ \$27.50 (CONSISTENT)	NOT NECESSARY	55.00	-
1	REAR WINDSHIELD GLASS WEATHERSTRIP (CONSISTENT)	NECESSARY	138.60	138.60
	LESS 20% DISCOUNT		-718.96	-329.94
			2,875.84	1,319.76
<u>SPECIAL NETT ITEMS</u>				
1	REAR PARKING SENSOR (SN) (CONSISTENT)	SERVICEABLE	450.00	-
1	REAR WINDSHIELD GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	150.00	40.00
1	REAR WINDSHIELD GLASS SPONGE SEAL (SN) (CONSISTENT)	NECESSARY	100.00	30.00
			700.00	70.00
<u>LABOUR</u>				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	60.00

Report Ref No. CC4/ASM18007518/Uja3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATER SEEPAGE TEST.		120.00	60.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		150.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		160.00	120.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		750.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		900.00	400.00
			2,350.00	1,020.00
GRAND TOTAL			5,925.84	2,409.76

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00
--	--	--	--	----------

Report Ref No. CC4/ASM18007518/Uja3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.