



S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid <i>20/suc</i>	\$ 953.30
02	1 pc	tailgate lid vezel badge <i>nu</i>	\$ 45.80
03	1 pc	tailgate lid weatherstrip <i>11</i>	\$ 104.40
04	1 pc	tailgate lid lock <i>11</i>	\$ 76.60
05	1 pc	tailgate lid lock striker <i>11</i>	\$ 24.70
06	2 pc	tailgate lid reflector @ \$264.60 <i>11</i>	\$ 529.20
07	1 pc	rear end panel <i>h</i>	\$ 415.60
08	1 pc	rear end panel inner trim <i>11</i>	\$ 98.00
09	1 pc	rear bumper centre <i>20/22</i>	\$ 508.50
10	1 pc	rear bumper clips <i>nu</i>	\$ 3.50
11	1 pc	rear bumper reflector <i>11</i>	\$ 151.10
12	1 pc	rear bumper lower diffuser <i>11</i>	\$ 190.00
13	1 pc	rear bumper lower diffuser clips <i>11</i>	\$ 3.50
14	2 pc	rear bumper side @ \$148.50 <i>11</i>	\$ 297.00
15	2 pc	rear bumper side retainer @ \$27.50 <i>11</i>	\$ 55.00
16	1 ps	rear windshield glass weaterstrip <i>nu</i>	\$ 138.60
			\$ 3,594.80
		Less 20 %	\$ 718.96
			\$ 2,875.84
		<u>SPECIAL NETT ITEMS</u>	
17	1 pc	rear bumper parking sensor <i>suc</i>	\$ 450.00
18	1 pc	rear windsheild glass sealant <i>nu</i>	\$ 150.00
19	1 pc	rear windshield glass sponge seal <i>nu</i>	\$ 100.00
			\$ 700.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
04		To rust-proofing of the affected areas.	\$ 150.00
05		To remove and refit rear windscreen glass.	\$ 160.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AXA Insured's Veh No : YN8948T
Date of Accident : 21 April 2018

no 4

Miss Lim Bee Hiang

Date : 23 April 2018

Estimate To Repair SGX7125T - Honda VEZEL 1.5X CVT
Chassis No : RU11114319

S/No	Quantity	Description	Amount
07		<u>LABOUR & MISC. CHARGES</u>	
		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,350.00
		Total	\$ 5,925.84

400

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To disclose (damaged parts) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: