## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SH 9120K

MAKE

PINCO ATAMOSIAGINALIVILLE

DATE 4/21/2018 9:00

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	Rear Bumper			
	Rear Bumper Reinforcement Bracket .			
	Rear Bumper Reinforcement 2			
	Rear Bumper Reverse Sensor			
	Rear Bumper Clip			
	Rear Bumper Sponge			
	Rear Bumper Under Cover			
	Rear Bumper Garnish —			
	SUB TOTAL			
	LESS 20%			
	DISCOUNTED TOTAL			
	Labour Chargo			200
	Labour Charge			\$ 250.00
	Panel Beating			\$ 250.00
	Spray Painting Charge			
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 120,00
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			
	Kaln ((1K)  23/4/8 1205L			
	Ca is t			
	1/ -2/8/12056	L L K K Au	to Consultants hence	e notify
	11/1/1/1/1/	the Rec	COLEGE OF THE PRINCIPLE	9+
	2 /			
NA	2 1071	<ul> <li>To disp</li> </ul>	lay damaged parits conf	irr ation
IN NO	01-	• Parts p	prices are subject to confinantly survey is on a "With	out Prejudice" basis
	P/P			
	21 0 11	• Supril	gal modification(s) is dis- ementary item(s) must b	e resurveyed and
	2 Ry. P/P Before P-4, 4.	is sub	ementary item(s) must b ject to final approval from	n maurance outriperty
		1	vledged by Repairer	
		Signati	uio.	
		Date:		
	This is an initial estimate based on a visual inspection of the prepared after the vehicle is surveyed by a motor Surveyed.			