

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019080
Lim Kian Hock

Page 1 of 2
Your ref. TP-SGH 4134X AXA
Job No. 69422
Our ref. 18.04.27
Payment
Date 19/4/2018

Attn

Vehicle No SKQ 2894D
Vehicle Model : Honda Jazz
Accident on ... 19/4/2018

*Not Authorized
1-B.1
Returning B4 paint
6 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate	898.30	20.00	<i>R2</i> 718.64 ✓
1.00	Pc	Rear Jazz emblem	32.90	20.00	<i>R2</i> 26.32 ✓
1.00	Pc	Rear bumper	774.90	20.00	<i>R2</i> 619.92 ✓
1.00	Pc	Rear bumper side retainer LH	20.50	20.00	<i>D11</i> 16.40 ✓
1.00	Pc	Rear bumper side retainer RH	20.50	20.00	<i>D11</i> 16.40 ✓
1.00	Pc	Rear windscreen moulding	26.30	20.00	<i>R2</i> 21.04 ✓
1.00	Pc	Rear end panel	391.80	20.00	<i>R2</i> 313.44 ✓
1.00	Pc	Rear tailgate lock	121.60	20.00	<i>R2</i> 97.28 ✓
1.00	Pc	Rear tail lamp LH	388.70	20.00	310.96 ✓
1.00	Pc	Rear tail lamp RH	388.70	20.00	310.96 ✓
1.00	Pc	Rear end panel top garnish	<i>mg D11</i> 101.60	20.00	81.28 ✓
1.00	Pc	Rear luggage tool tray	183.40	20.00	<i>R2</i> 146.72 ✓
1.00	Pc	Rear tailgate garnish	230.80	20.00	184.64 ✓
1.00	Pc	Rear tailgate weatherstrip	102.30	20.00	<i>R2/R2</i> 81.84 ✓
Special nett item:					
1.00	Set	Rear reversing sensr with installation (4 pcs)	280.00		<i>R2</i> 280.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental items must be resurveyed and is subject to final approval from Insurance Company

Noted by Repairer
Signature: _____
Date: _____

本公司拥有最先进的 CAROLINER MARK IV 机械, 可处理各种类型的车身及给予快速与准确的测量方式和大铁修理, 除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles"

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No: EST0019080
Lim Kian Hock

Page: 2 of 2
Your ref.: TP-SGH 4134X AXA
Job No.: 69422
Our ref.: 18.04.27
Payment
Date: 19/4/2018

Attn

Vehicle No: SKQ 2894D
Vehicle Model : Honda Jazz
Accident on ...: 19/4/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		Labour & Misc.			1200
1.00		To remove and refix rear windscreen	140.00		140.00
1.00		To supply sealant	40.00		40.00 ✓
1.00		To transfer rear tailgate top spoiler	50.00		50.00 ✓
1.00		To transfer rear camera	50.00		50.00 ✓
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel and renew of parts	1,000.00		1,000.00 8000
1.00		To spray paint	700.00		700.00 8400

Sub-Total 5,205.84
GST 7.00% 364.41
Total S\$ 5,570.25

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."