

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1158Y

DATE 23/4/2018 9:59

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid 'H' Emblem ✕			\$ 27.20	
	Boot Lid CRDI Plate ✕			\$ 41.00	
	Bootlid Moulding ✓			\$ 85.00	
	Bootlid i40 Emblem ✕			\$ 41.00	
	Bootlid Lower Garnish ✕			\$ 398.00	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	SUB TOTAL			\$ 2,548.55	
	LESS 20%			\$ 509.71	
	DISCOUNTED TOTAL			\$ 2,038.84	
	Boot Lid Comfort Logo & Tel No. Sticker ✕			\$ 30.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
				\$ 165.70	
	Labour Charge				
	Panel Beating			\$ 250.00	200
	Spray Painting Charge			\$ 500.00	200
	Wiring Charge			\$ 50.00	✕
	Tuff Kote			\$ 50.00	✕
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 970.00	
	ESTIMATE TOTAL			\$ 3,174.54	
<i>Kahin (11/11/14)</i> <i>23/4/18 1230</i> <i>2 Days</i> <i>P CP</i> <i>Before Part 1/14</i> <i>the Repairer of the following:</i> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					