

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 3609U

DATE 23/4/2018 9:56

MAKE :

DOA: 21.04.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Fender (LH) X Repair			\$ 2,020.10	
	Rear Fender Inner Lining (LH) X			\$ 164.40	
	Rear Windscreen Moulding X			\$ 60.00	
	Rear Door (LH) /			\$ 1,351.10	
	Rocker Panel Outer Garnish (LH) /			\$ 483.60	
	Rear Wheel Hup-Cap (LH) /			\$ 150.70	

Larry Ng

Kahr 10/10/18

23/4/18 1345h

3 days

PIP Peter P. H.