



SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB166R
Ref. No : BUS/04/18/1016
Reg. Date : 16/04/2018
Vehicle Type : BUS -12M
Make : MB CITARO MERCEDES
Model : MB CITARO O530
Name of Driver : Mohamad Helmi Bin Azar
Type of Accident : SIDE SWIPE
Date / Time of Accident : 15/04/2018 12:05:00 PM
Accident Reported Date / Time : 16/04/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : AIG
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB166R - LEFT CENTRE PORTION
SLF3308U (TP) - INSURED WITH AIG
Prepared Date : 16/04/2018 12:12:59 PM



Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labout Charges	1,325.00	0.00
Total Spray Painting Charges	616.00	0.00
Total Material Charges	285.05	285.05
Other Charges	0.00	0.00
TOTAL	2,226.05	0.00
Lum Sum Total	2,250.00	0.00
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		2 days - Lumpsum
Arc / Surveyor Sing Off Date	20/04/2018 09:40:14 AM	01/01/1900 12:00:00 AM

[Handwritten signature]

[Handwritten signature]
20/04/18 @ 1140

Prepared / Adjusted Date :
Remarks :

Prepared Date : 20/04/2018 09:40:14 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	0.00
Total Labour	1,325.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00
Total Spray Painting & Panel Beating	616.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
0005446911	VE	6010012	SIDE MARKER LAMP	1	94.50	10.00	85.05	Replace	Replace MS	No
	COMMO N	4005299	SMRT STICKER(B)	1	200.00	0.00	200.00	Replace	Replace PC	No
TOTAL MATERIALS							285.05	285.05		
TOTAL MATERIALS(Discounted)							285.05	285.05		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									