

ASS. REC. BY:

REF: CS/mstg18007533 / Rlnbnz

Special Instruction:

Surveyor:
Mehmen

Ravi

ASSIGNMENT (Office)

From (Person):

Flewer Foo

of

mstg

Date/Time:

23/04/2018 5:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKJ 5734A

Insured:

SKQ 3759E

at Workshop m/s

Perfurmana

Tel:

63190174

of

303 Alexandra Rd

Policy No:

28635558SMA

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 15/04/018

CA / REV / REP. / REV 24 HRS wpc

08052018

H.O.D. Endorsement:

Date/Time:

24/04/2018 10:06am

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKJ 5734A - x
	SKQ 3759E - x
	Revert thru menmen
	Confirm \$3,361.05 @ 3 days
	Red: \$2125.90, 39%

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 11 May 2018

Preliminary Advice

Insured Vehicle No	: SKQ3759E	Accident Date	: 15/04/2018
TP Vehicle No	: SKJ5734A	Assignment Date	: 23/04/2018
Make	: BMW 528I	Est. Duration of Repair	: 3.00
Date of Inspection	: 08/05/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,486.95
Revised Amount	:S\$	3,362.65
Check Items (Estimated)	:S\$	1,147.30
Total	:S\$	4,509.95

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Apr 2018		23 Apr 2018 17:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	ALICE LEOWARDY , ID: S7986589C		
Main Claimant:	LIM SIAN TONG , ID: S73459551		
Vehicle Reg. No.:	SKJ5734A	Date of Loss:	15/04/2018 10:00 - :59 [59 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28635558SMA (Comprehensive) Coverage: 25/11/2017 - 24/11/2018
Vehicle Reg. No. (Insured):	SKQ3759E	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/04/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Janice Lee (LKKAuto)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, May 18, 2018 5:39 PM
To: Rasul (LKKAuto); SUR
Subject: FINAL REPORT / SKJ5734A
Attachments: Final Report SKJ5734A.pdf

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,347.05
Total Labour & Parts : 3,361.05

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

“This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's.”

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 12:23
Date Of Accident	15/04/2018 10:00
Exact Location Of Accident	HOUSE CONDO CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ5734A
Insured/Policyholder	
Name Of Registered Owner	LIM SIAN TONG
NRIC No	S7345955I
Email Address	DENNISLIM@XINDEX.COM.SG
Mobile Phone No	(LOCAL) +65-97431972
Alternative Phone No	OFFICE-97431972

Vehicle Particulars

Manufacturer	BMW
Model	528I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1747714
Cover Note Number	

Driver

Name of Driver	LIM SIAN TONG
NRIC No	S7345955I
Date Of Birth	28/10/1973
Occupation	INDOOR
Date Of Driving Pass	10/06/1993
Driving Experience	24 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97431972
Fax Number	
Contact Number	OFFICE-97431972
EEmail Address	DENNISLIM@XINDEX.COM.SG

Address	BLK 511 BEDOK RESERVOIR RD #05-42
Postcode	479272
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR-CARPARK
Road Surface	DRY-CARPARK

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ3759E
Vehicle Make/Model/Colour	MAZDA RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ALICE
NRIC/Passport Number	
Contact Number	85339528
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 23 Apr 18
11:20 AM


Driver's Signature
(If driver is not the policyholder)
Date & Time:

GARY PUN
Performance M...
303 Alexan...
Sime Darby Perfom...
Singapore

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

23/4/18
11:30

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I went to my car and found a note on my windscreen. Stating that Ms Alice parked car beside mine accidentally gave on my right bumper. I called her mobile and we spoke on how the accident happen. She informed me that when she is driving out of the park lot, her red Mazda Accidentally gave onto my right car bumper. There are evidents of damage and we agree to do an assess of my car damage with Performance Motors Limited. We will decide upon the claims.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 23 Apr 2018
 11.30 am

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Performance Motors Limited
 303 Alexandra Road
 Singapore 119541

23/4/18
 11:30

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

23 APR 2018

Estimate No. : **b1 46688** Page No. : 1 of 1
Date Estimated : **23/04/2018**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -
Lim Sian Tong
64 Tanah Merah Kechil Avenue
#01-28

- ACCOUNT - **40000**
Cash Sales - Service
Singapore

Singapore 465531

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ5734A	D121943	19/04/2013	528ia	0

DESCRIPTION

To replace front bumper and attachment include knocking cause by the accident

VALUE

~~850 1,700.00~~

Painting front bumper

~~934 1,034.00~~

To check electrical wiring systems at the front section for proper function including pdc sensors

~~150 177.00~~

Sundries.

~~rec 80.00~~

Total Labour 1: **2,991.00**

DESCRIPTION

FRT BUMPER CARRIER
FRT BUMPER TOP IMPACT ABSORBER
FRT BUMPER BOTTOM MOUNT
FRT BUMPER TRIM PRIMED (PDC)
EMBLEM GROMMET
BMW EMBLEM
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

1 684.75

1 48.00

1 157.50

1 1,277.55

2 0.80

1 69.50

4 5.05

1 236.85

VALUE

684.75

48.00

157.50

1,277.55

1.60

69.50

20.20

236.85

Total Parts : **2,495.95**

Claim: BUMPER PDC SENSOR (SCHWARZ) Direct Settlement

Regn No. 08/05/18 @ 1145 Claim No. _____

Date & Time 08/05/18 @ 1145 Excess \$: _____

Surveyor's Tel 90010068 Authorise: Yes/No

Authorized Date _____ Title _____

RESURVEY PARTS PHOTO BY: _____ Date: _____

Surveyor's E-mail _____

Est. of Vehicle Time Required 3 days

Labour 1 : **2,991.00**

Parts : **2,495.95**

Labour 2 : **0.00**

Excess : **0.00**

Total GST @ 7% : **384.09**

Grand Total : **5,871.04**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46688
Date Estimated : 23/04/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Lim Sian Tong
Blk 511 Bedok Reservoir Road
#05-42

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 479272

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE		
SKJ5734A	D121943	19/04/2013	528iA	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dents caused by the accident				850.00		850.00
To spray paint front bumper				934.00		934.00
To check electrical wiring systems at the front section for proper function including pdc sensors				150.00		150.00
Sundries.				80.00		80.00

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
FRT BUMPER TRIM PRIMED (PDC)	1,277.55	1.00		1,277.55
BMW EMBLEM	69.50	1.00		69.50

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,347.05
Total Labour & Parts :	3,361.05
Deduction for Excess :	
Total Repair Costs less Excess:	3,361.05
GST @7%:	235.27
Grand Total :	3,596.32

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007533/R1RBN2

Date: 27/06/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28635558SMA
Claimant Vehicle No :	SKJ5734A	Insured Vehicle No :	SKQ3759E
Date of Loss:	15/04/2018	Nature of Claim:	TP
			Claim No: 556356

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ5734A	Engine No:	A1880442N20B20A
Make & Model:	BMW 528i, 2.0 (A)	Chassis No:	WBAXG32010D121943
Reg. Date:	19/04/2013 (Man. Year: 2013)	Odometer:	74741 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,575.95	1,427.05	1,148.90	44.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,911.00	1,934.00	977.00	33.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,486.95	3,361.05	2,125.90	38.74
+ GST 7.00/7.00% (S\$)	384.09	235.27	148.82	38.75
Nett Amount (S\$)	5,871.04	3,596.32	2,274.72	38.74

INSPECTION

Date of Assignment:	23/04/2018	
Date Inspected:	08/05/2018	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts: 143	BMW 528I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKJ5734A)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER CARRIER	Serviceable	684.75 FS	*- FS
2	1	*FRT BUMPER TOP IMPACT ABSORBER	Serviceable	48.00 FS	*- FS
3	1	*FRT BUMPER BOTTOM MOUNT	Serviceable	157.50 FS	*- FS
4	1	*FRT BUMPER TRIM PRIMED (PDC)	Scratched	1,277.55 FS	*1,277.55 FS
5	2	*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
6	1	*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
7	4	*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	20.20 FS	*- FS
8	1	*BUMPER PDC SENSOR (SCHWARZ)	Serviceable	236.85 FS	*- FS
9	1	*SUNDRIES	Necessary	80.00 FS	*80.00 FS
Total Parts (S\$)				2,575.95	1,427.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT	New	1,700.00	850.00
2	PAINTING FRONT BUMPER	New	1,034.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING PDC SENSORS	New	177.00	150.00
Gross Labour Cost (S\$)			2,911.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >