

ASS. REC. BY:

REF: CS / FCL 8007536 / Klrbnz Special Instruction:

SUMMITOR: Kahip ASSIGNMENT (Office)From (Person): CWS Joanne Yong of FCL Date/Time: 24042018 1254pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 8854UInsured: SHD 6977Bat Workshop m/s: PremierTel: 6544 6671of 23 Changi South Ave 2 #03-02Policy No: _____ Claim No: D18003173MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24042018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 24042018 126pmPerson Contacted: GrayVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 8854U - x
	SHD 6977B - x
	Revert from email

(08/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 88544 Yr Regn: 17 Feb, 24Type: M.Car / M.Cycle / Bus / Van / Lorry / T~~ab~~ / Prime Mover /

Truck / Trailer or

Make: Kia optima c.c. 1600Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 572449 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 1CNAHM 414ME 545 8149

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 20/4/8 D.O.I. 24/4/8Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rly

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/5/08	Continue 2 L/S \$1000 / 2 Rpt.
	RD: 8 691, 411.

RECEIVED 10 MAY 2013

Date/Time, File Pass to?

☐ : Prell. Report1) typst☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

100

50

50

29

229

Report Format: TPLump Sum / T.B.I.: (\$ 1000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18007536/K1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6977B	Veh. Inspected	SHD 8854U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003173MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/04/2018	Inspection Date	24/04/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003173MFSH

Our Ref: CS/FCI18007536/K1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8854U .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24.04.2018 at the premises of M/s PREMIER AUTOMOBILE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,691.00</u> .
Revised Estimate Amount	: S\$ <u>1,251.00</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at o/s body.



Yours faithfully
KALVIN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-04-2018	Our Ref No. D18003173MFSH
Accident Date	21-04-2018	Claim Type. Third Party
Insured Vehicle	SHD6977B	Third Party Vehicle. SHD8854U
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GOH WEE DEK	
Contact No.	62148880/ 65446682	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	17 Feb 2014 / 10:08:00	Receipt No.:	AACCK001-AX239-140217-000014
Asset Type:	Vehicle	Transaction Amount:	\$70,862.00
Asset ID:	SHB8854U	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140217100800500487		

Vehicle No.:	SHB8854U
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-

Vehicle Scheme:	Taxi (Company)
-----------------	----------------

First Registration Date:	17 Feb 2014
--------------------------	-------------

Original Registration Date:	17 Feb 2014
-----------------------------	-------------

Vehicle Make:	KIA
---------------	-----

Vehicle Model:	OPTIMA 1.7(A) DIESEL
----------------	----------------------

Chassis No.:	KNAGM414ME5454149
--------------	-------------------

Engine No.:	D4FDDH308901
-------------	--------------

Motor No.:	-
------------	---

Trailer Chassis No.:	-
----------------------	---

Propellant:	Diesel
-------------	--------

Passenger Capacity:	4
---------------------	---

Engine Capacity:	1685
------------------	------

Power Rating:	-
---------------	---

Unladen Weight:	1584
-----------------	------

Maximum Laden Weight:	2050
-----------------------	------

Primary Color:	Silver
----------------	--------

Secondary Color:	-
------------------	---

Manufacturing Year:	2013
---------------------	------

Open Market Value:	\$19,632.00
--------------------	-------------

Minimum PARF Benefit:	\$7,279.00
-----------------------	------------

PARF Eligibility:	Y
-------------------	---

No. of Transfer:	0
------------------	---

Effective Ownership Date/Time:	17 Feb 2014 10:08:00
--------------------------------	----------------------

COE No.:	2014021701000840R
----------	-------------------

COE Expiry Date:	16 Feb 2022
------------------	-------------

COE Bid Category:	-
-------------------	---

Actual QP/PQP Paid Amount:	\$58,590.00
----------------------------	-------------

Lifespan Expiry Date:	16 Feb 2022
-----------------------	-------------

Owner ID Type:	Company
----------------	---------

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8854 U

1 pc	O/s mirror Assy		\$	590.00
		Less 10%	\$	59.00
			\$	531.00
<u>S/nett</u>				
1 pc	Rear o/s fender sticker		\$	60.00
1 pc	Front o/s fender sticker		\$	30.00
	Towing fee		\$	50.00
	Sundry		\$	50.00
To labour charge for dismantle and renew the accident damaged parts. Including panel beating, knock out and repair on the rear o/s fender, front o/s fender				\$ 400.00
To putty and spray painting on rear o/s fender, front o/s fender, o/s mirror				\$ 500.00
To apply rustproofing on repair/replace panel				\$ 120.00
				<u>\$ 1,691.00</u>
				1741

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

K. L. L. L. L.
24/4/18 16:54
2 Pys.
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modifications allowed• Supplementary repair must be resurveyed and is subject to final approval from insurance Company
Acknowledged by Repairer
Signature:
Date:

CASH SALE/WORK ORDER No: AD 8225



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL: 6743 1987 (3 LINES) FAX: 6743 0013

Reg No: 200415052W

Date: 21/4/17

Premier

Messrs:

Vehicle No: SNB38254U Model No: 1C14

From: Honggang AVB 8 Bus 620

Other: Omega Acc

1/1/23/200/23/4 AMOUNT: \$

本公司對於拖之車輛，在進行中如有任何損壞或破壞，一概由車主自行負責。
Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdeemean
vehicle whilst being towed

ed by: [Signature]

Received by:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007536/K1rbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-05-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6977B	Veh. Inspected	SHB 8854U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003173MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KNAGM414ME5454149	Colour	SILVER	
Odometer	572449	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	7 mm	
L/H Front Tyre	205/65 R16	ACHILLES	7 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/04/2018	Inspection Date	24/04/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8854U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	O/S MIRROR ASSY	BROKEN	590.00	590.00
	LESS 10% DISCOUNT		-59.00	-59.00
			531.00	531.00
	SPECIAL NETT ITEMS			
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	FRONT O/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			140.00	60.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS,INCLUDING PANEL BEATING,KNOCK OUT AND REPAIR ON THE REAR O/S FENDER,FRONT O/S FENDER.		400.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR O/S FENDER,FRONT O/S FENDER,O/S MIRROR.		500.00	410.00
	TO APPLY RUSTPROOFING ON REPAIR/REPLACE PANEL.	NOT NECESSARY	120.00	-
			1,070.00	660.00
	GRAND TOTAL		1,741.00	1,251.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00

Report Ref No. CS/FCI18007536/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.