

22/03/2002

ASS. REC. BY:

REF: CS/FCL18007541/Tlr b n2 Special Instruction:

Surveyor:

Tawfik

ASSIGNMENT (Office)

From (Person):

CWS Kileen Lee

of

FCL

Date/Time:

23/04/2018 1135pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHW 8984D

Insured:

SHB 4188K

at Workshop m/s

Borneo Motor

Tel:

9847 6779

of

2 Pandan Crescent

Policy No:

Claim No:

D18002952MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

30/04/2018 @ 430pm

H.O.D. Endorsement:

Date/Time:

24/04/2018 9:10am

Person Contacted:

Francis.

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHW 8984D - X

SHB 4188K - X

Confirm

\$4270.50 @ 4 days (Red: \$2611.00, 38%.)

Signature: *Tanjun*

REF: **FA**

ASSIGNMENT

From:

Date: **30042018**

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SHW 8984D**

at Workshop m/s

**Borneo Motor
2 Pandan Crescent**

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Francis

(Policy Condition)

4.30pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHW 8984D

Yr Regn: **2017 June**

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

C.C. **1798**

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

22015

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

5TD66 20W00 500 7177

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or

Brake: **In order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I. **30/4/18 1640**

Survey held at

Borneo Motor Pandan

Des. of Damages: **Frt** / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 26 SEP 2018

Date/Time, File Pass to?

1) *typist*

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: **4**

Resurvey No. of Trip: **1**

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

: Photos

: Others

TOTAL

145

50

50

34

279

Report Format:

TP

Lump Sum / I.B.I. (\$ **4270.50**)

MOTOR SURVEY ASSIGNMENT

Date	18-04-2018	Our Ref No. D18002952MFSH
Accident Date	17-04-2018	Claim Type. Third Party
Insured Vehicle	SHB4188K	Third Party Vehicle. SGW8984D
Survey Location	INCHCAPE BODYCARE CENTRE LEVEL 4 INCHCAPE CENTRE2 PANDAN CRESCENT	
Contact Person.	FRANCIS CHER	
Contact No.	66311874/ 98476179	Fax No. 68727260
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BORNEO MOTORS (SINGAPORE) PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8187713J



Name

LEE AH LEE

Race

CHINESE

Date of birth

27-05-1981

Sex

M

Country of birth

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8187713J

Name

LEE AH LEE

Birth Date 27 May 1981

Issue Date 18 Feb 2013



002151619A



9188217

NRIC No S8187713J



Nationality

MALAYSIAN

Date of issue

25-01-2013

APT BLK 120A EDGE DALE PLAINS #05-239
SINGAPORE 821120

NRIC No: S8187713J

Date: 01/08/2016

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles $\leq$ 200 cc 14 Apr 2005
Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 14 Apr 2005

NP 428A



Licence No: S8187713J



POLICY INFORMATION		Policy No. : VPA/P1945659	
Source	:	(01) 14885	BMS-AXA TOYOTA NB
Insured	:	LEE AH LEE	
Address	:	BLK 120A EDGEDALE PLAINS #05-269 SINGAPORE 821120	
Business/Profession	:	OTHER OCCUPATION Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance : From 23/06/2017 To 22/06/2019 (Both Dates Inclusive)			
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.			
PREMIUM			
Premium After 40.00% : SGD 1,071.03			
NCD			
GST	7.00%	:	SGD 74.97
Annual Premium		:	SGD 1,146.00
Total Payable		:	SGD 2,292.00
RISK DETAILS THE MOTOR VEHICLE			
Type Of Cover	:	Comprehensive	
Regn No.	:	SGW8984D	
Type Of Use	:	Private Car	
Make/Model	:	TOYOTA WISH 1.8	
Year of Manufacture	:	2017	Seating Capacity (excl. Driver) : 07
Body Type	:	MULTI - PURPOSE VEHICLE	Engine C.C. : 1798
Engine No.	:	2ZR1965021	Chassis No. : JTDGG20W00J007177
Insured's Estimated Market Value	:	Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use : As specified in Certificate of Insurance			
Hire Purchase	:	UNITED OVERSEAS BANK LIMITED	
Basic Own Damage Excess		:	SGD 500.00
<u>Named Drivers</u>			
1 LEE AH LEE			
MEMORANDA, CLAUSES, WARRANTIES & ENDORSEMENTS			
Subject to the Memoranda, Clauses, Warranties & Endorsements attached hereto:			
Sales Agent ID : BSTU004			

Sales Draft Number One : 8061-1498533061341			
BTY			



Borneo Motors (Singapore) Pte Ltd

 Online Service Booking :
 www.toyotasingsapore.com.sg

 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631-1188

 Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Lee Ah Lee
	Document No	120A Edgedale Plains
	0	#05-269
	Document Date	Singapore 821120
	18/04/2018	Mobile: 91087740


Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP	S6	ZGE20R	23/06/2017	SGW8984D	0	30480 :5DS/SGW8984D/17041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

JTDGG20W00J007177	2ZR1965021	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	------------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : First Capital T/P VEH. : SHB4188K ACC DATE : 17.04.18 BY :			nee	50 100.00
2	B	BP-LAB DRILL HOLE TO INSTALL REVERSE				✓ 169.50
3	B	BP-LAB SENSOR. CHK REAR WIRING SYSTEM AND CONDUCT				✓ 169.50
4	Z	BP-SLANT WATER TEST. SUPPLY SEALANT (NETT)				✓ 100.00
5	B	BP-LAB REMOVE BOOT INTERIOR TO ASSIST				✓ 339.00
6	B	BP-LAB REPAIR. REPLACE AND REALIGN REAR BUMPER.			Repair - 1695	3080.00
7	B	CUT AND WELD TAIL-LAMP PANEL. SPRAY PAINT ON DAMAGED AFFECTED			Replace - 2712	1668.00
8	1	BP-RES PORTION OF CAR. REAR BUMPER COVER,	1.00	574.90		✓ 574.90
9	2	T52159-68907 REAR LOWER FLR PANEL,	1.00	520.00		✓ 520.00
10	3	T58307-68031 ELECTRICAL ANTENNA,	1.00	160.60		✓ 160.60
		T89997-30070				✓ 160.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	6,881.50
		Labour	1,255.50
		Materials	5,626.00
		Lubrication/Fluid	0.00
		Others	0.00
			0.00
			Amount Due
			7,363.21
			GST 7.00%
			Less
			0.00



Tanjiah 97495749 3666550

30/4/18 @ 1640 3666550

 Resurvey before paint
 swr @ lkkauto.com.
 4-6 days.


Borneo Motors

Inchcape

TO SECURITY GUARD

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES

VEHICLE NO

SGW8984D

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

CUSTOMER



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Page 2 of 2
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Attn: Taufi
Final Bill
TAX INVOICE

4 days.

Account Detail				Account No		Customer Detail	
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005/ICFIC1		Mr Lee Ah Lee 120A Edgedale Plains #05-269 Singapore 821120 Mobile: 91087740	
				Document No			
				38024353			
				Document Date			
				08/06/2018			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	HPXNP S6	ZGE20R	23/06/2017	SGW8984D	23568	30480	5DS/SGW8984D/17041:

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
JTDGG20W00J007177	2ZR1965021	60	Francis Cher T S	14/05/2018 11.28	08/06/2018 19.18	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : FIRST CAPITAL INS. T/P VEH. : SHB4188K ACC DATE : 17.04.18 BY : TAUFU (LKK)				50.00
2	B	BP-LAB DRILL HOLE TO INSTALL REVERSE	*			169.50
3	B	BP-LAB SENSOR.	*			169.50
4	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT	*			339.00
5	B	BP-LAB WATER TEST.	*			1695.00
6	B	BP-LAB REMOVE BOOT INTERIOR TO ASSIST	*			1112.00
7	1	BP-LAB REPAIR.	*			574.90
8	2	BP-LAB REPLACE AND REALIGN REAR BUMPER.	*			160.60
		CUT AND WELD TAIL-LAMP PANEL.				
		BP-RES SPRAY PAINT ON DAMAGED AFFECTED				
		PORTION OF CAR.				
		COVER RR BUMPER	1.00	574.90		574.90
		ANTENNA, ELECTRICAL	1.00	160.60		160.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	4,270.50
		Labour	298.94
		Materials	0.00
		Lubrication/Fluid	0.00
		Others	0.00
			Amount Due
			4,569.44

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

3669115

3669115

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/06/2018
TIME 19:19

VEHICLE NO SGW8984D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18007541/T1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4188K	Veh. Inspected	SGW 8984D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002952MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	23/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDGG20W00J007177	Colour	GREY	
Odometer	22015	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/04/2018	Inspection Date	30/04/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 8984D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER COVER (SN)	DEFORMED	574.90	574.90
1	REAR LOWER FLR PANEL (SN)	TO REPAIR SEE LABOUR	520.00	-
1	ELECTRICAL ANTENNA (SN)	CRACKED	160.60	160.60
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NOT NECESSARY	100.00	-
			1,455.50	785.50
	<u>LABOUR</u>			
	DRILL HOLE TO INSTALL REVERSE SENSOR.		169.50	169.50
	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.		169.50	169.50
	REMOVE BOOT INTERIOR TO ASSIST REPAIR.		339.00	339.00
	REPLACE AND REALIGN REAR BUMPER, CUT AND WELD TAIL-LAMP PANEL. INCLUSIVE OF THE REPAIR OF REAR LOWER FLR PANEL.		3,080.00	1,695.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		1,668.00	1,112.00
			5,426.00	3,485.00
	GRAND TOTAL		6,881.50	4,270.50
RECOMMENDED COST OF REPAIRS				4,270.50

Report Ref No. CS/FCI18007541/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.