



# TTS EUROCARS pte ltd

A member of the TTS Motor Group  
383 Sin Ming Drive, TTS Centre, Singapore 575717  
Tel: 67572622 Fax: 67411626

*Not Authorized*  
*Resiny Bepaint*  
*Kennoth 98910663*

## QUOTATION

To : AXA Insurance DATE : 20/4/2018  
 Attn : Claims Officer  
 CC : \_\_\_\_\_ VEHICLE NO : SLN 1868 R  
 YEAR : 2016 CHASSIS NO : WDD2130422A111929  
 MODEL : MERCEDES BENZ E200 AVG A/T PAGE : 1 OF 1

Please quote the following items listed.

S/NO	ITEMS	Qty	Price
1	Front bumper	1	<i>Bu</i> \$2,352.00 ✓
2	Front bumper grill trim chrome	1	<i>SL</i> <del>CMA</del> \$358.00 X <i>4 up</i>
3	Front bumper side retainer - RHS	1	<i>D.I</i> \$89.00 ✓
4	Front bumper towing cap	1	<i>SL</i> \$94.00 X
5	Front bumper mounting bracket	1	\$147.00 ?
6	Front bumper support impact absorber	1	\$259.00 ?
7	Front radiator grille housing	1	<i>CMA</i> \$245.00 ✓
8	Front radiator grille trim chrome	1	<i>CMA</i> \$385.00 ✓
9	Front radiator grille star badge	1	<i>CMA</i> \$107.00 ✓
10	Front radiator grille star badge emblem	1	<i>M</i> \$199.00 ✓
11	Front number plate	1	<i>DJ</i> \$90.00 <i>455</i>
12	Front number plate garnish	1	<i>DJ</i> \$130.00 ✓
13	Front headlamp - RHS	1	<i>MJ CMA</i> \$4,254.00 ✓
14	Rear bumper	1	<i>Bu / CMA</i> \$2,639.00 ✓
15	Rear bumper bottom trim	1	\$642.00 ?
16	Rear bumper bottom moulding	1	\$476.00 ?
17	Rear bumper towing cap	1	<i>SL</i> \$37.00 X
		TOTAL :	\$12,503.00
		LESS 5%	\$625.15
		TOTAL :	\$11,877.85

S/NO	SPECIAL ITEMS	Qty	Price
1	Front bumper distance sensor \$224.00 / PC	2	\$448.00 ?
2	Front bumper decoupling ring \$12.00 / PC	2	\$24.00 ?
3	Rear bumper decoupling sensor \$12.00 / PC	2	\$24.00 ?
4	Rear bumper distance sensor \$224.00 / PC	2	\$448.00 ?
5	Rear bumper clips @ \$9.00	5	<i>M</i> \$45.00 ✓
		TOTAL :	\$989.00
		Parts Total :	\$11,877.85
		S/P Item :	\$989.00
		TOTAL :	\$12,866.85



# TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive , TTS Centre . S'pore 575717

Tel : 67572622 Fax : 67411626

## QUOTATION

To : AXA Insurance DATE : 20/4/2018  
 Attn : Claims Officer  
 CC : \_\_\_\_\_ VEHICLE NO : SLN 1868 R  
 YEAR : 2016 CHASSIS NO : WDD2130422A111929  
 MODEL : MERCEDES BENZ E200 AVG A/T PAGE : 1 OF 1

S/NO	LABOURS	AMOUNT
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. <i>c &amp; p</i>	<i>800</i> \$ 1,560.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	<i>960</i> \$ 2,280.00
3	TO REMOVE AND REFIT FRONT AND REAR REVERSE SENSOR ASSY.	<i>160</i> 200.00
4	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET, ETC, REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	<i>50</i> 150.00

Working Days : ~~6~~ Days.  
*4 days*

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$4,190.00  
 PARTS TOTAL : \$12,866.85  
 GRAND TOTAL : \$17,056.85

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: