

Signature

Tanpin

REF:

ASM(AXA)

P

ASSIGNMENT

CoE 2020 Mail

From: Date: 26042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FS 4839A

at Workshop m/s Team HK Lim

of Blk 1008 Bukit Merah Lane 3 #0-24

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

10am - 2pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$4000

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

FS 4839A

Yr Regn: 2000 / Ins.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shadow 400 C.C. 398

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 170/80 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Shinko

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 26/4/18 @ 11am

Survey held at HKL Bm.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S #500 (Reel \$440/440).

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18007553/pb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 24-04-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFZ 49C	Veh. Inspected	FS 4839A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2018	Inspection Date		
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklilmotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Website: www.hklilmotorsport.com.sg

FS4839A

- 1 REAR FENDER SPRAY (120mm)
- 2 REAR NO PLATE
- 3 REAR SIGNAL RH
- 4 REAR SIGNAL BRACKET RH
- 5 LABOUR (1.5h)

250
150
\$350.00
\$45.00 bt 40
\$120.00 CR 40
\$80.00 cut
\$350.00 150

TOTAL

\$945.00

Tarikh 97495749
WP
26/4/18 @ 11am
Resurvey after repair
2 days
Sua @ hkauto-wm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Service Request Details

Claim

S8M00EVW

Reference

None 

Loss Date

March 24, 2018

Request Date

April 23, 2018

Due Date

April 30, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

23042018 @ 345pm
James veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FS4839A

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

KEE MUI HONG

64 WEST COAST DROVE, 127867, Singapore

muihong@ahlimmotor.com.sg

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

4/23/18 2:01 PM

FROM

CHAN Kian Chuan

SUBJECT

REQ FOR OI VIDEO FOOTAGE

BODY

BASED ON OI REPORT, TP CUT INTO OIV



Hsiao Tong (LKKAuto)

From: muihong@ahlimmotor.com.sg
Sent: Friday, 27 April 2018 3:14 PM
To: Hsiao Tong (LKKAuto)
Subject: Video SFZ49C
Attachments: video 49.mov

Dear Hsiao Tong,

Pls see attached
Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170



RE: REQ FOR OI VIDEO FOOTAGE

Type

🔗 Question

Message

Hi, we have uploaded a copy of OI video in SMART CLAIM for your easy reference. The video shows that third party had stopped in front of OI's vehicle while OID continued to move and collided onto third party. We are of the opinion that liability is not in OID's favour. Kindly let us have your comments/ instruction please. Hsiao Tong - 03/05/2018

Reply



Re:RE: REQ FOR OI VIDEO FOOTAGE

Type

🔔 Question

Message

WE ARE OF THE VIEW THAT WHILE APPROACHING THE TRAFFIC LIGHT JUNCTION, OI HAD DECREASE HIS SPEED AND TP CAME FROM BEHIND AND ENCROACHED INTO OI LANE. WHILE SLOWING DOWN. UNDER NORMAL CIRCUMSTANCES NO ONE WILL EXPECT A VEHICLE TO COME FROM BEHIND. PLS PROCEED TO REJECT TP CLAIM BASED ON OI REPORT AND DAMAGES. DO NOT REVEAL OI VIDEO FOOTAGE TO TP AT THE MOMENT. THANK YOU.

Reply

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Saturday, 5 May 2018 9:50 AM
To: HKL Lim Team Motorsport
Cc: Admin A
Subject: RE: FS4839A / SFZ49C on 24/03/2018 *LKK REF: CC4/ASM18007553/T1pb3
Attachments: STATEMENT OF SFZ 49C.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Attached here with a copy of our insured accident report for your easy reference. We are of the view that your client who came from behind had encroached into our insured's lane and resulted the collision.

In view of this, we regret to inform your that we have our principal instruction to deny liability and unable to look into your client claim.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: HKL Lim Team Motorsport [mailto:hklteam@gmail.com]

Sent: Wednesday, 2 May 2018 5:56 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FS4839A / SFZ49C on 24/03/2018

Hi Hsiao Tong,

May i know the liability for this case ?

--

Thank You.

Best Regards

James Lim (Keong)

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M00EVW	
Reference	CC4IASM18007553/71pb3s2  Loss Date	
Request Date	March 24, 2018	
Due Date	May 14, 2018	
Vendor Name	April 23, 2019	
Type of Loss	LKK AUTO CONSULTANTS PTE LTD (TP)	
Services	Third Party Vehicle Damage	
Pending verification - Direct Settlement		
Additional Instructions		

Actions

Next Step

Finish the work

Complete Work

Move

Document Type

Document SubType

Upload Documents

Vehicle Information	
Incident Vehicle Registration #	FS4839A
Make	Service Address
TPVD HONDA	Model
MOTOR	Primary Contact/Insured
KEE MUI HONG	64 WEST COAST DRIVE, 127867, Singapore
mulihong@ahlimmotor.com.sg	
Claim Handler	
CHAN Kian Chuan	
6568804269	
kianchuan.chan@axa.com.sg	

Messages	Invoices	History	Documents
Assessment	Metrics	Notes	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 2, 2018

<< Service Request Details

Claim

S8M00EYVW

Reference

CC4/ASM18007553/T1p63s2  Loss Date

Request Date

March 24, 2018

Due Date

May 14, 2018

Vendor Name

April 23, 2019

Type of Loss

LKK AUTO CONSULTANTS PTE LTD (TP)

Services

Third Party Vehicle Damage

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

FS4839A

Make

TPVD HONDA

Model

MOTOR

Primary Contact/Insured

KEE MUI HONG
64 WEST COAST DRIVE, 127867, Singapore
mulhong@ahlimmotor.com.sg

Service Address

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

STATUS

SHARE

CLONE

CREATED USER

VERSION DATE

ESTIMATED AMOUNT

APPROVED AMOUNT

User Portal

8/29/18 9:52 AM

500

500

Open

Share

Clone

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	FS4839A	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	08/21/2000
Mileage		Age of Vehicle	17
Driver Details			
CATEGORY	POLICY INFORMATION	FINOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	1999	Driver Name	MARK SHAUN FERNANDEZ
Make	TPVD HONDA	Date of Birth	April 27, 1994
Model	MOTOR	Age	24
Type		Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	NC34-1200584	Driving Experience	0
Engine No	NC25E-6001749	Driver License #	
Engine Capacity	398 cc		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	04/26/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	170/80R15	Rear Tyre Size	170/80R15
Front left side	SHINKO 5mm	Rear left side	SHINKO 5mm
Front right side		Rear right side	

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details				Vehicle & Driver Details				Vehicle Condition			Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE					
	1	1			REAR NO PLATE			Bent	40		10		36	Reviewing						
	2	1			REAR SIGNAL RH			Cracked	120		10		108	Reviewing						
	3	1			REAR SIGNAL BRACKET RH			Cut	80		10		72	Reviewing						

Labour

EDIT	S#	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		REAR FENDER SPRAY	250	0	0	Reviewing		
		2		LABOUR	150	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

<< **Assessment Details**

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		2	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$616.00					
Claim Amount	\$616.00					
CATEGORY	ESTIMATE	REVISED AMOUNT				
Labour	\$400.00	\$400.00				
Spare Parts	\$216.00	\$216.00				

Submit for Review

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

	1	FINAL LUMP SUM	Reviewing	500		
--	---	----------------	-----------	-----	--	--