



HKL LIM TEAM MOTORSPORT

Blk 1008 #01-24, Bukit Merah Lane 3, Singapore 159722 Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Email: support@hklimmotorsport.com.sg Website: www.hklimmotorsport.com.sg

FS4839A

- 1 REAR FENDER SPRAY
- 2 REAR NO PLATE
- 3 REAR SIGNAL RH
- 4 REAR SIGNAL BRACKET RH
- 5 LABOUR

TOTAL

250
150
\$350.00
\$45.00 ~~66~~ 40
\$120.00 ~~cm~~
\$80.00 ~~cut~~
\$350.00 150
\$945.00

Tanjik 97495749
WP
26/4/18 @ 11am.
Resurvey after repair
2 days.
sur@hkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: