

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

20-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8581 G

|               |                                                                      |    |                       |
|---------------|----------------------------------------------------------------------|----|-----------------------|
| 1 pc          | Front bumper ✓                                                       | \$ | 531.00                |
| 1 pc          | Front o/s bumper side bracket X                                      | \$ | 16.00                 |
| 1 pc          | Front bumper o/s fog lamp cover X                                    | \$ | 66.00                 |
| 1 pc          | Front bumper o/s protector X                                         | \$ | 51.00                 |
| 1 pc          | Front o/s fender ✓                                                   | \$ | 384.00                |
| 1 pc          | Front o/s fender inner shield ✓                                      | \$ | 120.00                |
| 1 pc          | Wheel cover X <del>XXXX</del>                                        | \$ | 116.00                |
|               |                                                                      | \$ | 1,284.00              |
|               | Less 10%                                                             | \$ | 128.40                |
|               |                                                                      | \$ | 1,155.60              |
| <u>S/nett</u> |                                                                      |    |                       |
| 1 set         | Front bumper clips ✓                                                 | \$ | 48.00                 |
| 1 set         | Front o/s fender inner shield clips ✓                                | \$ | 28.00                 |
|               | Sundry                                                               | \$ | <del>50.00</del> 20   |
|               | To check wheel alignment                                             | \$ | <del>80.00</del> X    |
|               | To labour charge for dismantle and renew the accident damaged parts. | \$ | <del>550.00</del> 400 |
|               | To putty and spray painting on front bumper, front o/s fender        | \$ | <del>400.00</del> 360 |
|               | To apply rustproofing on repair/replace panel                        | \$ | <del>120.00</del> 20  |
|               |                                                                      | \$ | 2,431.60              |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer