

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Apr-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1644 U

1 pc	Front windscreen ✓	\$	923.10
1 pc	Front windscreen moulding ✓	\$	87.00
1 pc	Bonnet ✓	\$	1,052.00
1 pc	Bonnet lock ✓	\$	54.10
1 pc	Bonnet lock cover ?	\$	6.40
2 pcs	Bonnet hinge @ \$47.10 ✓	\$	94.20
1 pc	Bonnet insulator ?	\$	180.70
1 pc	Bonnet rubber weatherstrip ?	\$	37.60
1 pc	Support panel ✓	\$	611.70
1 pc	Grille ✓	\$	80.90
1 pc	Grille emblem ✓	\$	17.60
1 pc	Grille chrome ✓	\$	150.00
2 pcs	O/s & n/s head lamps @ \$585.60 ✓	\$	1,171.20
2 pcs	Front n/s & o/s fender @ \$396.70 n/s ✓ o/s x 144-2	\$	793.40
2 pcs	Front n/s & o/s fender inner shield @ \$53.30 ?	\$	106.60
1 pc	Front bumper ✓	\$	428.60
1 pc	Front bumper inner sponge ?	\$	95.70
1 pc	Front bumper reinforcement ?	\$	239.40
1 pc	Front bumper centre grille ?	\$	52.40
2 pcs	Front bumper o/s & n/s side support bracket @ \$24.40 ?	\$	48.80
2 pcs	Front bumper o/s & n/s upper side bracket @ \$14.40 ?	\$	28.80
2 pcs	Front bumper o/s & n/s brackets @ \$23.00 ?	\$	46.00
1 pc	Front bumper centre bracket ?	\$	27.50
1 pcs	Front bumper o/s & n/s sport lamp covers @ \$52.40 ?	\$	104.80
1 pc	Front bumper lip x	\$	53.10
1 pc	Air cond condenser ?	\$	976.30
1 pc	Radiator assy ?	\$	502.90
2 pcs	Radiator upper bracket @ \$17.00 ?	\$	34.00
1 pc	Radiator upper hose ?	\$	49.90
1 pc	Radiator lower hose ?	\$	32.10
1 pc	Blower Assy ?	\$	548.20
1 pc	Intercooler ?	\$	629.00
1 pc	Air duct ?	\$	91.20
1 pc	Air duct hose ?	\$	40.20
1 pc	Rear bumper ?	\$	447.00
1 pc	Rear bumper inner sponge ✓	\$	129.00

23-Apr-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1644 U

1 pc	Rear bumper beam	✓	\$	270.00
1 pc	Rear bumper tow hook cap	✓	\$	38.20
2 pcs	Rear bumper o/s & n/s stay @ \$79.00	✓	\$	158.00
1 pc	Rear bumper beam lower bracket - centre	?	\$	13.70
2 pcs	Rear bumper beam lower bracket - RH & LH @ \$16.20	?	\$	32.40
2 pcs	Rear bumper beam o/s & n/s upper bracket @ \$13.70	?	\$	27.40
2 pcs	Rear bumper o/s & n/s side bracket @ \$16.00	?	\$	32.00
2 pcs	Rear bumper o/s & n/s side upper bracket @ \$15.20	?	\$	30.40
2 pcs	Rear bumper o/s & n/s upper bracket @ \$13.30	?	\$	26.60
1 pc	Rear bumper lower cover	✓	\$	62.40
1 pc	Rear o/s tail lamp	✓	\$	477.50
1 pc	End panel	✓	\$	470.60
1 pc	End panel top garnish	✓	\$	55.60
1 pc	Rear floorboard panel	✓	\$	607.50
1 pc	Rear o/s side panel	✓	\$	168.40
1 pc	Rear o/s luggage tray	✗	\$	158.00
1 pc	Rear o/s inner trim	✗ ?	\$	153.70
1 pc	Rear luggage tray top covering	?	\$	298.50
1 pc	Rear luggage tray centre	?	\$	120.50
1 pc	Tail gate	✓	\$	1,667.40
1 pc	Tail gate glass moulding	✓	\$	48.80
1 pc	Tail gate emblem	✓	\$	31.20
1 pc	Tail gate "CRDi"	✓	\$	28.70
1 pc	Rear exhaust pipe	✗	\$	711.20
1 pc	Rear o/s fender	✓	\$	1,736.30
1 pc	Rear o/s fender inner shield	✓	\$	32.90
			\$	17,429.30
			Less 20%	\$ 3,485.86
				\$ 13,943.44

S/NETT

1 pc	Front number plate with casing	✓	\$	50.00
1 set	Bonnet insulator clips	✗	\$	45.50
1 set	Front bumper clips	✓	\$	48.00
1 set	Rear bumper clips	✓	\$	48.00
2 pcs	Front o/s & n/s fender sticker @ \$30	✓	\$	60.00
2 set	Front o/s & n/s fender inner shield clip @\$28	✗	\$	56.00
1 set	Reverse sensor	✓	\$	280.00 200
1 pc	Tailgate sticker	✓	\$	100.00
1 pc	Rear number plate with casing	✓ No casing	\$	50.00 30
1 set	Rear o/s fender inner shield clip	✓	\$	28.00

23-Apr-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1644 U

Towing Fee	\$	50.00	✓
To check wiring and focus head lamps;	\$	40.00	20
To dismantle / refit the air cond accesories to facilitate repair, including refill of air cond gas	\$	150.00	60?
To Dismantle and replace reverse sensor and test system	\$	80.00	20
To dismantle and replace the front windscreen	\$	120.00	100
To dismantle and refit the rear windscreen	\$	120.00	100
To dismantle and refit the inner component of tailgate into new shell, test water etc	\$	80.00	50
To labour charge for dismantle and renew the accident damaged parts. To cut off/heat and weld on the end panel, rear o/s fender, rear o/s side panel, floorboard panel. Including to knock-out, straighten, repair, reshape and adjust of the rear o/s chassis member	\$	2,500.00	1600
To putty and spray painting on the bonnet, front bumper, front o/s & n/s fenders, rear bumper, end panel, tailgate, rear o/s fender, floorboard panel, rear o/s chassis	\$	2,000.00	1600
To apply rustproofing on the repaired and replaced panels	\$	300.00	100
Total	\$	20,148.94	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kate 11/11/17

✓ 23/4/18 1620hr.

12 Days

4/5

After Repair photo

CASH SALE/WORK ORDER No:AD4015



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 21.4.18

寶號

Messrs:

Premier

車號

Vehicle No:

SHD16444

車型

Model No:

i30(m)

由

From:

Steven Rd Caltex

到

To:

Omega

其他

Remark:

時間

Time :

04:44:05:25:05:45

AMOUNT:

\$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by: