					발
263/2602 ASS, REC, BY:	REF	cs/msh18	5007558/AVb	02 Special Instruction:	
Surveyor	Adrica	ASSIGNM	ENT (Office)		
M√imman From (Person);	Irene Tan	of	melly	Date/Time: 240	42018 334pm
Estimated Cost:			Bill to:		
OD (T) / WS / To Inspect Vehic	TP RES / OD RES / EV	JAMINVIMVI JAGULA	CS	Insured: SW 4	192H
	ma sol			Tel: 6744 4165	11
of	13 Kula I	Bulet Are L	4 # 02-13B		
ALTON CONTRACTOR OF THE PARTY O	MSD/VPCP/18-		Claim No:		
Sum Insured:	2/1/01/13		Excess:		
Make of Veh:				D.O.A. 22047	UI&
(Client's Record)			25042018	H.O.D. Endorsemen	
	REP. / REV 24 HRS 24042618 355pm		t Hong	Vehicle IN OUT	
Date/Γime	Action/Instruction (3
	SUI 9448E - X		1.5		
	SLU 4992H -x	•			
26/4/18	la Cumal Ivana	manding	ackchon as	it by marimen	A
28/6/18	Adrian confirm	Transfer of	3000 (Re	el 8507.30, 549)
28/9/18	0	rised via	merimen		

Weekend (\$

210

7200/2

Lump Sum / I.B.I: (\$

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date: 29 Jun 2018

Preliminary Advice

Insured Vehicle No

: SLU4992H

: SLU9448E

Accident Date

: 22/04/2018

Make

: NISSAN TEANA

Assignment Date

Date of Inspection: 25/04/2018

TP Vehicle No

: 24/04/2018

Inspection At

Est. Duration of Repair : 9

: MG SOLUTION PTE LTD (HQ)

23 KAKI BUKIT AVENUE 4 #02-03B, VICOM INSPECTION CENTRE

SINGAPORE 415933

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,707.32
Revised Amount (est)	:S\$	7,200.00 (lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,200.00

:S\$

Total Loss Consideration

Lump Sum Repair

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

No results.

...CLAIM SUBFOLDER...(New Assignment)

24 Apr 2018 15:34 Assign Reference Claim Details Documents			
Reference Claim Details Documents			
La competenda Documento	Show All		
R DETAILS [Created by insurer]			
BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H			
SUBRAMANIAM VENKATRAMAN, ID: S7662070I			
	22/04/2018 13:00 - :59 [100 Months and 3 Days From LTA Reg Date (Man Yr)]		
TP Policy/Cover Note No.: MSD/VPCP/18-000001 Coverage: 01/01/2018 - 31/12/2018	verage: 01/01/2018 -		
ured): SLU4992H Policy No. (Claimant):			
Excess: S\$2,000.00			
MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Tel: 91886931	i Bukit -		
MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Irene Tan Gel 6594 2541]	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Irene Tan Gek Ing - 6594 2541]		
LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Imm.Advice due 25/04/2018]			
Adj Asg. Remarks: REQUEST TO ASSIGN ADRIAN LING WAI PING			
RECEIVED View All Compose Ca	ise Mail		
this case.			
TASKS View All Search Tasks Create New Task			

View Sent Message

This mail is associated with:

*SLU9448E (556452) [SLU4992H]

TP
SUBRAMANIAM VENKATRAMAN
Apr 22 2018 1:00PM
[BLUECAR EAST ASIA PTE LTD]
MG Solution Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 26/04/2018 09:23 AM.

To MSI_ITAN

Subject TP SURVEY SLU 9448E

Dear Irene,

Please be informed that we have inspected the vehicle SLU 9448E on 25/4/2018.

We are pending estimate from repairer.

Best Regards, Veron Chen

DOCUMENTS SUMMARY

There are no documents.

SGC.ARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

- · Electrician lobang?
- PAP New Cabinet 2015! Reshuffle 2017/2018
- 2017 Hyundai i30

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! Popular 320 Sporty! Cheaper Than Normal Sedan Car!



No Repairs Needed For Sure! No Gimmicks: View To Believe For

Direct Owner Star Ac



Browse by Category

Post an Ad

Advertiser Login

*

Ways of Selling

« Back (1 2) Next »

Sort by Date Posted Advanced Search

▼ 20 results/page

28 vehicles

Teana

Model

Price Depreciation

Reg Trate

Eng Cap

Mileage

Veh Type Arty

Available

Search Selection

Teana

2009

2,496 cc

112,485 km

Available

Nissan Teana 2.5A

\$26,800

\$10,010 /yr

23-Jul-2009

Luxury

Appearance Of The Atmosphere, Beautiful! Only \$2,680 Down Payment. Up To 90% Flexible Loan.Look No Further! We Provide Lowest Interest Rate In Town. Flexible Loan And High Trade In Are Available. Pack...

Classic Credit Pte Ltd

Posted: 31-Mar-2018 Taus: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan



Nissan Teana 2.5A

\$27,800

\$8,140 /yr

13-Aug-2009

2,496 cc

Luxury

Available

Up To 95% Loan Package Available. High Approval Rate, Balloon Scheme To Lessen Your Monthly Installment Burden. All Vehicles Are Inspected By Our Professional Team For Highest Quality. Extended Warran...

Avant Automobile Pte Ltd

Posted: 30-Mar-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan



Nissan Teana 2.0A

\$26,800

\$9,490 /vr

10-Oct-2009

1,997 cc

Luxury

Available

Lowest Depreciation, 1 Owner Only, Comfortable Luxury Sedan, Very Well Maintained Engine Conditions, No Repairs Needed, Road Tax Till Oct 2018, Various Loan Type Available, Buy With A Peace Of Mind Fro...

Benefit Auto Enterprise Pte Ltd

Posted: 24-Apr-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan



Nissan Teana 2.5A

\$29,988

\$8,780 /vr

15-Oct-2009

Available

2,496 cc 6k Downpayment Available, 1 Owner, Very Low Mileage, Powerful Engine, Smooth Auto Transmission, Flexible Loans With Low Interest Rates, Trade In Welcome.

Posted: 19-Mar-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan

Car Buying

Car Selling

Car Ownership

Bidded Carplates

Car Aftermarket

On The Move

Lifestyle

Luxury



Nissan Teana 2.0A

\$31,800

\$12,970 /vr

N.A

19-Oct-2009

1,997 cc

121,945 km

Available

Very Well Maintained By Owner And Good Condition, Only \$3,180 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate, Flexible Loan And High Trade In Are Available. Package With Unriva...

Classic Credit Pte Ltd

Posted: 19-Mar-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan



Nissan Teana 2.5A

05-Dec-2009

2,496 cc

125,000 km

Luxury

Available

Only \$7K Plus Depreciation! Lowest Priced Nissan Teana 2.5A, High OMV, High Paper Value, 2 Owner, New Road Tax, All Wears And Tears Replaced. Car Is In Brand New Conditions. Price Negotiable. No Consi...

Posted: 16-Apr-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan



Nissan Teana 2.5A

\$37,800 \$12,720 /yr 12-Dec-2009 2.496 cc

Luxury

Available

Feel The Power And Comfort From A V6 Engine. Only \$3,780 Down Payment. Up To 90% Flexible Loan, We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaled W...

Classic Credit Pte Ltd.

Posted: 26-Feb-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan

Used Teana Car & Used Cars & Vehicles Singapore - sgCarMart

6

Nissan Teana 2.5A

\$32,700

\$8,970 /yr

31-Dec-2009

2,496 cc

Luxury

Available

Road Tax Till June2018, Good Driving Conditions Luxury Sedan For Your Family, Well Maintained And Regular Serviced, No Further Repairs Needed, We Deliver Our Promise! Beautiful Paintwork With Clean An...

Posted: 24-Apr-2018 Tags: 2009 Nissan Teana, Nissan Teana, Nissan, Teana, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Rog Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

« Back (12) Next »

20 ▼ results/page

Home New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are pienty of cars for sale, from vans, trucks, sedan cars, kixury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars. & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Teana Singapore, used Teana Singapore, used Teana Singapore are even buy used Teana Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for yob openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement
©2004-2018 sgCarMart. All rights reserved.

Compare

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	20701
Vehicle No.:	SLU9448E
Vehicle to be Exported:	Yes
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	VQ25390611A
Chassis No.:	JN1BBUJ32Z0000821
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$29,103.00
Original Registration Date:	19 Dec 2009
First Registration Date:	19 Dec 2009
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$29,103.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2019
PARF Rebate Amount: Intended COE Rebate Details	\$16,006.00
COE Expiry Date:	18 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,003.00
COE Rebate Amount:	\$3,127.00
Total Rebate Amount:	\$19,133.00

The information contained herein is correct as at 25 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

or government of government of the training	ACCIDENT STATEMENT
Date Of Report	23/04/2018 16:47
Date Of Accident	22/04/2018 13:10
Exact Location Of Accident	DRIVEWAY OF BLK 185 BEDOK NORTH ROAD
Country/State of Loss	SINGAPORE

White the World had you'll be refet to	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLU9448E
Insured/Policyholder	
Name Of Registered Owner	SUBRAMANIAM VENKATRAMAN
NRIC No	S7662070I
Email Address	VENKATSUBU@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94892713
Alternative Phone No	OFFICE-88888888
Vehicle Particulars	

Manufacturer	NISSAN
Model	TEANA-2.5 (A)

Exact Purpor	se for which	vehicle wa	s being	used at
time of accid	ent			

Are you claiming	under your	own	insurance	policy	NO
for renair to your	vehicle?				140

to repen to your servers	
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
trains of made and occupant	

Type Of Coverage	COMPREHENSIVE

Fleet Policy	NO

Policy Number	5097777695

Cover Note Number

Driver

Name of Driver	SUBRAMANIAM VENKATRAMAN

NRIC No	\$76620701
Date Of Birth	21/05/1976
Occupation	INDOOR
Date Of Driving Pass	28/10/2015

Driving Experience	2 YEARS AND 5 MONTHS

MALE Gender

(LOCAL) +65-94892713 Mobile Number

Fax Number

OFFICE-88888888 Contact Number

VENKATSUBU@HOTMAIL.COM EMail Address

Address

BLK 180 BEDOK NORTH RD

#02-06

Postcode

460180

Was driver an employee of the Insured's Company NO If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: HARRISH RAHUL VENKATRAMAN (BOY)

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 22/04/2018 AT ABOUT 1310HRS AT ALONG DRIVEWAY OF BLK 185 BEDOK NORTH ROAD. MY VEHICLE WAS STATIONARY STOP AT THE LEFT SIDE OF THE DRIVEWAY WHILE ALIGHTING PASSENGER. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND THE GREAT IMPACT FORCED MY VEHICLE (A) TO HIT ONTO THE LEFT KERB. WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. DRIVER OF VEHICLE (B) MENTIONED THAT HER TYRE WAS PUNCTURED AND SHE LOSS CONTROL HENCE COLLIDED ONTO MY REAR PORTION OF MY VEHICLE (A), I STILL HAVE ONE PASSENGER INSIDE MY VEHICLE, (A) SLU9448E (B) SLU4992H

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLU4992H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

MEGREANT NOTICE

- Face 1990 To provide a contract to the contr
- The Form that be completed by the defended by the deposit of the discount of the property.
- 5. This may allow the areas of a graphful and acturate as norship, any wife in a representation or work of go, improved to the may allow the companies to populate pulling linearly.
- The foliation and experience of the Point by initial and companies and the provincial organization of the foliation of the companies.
- I have fall a regarding may be referred to the Delice for inspit parties.
- The report of the forwarded by the logulars of the GRA Reservative seamont Control and Dished by the Tondral number of Association of Singapore (GRA) for architecting and the control of the report will for a fee the many event of a control of the report will be a feet as the control of the seamont will be the control of the control of the seamont will be a feet as the control of
- Terms degreed of the intermediates, our largers, restrained and consequent of the consequences are an ininterport being made typically afforcate.
- ... Constitution the Personal Jose Protection Act (Poach
 - aum department, when any edge, edgive and part was they
 - My insurer, my workshop and the General Insurer as Assentian of Singapora ("G"A") may be permitted to collect, use pisclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by the or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetery Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - If the control of the state of the control of the con
 - The street carried the rate treet and promy grade or
 - (iii) terrying out and/or dealing with my instructions or responding to any enquiries by mos-
 - (N) administering my disms (including the mailing of correspondence, tratements, invaded, reports or netices to mis, which could invalve disclosure of behaving erachel data about me to bring about as (xar, of the same as well as another subministration of any materime? cooking each of any materime?
 - The product of the first of the content of the product of the specific part of the product of th
- (b) published the resemble of the later o
- To faith the first the control of the
- Control of the control of the second control of the c
- So the free property of the state of the sta
 - A Description of the property of the part of the property of the
 - In the state property recognition and conceptuary regularization favorate and a security

- 1. 4774-221, 221, 321, 327

On let a DigNations of propertie noticing a Central Year Date & Times

Name: Name: NBIC/2/N No. Licusenta

a Ferransels digitation

INETCH PLAN	THE RESERVE TO THE PARTY OF THE PARTY.		
		Bedole Hort	182
		Bedole Mont	h Road
	72/		
7777			
	Drivery !	\rightarrow	M S C
	4		
F7 12			
DESCRIBE CIRCUMSTANCES OF THE ACC	DINT	The same of the sa	
Cn 22/ort/2018 of a	Land 1310 his c	+ whong trive	way of
12k iss Ralak Nort	Recel My	othicle was st	utionery
stop at Au helt sie	le of the drive	enxy while	dighting
passenger, Sudde			
beland and the gre			
to hit outs the let			
reclined that it was			
Rece Portion of my			
vehicle. Sier of 1		and the second second second second	
Recorporation of my	La losa control Vehicle (A).	1 still have o	14 Desserver
DECLARATION DECLARATION		(B) SLU 2	48'E 1
Por cynological Section 1	i Zicherung nt andere de layeriden) Tiena	Security of The Period Name Very Service	La Girson Tar

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO

: MSIG INSURANCE

DATE

: 24/04/2018

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

VEHICLE DETAILS

YELON

VEHICLE NO

: SLU9448E

JN1BBUJ3220000821

MODEL

: NISSAN TEANA 2.5

CHASSIS NO

ACCIDENT DETAILS

DATE : 22-Apr-18

TIME : 13:10HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	T TOTAL LIST PRICE] 071/
1	BOOTLID Perted.	1	\$ 1,120.	00 \$ 1,120.0	9716
2	REAR BUMPER Distorted	1	\$ 920.		804
3	TAIL LAMP PANEL RH Buekled.	2	\$ 249.	20 \$ 498.4	249.20
4	REAR FENDER RH Buckles	1	\$ 1,398.	40 \$ -1,398.4	1282
5	REAR END PANEL Distarted	1	\$ 650.	.60 \$ 650.6	0
6	REAR END PANEL TOP GARNISH Rel	1	\$ 144.	.10 \$ 144.1	0
7	REAR FLOOR PANEL REPIS	1	\$ 1,497.	.90 \$ 1,497.9	0 4.
8	REAR FLOOR PANEL BOARD NO NO	1	\$ 647.	.90 \$ 647.9	O T.
9	REAR FLOOR PANEL TOP SPONGE COLL	1	\$ 479.	40 \$ 479.4	0) -
10	REAR FLOOR PANEL SIDE SPONGE RHOULD	2	\$ 169.	.90 \$ 339.8	65.50

A7518 332626.

TOTAL PRICE

\$ 7,696.50

LESS 30%

\$ 2,308.95

SUB TOTAL PRICE

\$ 5,387.55

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE		TOTAL LIST PRICE	
1	BOOT LID LOGO New	1	\$	53.20	\$	53.20

		_			
2 BOOT LID EMBLEM TEANA' 7	1	\$	75.10	\$	75.10
3 BOOT LID EMBLEM '250 XV' / Ker	1	\$	65.20	S	65.20
4 BOOT LID EMBLEM 'V6'	1	\$	65.20	\$	65.20
5 BOOT LID TOP LOCK Pand	1	\$	190.00	\$	190.00
6 BOOT LID LOWER LOCK rept New	1	s	50.60	S	50.60
7 BOOT LID DETECTOR NEW COULD	1	S	384.90	S	384.90 F. 58
8 BOOT LID WEATHER STRIP OF	1	\$	190.00	\$	190.00
9 BOOT LID OUTER MOULDING (LOWER) Let	1	S	211.00	\$	211.00
10 REAR BUMPER SIDE RETAINER	2	s	62.00	\$	124.00
11 REAR BUMPER SIDE CHROME MOULDING	2	\$	210.00	\$	420.00 210
12 REAR BUMPER REINFORCEMENT Bet	1	\$	455.30	\$	455.30 360.30
13 REAR BUMPER SPONGE Coulded	1	s	195.00	\$	195.00
14 TAIL LAMP RH couled	2	s	480.00	\$	960.00 480.
15 REAR FENDER INNER TRIM NH 1	2	\$	398.60	s	797.20 +
16 REAR AIR VENT HE M	2	\$	94.90	\$	189.80
17 REAR WINDSCREEN MOULDING MAL	1	\$	198.80	\$	198.80
18 REAR EXHAUST PIPE Bert	1	\$	930.00	\$	930.00 550-1

2875.90 2588.31

TOTAL PRICE

\$ 5,555.30

LESS 10%

\$ 555.53

SUB TOTAL PRICE

4,999.77

S/N	DESCRIPTION	QTY	UNI	S/NETT	TOTA	AL S/NETT	
1	REAR NUMBER PLATE Not son	1	s	50.00	s	50.00	+
2	REAR BUMPER CLIP(SET) NA	1	S	20.00	\$	20.00	-
3	BOOT LID SEALANT HE	1	\$	80.00	\$	80.00	X
4	BOOT LID OUTER MOULDING (LOWER) CLIP(SET)	1	\$	20.00	\$	20.00	-
5	TAIL LAMP CLIP Now	1	\$	20.00	\$	20.00	-
6	TAIL LAMP PANEL SEALANT	2	S	80.00	S	160.00	+
7	REAR FENDER SEALANT RH	1	\$	80.00	s	80.00	+
8	REAR FENDER INNER TRIM CLIPS(SET)	1	\$	20.00	\$	20.00	
9	REAR WINDSCREEN MOULDING SEALANT	1	\$	80.00	\$	80.00	30
10	REAR WINDSCREEN MOULDING INNER SEAL	1	\$	60.00	\$	_60.00	30
11	REAR END PANEL TOP GARNISH CLIPS	1	\$	20.00	\$	20.00	1
12	REAR END PANEL SEALANT New	1	\$	150.00	\$	150.00	-60
13	REAR FLOOR PANEL INSULATION SEAL NEW	1	s	250.00	\$	250.00	+
14	REVERSE SENSOR Purgd	1	s	220.00	\$	220.00	-20

TOTAL \$

1,230.00

OUR AND SPRAY PAINTING

A	IM DETAILS: LABOUR AND SPRAY PAINT	NG			
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	s	1,400:00	1200.	1100
2	TO SPRAY PAINT AFFECTED AREA	\$	1,400:00	(200)	1100
3	TUFF COAT	\$	250.00	40.	
4	WIRING CHECK	\$	120,00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$	180:00	60 .	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$	80,00	50	
7	REMOVE/REFIX REAR WINDSCREEN	\$	120.00	1/00	
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$	180,00	80.	
9	TRANFER BOOTLID MECHANISM	s	80.00	×	
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	280.00	х	

TOTAL

\$4,090.00

2760

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,617.32 TOTAL LABOUR COST: \$ 4.090.00 TOTAL REPAIR COST : \$ 15,707.32

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS :

RE-SURVEY

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before after spray painting
- To display damaged part(s) during resurvey
- * Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling. 1/825/04/18.

total 9094 57

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18007558/AVBN2

Date:

02/07/2018

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Ltd. Policy No:

MSD/VPCP/18-000001

Claimant

Insurer:

SLU9448E

Insured Vehicle No: SLU4992H

Vehicle No :

.....

Date of Loss:

22/04/2018

Nature of Claim: TP

Claim No: 556452

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLU9448E

Make & Model:

NISSAN TEANA, 2.5 CVT ABS D/AB HID 2WD

Engine No:

VQ25390611A

141973 km

Reg. Date:

4DR (A) 19/12/2009 (Man. Year: 2008)

Chassis No: Odometer: JN1BBUJ32Z0000821

Colour:

Blue

Engine Capacity: Market Value/New Car 2496 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/55R17

Rear Tyre Size: Rear Left Side: 215/55R17 Bridgestone 6 mm

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's 6,505,57	Difference 5,111.75	Diff % 44.00
Parts	11,617.32 0.00	0.00	0.00	44.00
Miscellaneous Items	4.090.00	2.560.00	1,530.00	37.41
Labour Paintwork Labour	0.00	0.00	0.00	07.41
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,707.32	9,065.57	6,641.75	42.28
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	15,707.32	7,200.00	8,507.32	54.16
+ GST 7.00/7.00% (S\$)	1,099.51	504.00	595.51	54.16
Nett Amount (S\$)	16,806.83	7,704.00	9,102.83	54.16

INSPECTION

Date of Assignment:

24/04/2018

Date Inspected:

25/04/2018 Inspected At:

MG Solution Pte Ltd (HQ)

23 Kaki Bukit Avenue 4 #02-03B,

VICOM Inspection Centre Singapore 415933

Estimated Period of Repair:

9.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 02 Jul 2018)

Parts:

143

NISSAN TEANA 2.5 CVT ABS D/AB HID 2WD 4DR (A) (Catalogue:Merimen Singapore

1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU9448E)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Reco	mmer	habr	Parts
Neco		lucu	alto

1					
	1	*BOOT LID	Dented	1,120.00 FL	*971.60 FL
2	1	*REAR BUMPER	Distorted	920.00 FL	*804.60 FL
3	1	*TAIL LAMP PANEL	O/s Buckled	498.40 FL	*249.20 FL
4	1	*REAR FENDER RH	Buckled	1,398.40 FL	*1,282.40 FL
5	1	*REAR END PANEL	Distorted	650.60 FL	*650.60 FL
6	1	*REAR END PANEL TOP GARNISH	Deformed	144.10 FL	*144.10 FL
7	1	*REAR FLOOR PANEL	Repair	1,497.90 FL	*-FL
В	1	*REAR FLOOR PANEL BOARD	Not Necessary	647.90 FL	*-FL
9	1	*REAR FLOOR PANEL TOP SPONGE	Cracked	479.40 FL	
10	1	*REAR FLOOR PANEL SIDE SPONGE	O/s Cracked	339.80 FL	*169.90 FL
11	1	*BOOT LID LOGO	Necessary	53.20 FN	
12	1	*BOOT LID EMBLEM TEANA	Necessary	75.10 FN	*75.10 FN
13	1	*BOOT LID EMBLEM 250XV	Necessary	65.20 FN	*65.20 FN
14	1	*BOOT LID EMBLEM V6	Necessary	65.20 FN	*65.20 FN
15	1	*BOOT LID TOP LOCK	Damaged	190.00 FN	*190.00 FN
16	1	*BOOT LID LOWER LOCK	Not Necessary	50.60 FN	*- FN
17	1	*BOOT LID DETECTOR	Cracked	384.90 FN	*58.00 FN
18	1	*BOOT LID WEATHER STRIP	Cut	190.00 FN	*190.00 FN
19	1	*BOOT LID OUTER MOULDING (LOWER)	Cut	211.00 FN	*211.00 FN
20	2	*REAR BUMPER SIDE RETAINER	Necessary	124.00 FN	*124.00 FN
	1	*REAR BUMPER SIDE CHROME MOULDING	O/s Damaged	420.00 FN	*210.00 FN
22	1	*REAR BUMPER REINFORCEMENT	Bent	455.30 FN	*360.30 FN
23	1	*REAR BUMPER SPONGE	Cracked	195.00 FN	*195.00 FN
24	1	*TAIL LAMP	O/s Cracked	960.00 FN	*480.00 FN
25	2	*REAR FENDER INNER TRIM	Not Necessary	797.20 FN	*- FN
26	2	*REAR AIR VENT	Not Necessary		*- FN
27	1	*REAR WINDSCREEN MOULDING	Necessary	198.80 FN	*198.80 FN
28	1	*REAR EXHAUST PIPE	Bent	930.00 FN	*590.10 FN
29	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	1	*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
31	1	*BOOT LID SEALANT	Not Necessary	80.00 FS	*- FS
32	1	*SET BOOT LID OUTER MOULDING (LOWER) CLIP	Necessary	20.00 FS	*20.00 FS
33	1	*TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
34	2	*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
35	1	*REAR FENDER SEALANT RH	Not Necessary		*-FS
36	1	*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	
37	1	*REAR WINDSCREEN MOULDING SEALANT	Necessary	80.00 FS	
38	1	*REAR WINDSCREEN MOULDING INNER SEAL	Necessary	60.00 FS	
		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	
39	1	*REAR END PANEL SEALANT	Necessary	150.00 FS	
40	1	*REAR FLOOR PANEL INSULATION SEAL	Not Necessary		
41 42	4	*REVERSE SENSOR	Damaged	220.00 FS	

Report was unsubmitted during this print-out.

No. Q	ty Part No. Particulars	Condition	Repairer's	Amount
		Sub Total (S\$)	14,481.80	8,237.70
		- List Item Discount on L Items 30.00/30.00% (S\$)	2,308.95	1,425.54
		- Nett Item Discount on N Items 10.00/10.00% (S\$)		306.59
		Total Parts (S\$)	11,617.32	6,505.57
-		Report was unsubmitted during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour
Recommended	Labour

Particulars	Lab.Type	Repairer's	Amount
ır Items		100 100020 2.20	
PANEL BEATING, REMOVAL AND REPLACING PARTS	New		1,100.00
TO SPRAY PAINT AFFECTED AREA	New	1,400.00	1,100.00
TUFF COAT	New	250.00	40.00
WIRING CHECK	New	120.00	30.00
REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND	New	180.00	60.00
. (1) THE THE TREE OF THE PERSON OF THE PER	New	80.00	50.00
REMOVE/REFIX REAR WINDSCREEN	New	120.00	100.00
	New	180.00	80.00
TRANFER BOOTLID MECHANISM	New	80.00	105
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	280.00	নিক
Gross Labour Cost (S\$)	4,090.00	2,560.00	
	PANEL BEATING, REMOVAL AND REPLACING PARTS TO SPRAY PAINT AFFECTED AREA TUFF COAT WIRING CHECK REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING REMOVE/REFIX REAR WINDSCREEN REMOVE/REFIX REAR EXHAUST PIPE TRANFER BOOTLID MECHANISM TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	PANEL BEATING, REMOVAL AND REPLACING PARTS TO SPRAY PAINT AFFECTED AREA New TUFF COAT New WIRING CHECK REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING REMOVE/REFIX REAR WINDSCREEN REMOVE/REFIX REAR EXHAUST PIPE New TRANFER BOOTLID MECHANISM TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	PANEL BEATING, REMOVAL AND REPLACING PARTS TO SPRAY PAINT AFFECTED AREA New 1,400.00 TUFF COAT New 250.00 WIRING CHECK New 120.00 REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING REMOVE/REFIX REAR WINDSCREEN REMOVE/REFIX REAR EXHAUST PIPE New 180.00 TRANFER BOOTLID MECHANISM New 80.00 TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC

< END OF ESTIMATES >