

ASS. REC. BY:

REF: CS/MSL18007559 / Alrb 91

Special Instruction:

CUMULATOR

Regul

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSTH

Date/Time:

24/04/2018

2:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 7937X

Insured:

YN 2880T

at Workshop m/s

Auto Wheels Motorworks

Tel:

9192 8963

of

No. 1 Bukit Batok Crescent #01-46

Policy No:

28674301MKF

Claim No:

556421

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23042018

CA / REV / REP. / REV 24 HRS wpi

25042018

H.O.D. Endorsement:

Date/Time:

24/04/2018

Person Contacted:

Louis

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJZ 7937X - CS / ALG11UJ6291 / Nvd1
	YN 2880T - X
	Permit the menmen

DCA 1/11/2011

Signature
Mamun

REF: MSLH

23207

ASSIGNMENT

From: Date: 25042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJZ 7937X

at Workshop m/s Auto Wheels

of NO. 1 Bukit Bortok Crescent #02-40

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJZ 7937X Yr Regn: 2010 DEC

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES Benz 26250CH1 cc 1796

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 261513 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2120472A366389

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/402R17

R: .

BS / SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 23/04/18

D.O.I. 25/04/18

Survey held at Auto wheels

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5
Confirm, \$ 2650, 3 days
Red: \$ 3810.59, 59%

RECEIVED 29 JUN 2018

Date/Time, File Pass to?

☐ : Prel. Report

☒ : Final Report

1) typist

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Report Format : TP

Lump Sum / LBS (\$ 2650

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		24 Apr 2018 14:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CYCLE & CARRIAGE INDUSTRIES PTE LTD, Co. Reg. No.: 196400367W								
Main Claimant:	MM LIMO, Co. Reg. No.: 533523203								
Vehicle Reg. No.:	SJZ7937X	Date of Loss:	23/04/2018 11:00 - :59 [87 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556421	Policy/Cover Note No.:	28674301MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	YN2880T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/04/2018]								
Driver/Custodian (Insured):	ARUMUGAM PASAN (), NRIC: S7005854E, Tel: +6596714853								
Adj Asg. Remarks:	PLS CONTACT DIRECT TO WORKSHOP FOR SURVEY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 27 Apr 2018

Preliminary Advice

Insured Vehicle : YN2880T
No

TP Vehicle No : SJZ7937X

Make : MERCEDES-BENZ E250

Date of : 25/04/2018
Inspection

Inspection At : AUTO WHEELS MOTORWORKS PTE LTD (HQ)
NO.1 BUKIT BATOK CRESCENT, #02-40 WCEGA PLAZA
SINGAPORE 658064

Accident Date : 23/04/2018

Assignment Date : 24/04/2018

Est. Duration of : 3.00
Repair

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,460.59
Revised Amount	:S\$	3,831.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,831.08

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	24/04/2018 12:42
Date Of Accident	23/04/2018 11:00
Exact Location Of Accident	ANG MO KIO AVE 6 TOWARDS YIO CHU KANG MRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJZ7937X
Insured/Policyholder	
Name Of Registered Owner	MM LIMO
Co Reg No	53352320J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88385744
Alternative Phone No	OFFICE-88385744
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	E250-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090836995 (CLASSIC)
Cover Note Number	
Driver	
Name of Driver	LAU GEE HONG
NRIC No	S7614228I
Date Of Birth	12/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	18/07/1997
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88385744
Fax Number	
Contact Number	OFFICE-88385744
EMail Address	NOEMAIL

Address 987B JURONG WEST ST 93
#15-573
Postcode S642967
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - RENTAL
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN2880T
Vehicle Make/Model/Colour LORRY
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



24 APR 2018


IDAC BUKIT BATOK (VAC)
 511 Bukit Batok Street 23
 Singapore 659545
 Tel: 6560 3312 Fax: 6569 0722
 Email: vacbb@singnet.com.sg

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name
 NRIC/Fin No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

just turn green light

Along Ark Ave 6, before moving off and got blocked by YND880T, from behind.

archer's particular driver id YND880T said he was

standing with the car at the time he was coming / on the way

from C2C.

DECLARATION

(We declare the foregoing particulars are true to the best of our knowledge)



24 APR 2018

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUNGE BAY (IDAC)
510 River Road, Phnom Penh
Cambodia 12150
Tel: 8555 2312 Fax: 8555 0722
Email: info@idac-cambodia.org.kh

Reporting Centre Personnel's Signature
Name:
NRIC/ID No:

AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WEEGA PLAZA

#01-40 SINGAPORE 610054

ATTN: MSIG INSURANCE

DATE: 24/4/2018
VEHICLE NO: SJZ7937X
MODEL: MERCEDES E250
YEAR: 2010
ACCIDENT DATE: 23/4/2018
TYPE OF CLAIM: TP AGAIN MSIG
CLAIM ADVISOR: LOUIS (91928963)
Email: louis@autowheels@yahoo.com

ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	REPAIR
REAR BUMPER	1	\$ 1,754.10 <i>DE -</i>
REAR BUMPER CLIPS	10	\$ 50.00 <i>one -</i>
REAR BUMPER RETAINER	2	\$ 288.60 <i>X m</i>
REAR BUMPER CENTRE CHROME MOULDING	1	\$ 201.50 <i>see -</i>
REAR BUMPER CHROME MOULDING - L&R	2	\$ 266.80 <i>see -</i>
REAR REINFORCEMENT	1	\$ 655.30 <i>X m</i>
END PANEL	1	REPAIR
REVERSE SENSOR	<i>2 pcs</i>	\$ 1,028.80 <i>see / 574.40</i>
TOTAL:		\$ 4,245.10
DISCOUNT 10%:		\$ 424.51
		<u>\$ 3,820.59</u>



AUTO WHEELS

MOTORWORKS PTE LTD

NO 15 UNIT 8/8/01 CRESCENT WEGA PLAZA

#01 RD SINGAPORE 110601

ATTN: MSIG INSURANCE

DATE: 24/4/2018
VEHICLE NO: SJZ7937X
MODEL: MERCEDES E250
YEAR: 2010
ACCIDENT DATE: 23/4/2018
TYPE OF CLAIM: TP AGAIN MSIG
CLAIM ADVISOR: LOUIS (91928963)
Email: louis@autowheels@yahoo.com

ESTIMATE

LABOUR

LABOUR FOR FACILITATE REPAIR - REAR PORTION
TO RESPRAY AFFECTED AREAS - BOOTLID
TO RESPRAY AFFECTED AREAS - REAR BUMPER
TO RESPRAY AFFECTED AREAS - END PANEL
TO CHECK AND RECONNECT ALL NECESSARY WIRING
TO REMOVE AND REFIT REAR TRIMMING FOR FACILITATE REPAIR
TO REMOVE AND REFIT REVERSE SENSOR
SUNDARIES 10
RUST PROOFING

PRICE

\$	1,200.00	200
\$	300.00	200 300
\$	300.00	250
\$	300.00	250
\$	100.00	X ^{un}
\$	150.00	X ^{un}
\$	150.00	X ^{un}
\$	60.00	60
\$	80.00	X ^{un}
TOTAL: \$	2,640.00	

TOTAL: \$ 6,460.59
7% GST: \$ 452.24
\$ 6,912.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 900/1000s
3 days
4s
25/04/18 @ 1445
Rag after repair
email: rasul@lkkauto.com

AUTO WHEELS

MOTORWORKS PTE LTD

1100 J BLUNT BAYON (11) 5111111111111111

1100 J BLUNT BAYON (11) 5111111111111111

ATTN: MSIG INSURANCE

DATE: 24/4/2018
 VEHICLE NO: SJZ7937X
 MODEL: MERCEDES E250
 YEAR: 2010
 ACCIDENT DATE: 23/4/2018
 TYPE OF CLAIM: TP AGAIN MSIG
 CLAIM ADVISOR: LOUIS (91928963)
 Email: louis@autowheels@pvhba.com

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTUD	1	REPAIR
REAR BUMPER	1	1,714.10 PA
REAR BUMPER CLIPS	10	10.00 PA
REAR BUMPER RETAINER	2	188.60 PA
REAR BUMPER CENTRE CHROME MOULDING	1	201.50 PA
REAR BUMPER CHROME MOULDING - L&R	2	266.80 PA
REAR REINFORCEMENT	1	655.30 PA
END PANEL	1	REPAIR
REVERSE SENSOR	2 2 pcs	1,028.80 PA (514.40)
	TOTAL: \$	4,245.10
	DISCOUNT 10%: \$	424.51
		3,820.59

2,786.8
 278.68
 2,508.12

PA

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018		24 Apr 2018 14:30 Edit Adj Rpt	S\$2,650.00 Edit Estimates	S\$2,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CYCLE & CARRIAGE INDUSTRIES PTE LTD , Co. Reg. No.: 196400367W								
Main Claimant:	MM LIMO , Co. Reg. No.: 53352320J								
Vehicle Reg. No.:	SJZ7937X	Date of Loss:	23/04/2018 11:00 - :59 [87 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556421	Policy/Cover Note No.:	28674301MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	YN2880T	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/05/2018]								
Driver/Custodian (Insured):	ARUMUGAM PASAN (), NRIC: S7005854E, Tel: +6596714853								
Adj Asg. Remarks:	PLS CONTACT DIRECT TO WORKSHOP FOR SURVEY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (27/06/2018): Survey report - urgent									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJZ7937X (556421)
[YN2880T]
TP
MM LIMO
Apr 23 2018 11:00AM
[CYCLE & CARRIAGE INDUSTRIES PTE LTD]
Auto Wheels Motorworks Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/04/18 14:29	Accident Statement From: SC - Reg. No: YN2880T, Claimant: CYCLE & CARRIAGE INDUSTRIES PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/04/18 18:02	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/06/18 17:28	General View		Load JPG	☒
2	28/06/18 17:28	General View		Load JPG	☒
3	28/06/18 17:28	General View		Load JPG	☒
4	28/06/18 17:28	General View		Load JPG	☒
5	28/06/18 17:28	General View		Load JPG	☒
6	28/06/18 17:28	General View		Load JPG	☒
7	28/06/18 17:28	General View		Load JPG	☒
8	28/06/18 17:28	General View		Load JPG	☒
9	28/06/18 17:28	General View		Load JPG	☒
10	28/06/18 17:28	General View		Load JPG	☒
11	28/06/18 17:28	General View		Load JPG	☒
12	28/06/18 17:28	General View		Load JPG	☒
13	28/06/18 17:28	General View		Load JPG	☒
14	28/06/18 17:28	General View		Load JPG	☒
15	28/06/18 17:28	General View		Load JPG	☒
16	28/06/18 17:28	General View		Load JPG	☒
17	28/06/18 17:28	General View		Load JPG	☒
18	28/06/18 17:28	Reinspection Photo		Load JPG	☒
19	28/06/18 17:28	Reinspection Photo		Load JPG	☒
20	28/06/18 17:28	Reinspection Photo		Load JPG	☒
21	28/06/18 17:28	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/04/18 14:29	TPD SJZ7937Z GIA REPORT.pdf		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007559/R1RBQ2

Date: 29/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28674301MKF

Claimant

Vehicle No : SJZ7937X

Insured Vehicle No : YN2880T

Date of Loss: 23/04/2018

Nature of Claim: TP

Claim No: 556421

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ7937X**

Make & Model: MERCEDES-BENZ E250, 1.8 CGI COUPE (A)

Engine No: 27186030172710

Reg. Date: 28/12/2010 (Man. Year: 2010)

Chassis No: WDD2120472A366389

Colour: Black

Odometer: 261513 km

Engine Capacity: 1796 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40Z 17

Rear Tyre Size:

235/40Z 17

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,880.59	2,508.12	1,372.47	35.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	860.00	1,720.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,460.59	3,368.12	3,092.47	47.87
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	6,460.59	2,650.00	3,810.59	58.98
+ GST 7.00/7.00% (S\$)	452.24	185.50	266.74	58.98
Nett Amount (S\$)	6,912.83	2,835.50	4,077.33	58.98

INSPECTION

Date of Assignment: 24/04/2018

Date Inspected: 25/04/2018 Inspected At:

Auto Wheels Motorworks Pte Ltd (HQ)

No.1 Bukit Batok Crescent, #02-40

WCEGA PLAZA

Singapore 658064

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2018)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI COUPE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7937X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID (NPA)	Repair	0.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	1,754.10 FL	*1,754.10 FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	2		*REAR BUMPER RETAINER	Not Necessary	288.60 FL	*- FL
5	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	201.50 FL	*201.50 FL
6	2		*REAR BUMPER CHROME MOULDING -L&R	Necessary	266.80 FL	*266.80 FL
7	1		*REAR REINFORCEMENT	Not Necessary	655.30 FL	*- FL
8	1		*END PANEL (NPA)	Repair	0.00 FL	*- FL
9	4		*REVERSE SENSOR	Not Working (2 PCS ONLY)	1,028.80 FL	*514.40 FL
10	1		*SUNDARIES	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,305.10	2,786.80
- List Item Discount on L Items 10.00/10.00% (S\$)	424.51	278.68
Total Parts (S\$)	3,880.59	2,508.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR -REAR PORTION	New	1,200.00	300.00
2	TO RESPRAY AFFECTED AREAS -BOOTLID	New	300.00	250.00
3	TO RESPRAY AFFECTED AREAS -REAR BUMPER	New	300.00	250.00
4	TO RESPRAY AFFECTED AREAS -END PANEL	New	300.00	0.00
5	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	0.00
6	TO REMOVE AND REFIT REAR TRIMING FOR FACILITATE REPAIR	New	150.00	0.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	60.00
8	RUST PROOFING	New	80.00	0.00
Gross Labour Cost (\$\$)			2,580.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >