

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBA6035G

Not Authorized
C/Lay 8?
Resurvey After Paint
5 days

Fax: 62564315

20-04-18

No.	Qty	List Items			
1	1	Front bumper	\$	547.23	✓
2	2	Front bumper side retainer	\$	220.46	X
3	1 set	Front bumper clips	\$	30.00	✓
4	1	Front bumper inner reinforcement	\$	407.20	?
5	1	Front grille	\$	408.00	?
6	2	Headlamp	\$	1,378.46	?
7	1	Front bonnet	\$	606.23	✓
8	1	Front bonnet "TOYOTA" logo	\$	74.52	✓
9	1	Front bonnet lock	\$	123.10	✓
10	1	Front support panel	\$	405.20	?
11	1	Front intercooler	\$	1,794.20	✓
12	1	Water tank	\$	98.23	?
13	1	Air con condenser	\$	899.10	✓
14	1	Radiator	\$	1,480.23	?
15	1	Radiator spare tank	\$	359.47	?
			\$	8,831.63	
		Less 25%	\$	2,207.91	
		Total :	\$	6,623.72	

Special Nett Items

16	1	Front number plate	\$	50.00	25%
		Total :	\$	50.00	

Labour

1	Labour Charges for remove/refit and replace damage part:	\$	1,000.00	5-600
2	To putty and spray Spray Paintings charges.	\$	1,000.00	450
3	To check wirings and lightings.	\$	40.00	20
4	To remove, refit A/C condenser, radiator etc., including refill A/C gas.	\$	150.00	100
5	To remove, refit front intercooler.	\$	100.00	50
6	To supply and apply anti rust treatment	\$	80.00	X
	Total :	\$	2,370.00	

Total Parts and Labour : \$ 9,043.72

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: