

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: LONPAC	DATE	: 23-Apr-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Ashes.	VEHICLE NO	: SLR3817D
ADDRESS	:	MODEL	: VOLKWAGEN SCIROCCO
TEL. NO.	:	CHASSIS NO	: WVV222132AV44619
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET	1	\$ 987.33	\$ 987.33
2	BONNET LOGO	1	\$ 83.75	\$ 83.75
3	BONNET HINGE	2	\$ 70.99	\$ 141.98
4	BONNET BOTTOM LOCK	1	\$ 212.20	\$ 212.20
5	BONNET WEATHERSTRIP	1	\$ 40.33	\$ 40.33
6	FRONT GRILLE COVER	1	\$ 200.97	\$ 200.97
7	FRONT GRILLE	2	\$ 325.20	\$ 650.40
8	FRONT BUMPER	1	\$ 1,428.31	\$ 1,428.31
9	FRONT BUMPER SIDE LAMP	2	\$ 189.90	\$ 379.80
10	FRONT BUMPER SIDE LAMP RING	2	\$ 112.10	\$ 224.20
11	FRONT BUMPER FOGLAMP	2	\$ 398.50	\$ 797.00
12	FRONT BUMPER FOGLAMP COVER	2	\$ 130.97	\$ 261.94
13	FRONT BUMPER REINFORCEMENT	1	\$ 531.70	\$ 531.70
14	FRONT BUMPER SIDE RETAINER	2	\$ 48.70	\$ 97.40

+
 +
 +
 +
 +
 ✓
 1207
 189.90
 112.10
 398.50
 130.97
 ✓

15	FRONT BUMPER LOWER GRILLE <i>at</i>	1	\$	385.62	\$	385.62	✓
16	FRONT BUMPER SPONGE <i>cracked</i>	2	\$	198.40	\$	396.80	198.40
17	FRONT BUMPER LOWER LID <i>3 new</i>	1	\$	521.20	\$	521.20	+
18	FRONT FENDER COWLING	2	\$	179.75	\$	359.50	+
19	HEADLAMP <i>Lt cracked</i>	2	\$	1,259.20	\$	2,518.40	1259.20
20	HEADLAMP TOP PANEL	2	\$	145.20	\$	290.40	+
21	FRONT SUPPORT PANEL	1	\$	1,528.80	\$	1,528.80	+
22	FRONT SUPPORT PANEL TOP GARNISH	1	\$	321.20	\$	321.20	+
23	FRONT SUPPORT PANEL LOWER GARNISH	1	\$	289.20	\$	289.20	+
24	FRONT AIR GUIDE GARNISH	2	\$	68.20	\$	136.40	+
25	FRONT AIR DUCT	1	\$	112.50	\$	112.50	+
26	AIRCON CONDENSOR	1	\$	1,210.20	\$	1,210.20	+
27	RADIATOR <i>new</i>	1	\$	1,598.60	\$	1,598.60	+
28	RADIATOR BRACKET	2	\$	49.77	\$	99.54	+
29	RADIATOR TOP GARNISH	1	\$	40.31	\$	40.31	+
30	HORN	2	\$	148.00	\$	296.00	+
31	WIPER WASHER TANK	1	\$	259.20	\$	259.20	+
32	WIPER WASHER TANK MOTOR	1	\$	212.30	\$	212.30	+
33	ENGINE TOP COVER	1	\$	347.35	\$	347.35	+
34	ENGINE UNDER COVER	1	\$	358.30	\$	358.30	+

Front Bumper Inner Bracket Cracked
189. ✓

TOTAL PRICE

\$17,319.13

LESS 0%

\$

SUB TOTAL PRICE

\$17,319.13

S/N	DESCRIPTION	QTY	UNIT	S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$	50.00	\$	50.00 ✓
2	BONNET INSULATOR CLIP (SET) <i>new</i>	1	\$	50.00	\$	50.00 +
3	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$	50.00	\$	50.00 30
4	FRONT GRILLE COVER CLIP (SET) <i>new</i>	1	\$	30.00	\$	30.00 10
5	FRONT GRILLE (UPPER) CLIP (SET) <i>3 new</i>	1	\$	30.00	\$	30.00 +
6	FRONT GRILLE (LOWER) CLIP (SET) <i>new</i>	1	\$	30.00	\$	30.00 ✓
7	FRONT FEENDER COWLING CLIPS (SET) <i>new</i>	1	\$	50.00	\$	50.00 +
8	FRONT AIR GUIDE GARNISH CLIP (SET) <i>new</i>	1	\$	50.00	\$	50.00 +
9	ENGINE UNDER COVER CLIP (SET)	1	\$	50.00	\$	50.00 +
10	COOLANT	1	\$	80.00	\$	80.00 +

TOTAL

\$470.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	300.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	250
3	TUFF COAT	\$ 550.00	x
4	WIRING AND BULB CHECK	\$ 80.00	30
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS	\$ 120.00	x
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	x
8	RESET ENGINE LIGHT ON	\$ 350.00	x
9	S.R.S RESET	\$ 350.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$4,770.00

580

ESTIMATE REPORT

TOTAL PARTS COST : \$17,789.13
TOTAL LABOUR COST : \$4,770.00
TOTAL REPAIR COST : \$22,559.13

APPROVED DETAILS

EXCESS :
NO. OF DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Limy. tel: 4270.36
L/S 24/04/18. c/s: 3-AK.
03 days.

35K