

JOYCE
FOO

CC 7/QBE1800 7568, F1j63n2

LKK:
IDAC:

INS. CASE OWNER:

Kalvin

ASSIGNMENT
DOI: 7/14/18

Date / Time: 7/14/18
Registered in Merimen: _____


Pre-assign / CCU / FTE:



Insured Vehicle No.: WC 4487A
Name of Insured: STAR READY-MIX P/L
Insured Tel No.: _____ HP: 7/14/18
Excess Sec II :\$\$ D.O.A: 7/14/18
Is driver the owner? (YES/NO) Nature of Accident:
If NO, Driver Name / Age: GOM KM KWEE
Driver Tel No.: _____ (V/L: YES/NO)

Claim No.: V1011416
Policy No.: 8-0008896-MMA R003
Make / Model: ISUZU
Place of Accident: JNM OF JAMPINESAVE 106
PABIR RIS PR 12
OI GIA REPORT: YES/NO; TP GIA REPORT: YES/NO
Insured Liability: % Final? Yes/No

SNC 69405



INSRS:
WSP:
Tel:
Liability:
RMKS:
premier



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
25/4/18 7/14/18	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup):	
15/2/18 3.50pm	Call OI: After call ltr to OI: 3/5/2018	Vic-oc #15
16-5-18	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

RECEIVED 6 JUN 2018

RECEIVED 16 MAY 2018

RECEIVED 6 JUN 2018

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by:

FINALIZATION Date/Time: Confirm with: Confirm by: Email Call

FINAL SETTLEMENT Date/Time: 4-6-18 Confirm with: GARY Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27-
Repair Cost: GST SS 2,193.50
Loss of Rental (LOR): SS 326.79 (3 days) X 108.93
Loss of Use (LOU): SS 120 (\$ 40 x 3 days)
Loss of Income (LOI): SS (\$ x days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search: SS 2.X
Medical: SS -
Disbursement: SS - (e.g. Tow/Independent)
Legal Cost: SS -
Total: SS 2,642.29 Global Sum SS: 2,640
If NO or B 28, Ass. Lia: front to rear collision /
COPY SENT 6/6/18
1) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 2,640 Name 1: PREMIER AUTOMOTIVE SERVICES PTZ LTD
Payee 2: (Strike if N.A.) SS X Name 2: X
Payee 3: (Strike if N.A.) SS X Name 3: X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD Ref : CC3/QBE18007568/K1jb3

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 24-04-2018



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC 4483A	Veh. Inspected	SHC 6990S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/04/2018	Inspection Date	23/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE. 1. #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/QBE18007568/K1jb3

Date: 24.04.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC6990S


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.04.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	<u>5,782.40</u>
Revised Estimate Amount	: S\$	<u>2,575.50</u>
"Check" Items Amount	: S\$	<u>-</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Wednesday, 25 April 2018 10:01 AM
To: Shu Pei (LKKAuto)
Cc: Joy Irene (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving WC4483A (OI : QBE - TBA) AND SHC6990S (TP : LKK REF - CC3/QBE18007568/K1jb3) on 23.04.2018 [VC011416]
Attachments: WC4483A.pdf

Our Ref. VC011416


Dear Shu Pei

Attached is OI's report for your attention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 24 April, 2018 5:51 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving WC4483A (OI : QBE - TBA) AND SHC6990S (TP : LKK REF - CC3/QBE18007568/K1jb3) on 23.04.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 6990S at M/s Premier Automotive Services Pte Ltd – Changi.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Enquire Transaction History

Transaction History Details

Log Date/Time:	04 Dec 2015 / 09:03:53	Receipt No.:	AACCK001-AX239-151204-000006
Asset Type:	Vehicle	Transaction Amount:	\$68,285.00
Asset ID:	SHC6990S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151204090353209073		
Vehicle No.:	SHC6990S		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	04 Dec 2015		
Original Registration Date:	04 Dec 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5657643		
Engine No.:	D4DFDH314472		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$21,913.00		
Minimum PARF Benefit:	\$13,607.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	04 Dec 2015 09:03:53		
COE No.:	2015120401003352E		
COE Expiry Date:	03 Dec 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,466.00		
Lifespan Expiry Date:	03 Dec 2023		

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893 **Cover** : Third Party
1. Index mark and Registration Number of Vehicle : **SHC6990S**
Chassis Number : KNAGM414MF5657643
2. Name of Policyholder : PREMIER TAXIS PTE. LTD.
3. Effective Date of Insurance : 20 Oct 2017
4. Expiry Date of Insurance : 19 Oct 2018

5. Persons or Classes of Persons entitled to drive*
(a) The Policyholder.
(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use*
(a) Use as a Taxi.
(b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A
EXCESS (SECTION II) : S\$3,500
INSURE WITH COE : N/A
HIRE PURCHASE COMPANY : UNITED OVERSEAS BANK LIMITED
SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)


Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)
Date of Issue : 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

Enquire Transaction History

Transaction History Details

Log Date/Time:	04 Dec 2015 / 09:03:53	Receipt No.:	AACCK001-AX239-151204-000006
Asset Type:	Vehicle	Transaction Amount:	\$68,285.00
Asset ID:	SHC6990S	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151204090353209073		

Vehicle No.:	SHC6990S
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	04 Dec 2015
Original Registration Date:	04 Dec 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5657643
Engine No.:	D4FDFH314472
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,913.00
Minimum PARF Benefit:	\$13,607.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	04 Dec 2015 09:03:53
COE No.:	2015120401003352E
COE Expiry Date:	03 Dec 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,466.00
Lifespan Expiry Date:	03 Dec 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S

1 pc	Rear bumper <i>X repair</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>X</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$ 36.00
2 pcs	Rear bumper ns & o/s reflector @ \$46.00 <i>X</i>	\$ 92.00
1 pc	Bootlid	\$ 1,119.00
1 pc	Bootlid lower garnish <i>X repair</i>	\$ 290.00
1 pc	Bootlid cRdi	\$ 29.00
1 pc	Bootlid emblem	\$ 27.00
		<hr/>
		\$ 3,416.00
	Less 10%	\$ 341.60
		<hr/>
		\$ 3,074.40

S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 280.00 200
1 set	Bootlid stickers	\$ 100.00
1 pc	Rear bumper top protector	\$ 80.00
	Sundry	\$ 50.00 20
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$ 120.00 0X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 0B
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, bootlid lower garnish	\$ 400 850.00
	To putty and spray painting on end panel, rear bumper, bootlid lower garnish, bootlid	\$ 600 800.00
	To apply rustproofing on the repaired and replaced panels.	\$ 200.00 20
		<hr/>
		\$ 5,782.40

Kahin (LKK)
23/4/18 16:04.
3 Lys.
PIP
Before part pll

LKK Auto Consultants hence notify the following:
 • Parts prices are subject to confirmation
 • This quote is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary (s) must be resurveyed and is subject to final approval from insurance Co.
 Acknowledged by Repairer
 Signature:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X see</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X see</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X see</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X see</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X see</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X see</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X see</i>	\$	36.00
2 pcs	Rear bumper ns & o/s reflector @ \$46.00 <i>X see</i>	\$	92.00
1 pc	Bootlid <i>Hand</i>	\$	1,119.00
1 pc	Bootlid lower garnish <i>X repair</i>	\$	290.00
1 pc	Bootlid cRdi <i>see</i>	\$	29.00
1 pc	Bootlid emblem <i>see</i>	\$	27.00
			\$ 3,416.00
Less 10%			\$ 341.60
			\$ 3,074.40

S/NETT

1 set	Rear bumper clips <i>see</i>	\$	48.00
1 set	Reverse sensor <i>should</i>	\$	280.00 <i>200</i>
1 set	Bootlid stickers <i>see</i>	\$	100.00
1 pc	Rear bumper top protector <i>see</i>	\$	80.00 <i>50</i>
	Sundry <i>see</i>	\$	50.00 <i>20</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	120.00 <i>200</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$	180.00 <i>60</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair reshape and adjust of the end panel, bootlid lower garnish	\$	850.00 <i>400</i>
	To putty and spray painting on end panel, rear bumper, bootlid lower garnish, bootlid	\$	800.00 <i>600</i>
	To apply rustproofing on the repaired and replaced panels.	\$	200.00 <i>30</i>
			\$ 5,782.40

Karin (KHK)
23/4/18 16/04.
3 bgs.
PIP
Before part pll

LKK Auto Consultants hence notify the following:

- Parts prices are subject to confirmation
- No illegal modification is allowed
- Supplementary "SI" must be issued, yet not subject to final approval from insurance co.

Acknowledged by Repairer
Signature: _____

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

16/5/18
total ups \$2050/3 bgs

Gary Shi

From: Gary Shi
Sent: Monday, 4 June, 2018 4:20 PM
To: 'Joy Irene (LKKAuto)'
Subject: RE: LOD / Accident involving SHC6990S & WC4483A on 23.04.18 (QBE case)
Attachments: SHC6990S - DV.pdf

WITHOUT PREJUDICE

Dear Joy,

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6990S, our client agreed to direct settle the above claims at \$2640.00

We enclosed hereby Discharge voucher for your kind attention, original copies will pass to Mr Calvin.

Kindly let us have your settlement sum of S\$2640.00 in our favour – Premier Automotive Services Pte Ltd within 14days from the date hereof.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damage only.

Regards

Gary Shi
Senior Executive, Claims
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 069 | DID: 6544 6671 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Monday, 4 June, 2018 3:35 PM
To: Gary Shi
Subject: RE: LOD / Accident involving SHC6990S & WC4483A on 23.04.18 (QBE case)

WITHOUT PREJUDICE

Dear Gary,

Attached DV for your necessary action.

Thank you.

This Settlement excludes any
bodily injuries arising out of the
above said accident and pertains
to property damage only

DISCHARGE VOUCHER

Without Prejudice
Save As to Costs

Your Reference : SHC6990S/GS
Our Reference : VC011416

I/We, **PREMIER TAXIS PTE LTD** do hereby acknowledge the sum of Singapore Dollars: **Two Thousand Six Hundred Forty Only (S\$2,640.00)** being full discharge and satisfaction of all claims against QBE Insurance (Singapore) Pte Ltd and their Insured, **STAR READY-MIX PTE LTD**, over damage to my/our vehicle **SHC 6990S** from an accident involving **WC 4483A** at/along **TAMPINES AVE 10/TAMPINES AVE 12**, which occurred on **23 APRIL 2018** at about **0900** hours.

Further, I/we hereby acknowledge and accept that the above said sum paid to me is 'strictly on a without admission of liability basis' and I/we hereby discharge and release the said QBE Insurance (Singapore) Pte Ltd and their Insured, **STAR READY-MIX PTE LTD**, from all claims, demands or action of damages as a result of the said accident.

Also, I/we hereby agree to indemnify and keep indemnified the said QBE Insurance (Singapore) Pte Ltd against all and any claims whatsoever made or to be made by any person or persons on my/our behalf in respect of the said accident.

Dated this (day) 4 of (month) June (year) 2018

Signature

Claimant's Name

FIN/NRIC No.

Address



Company stamp if applicable

Witness's Signature

Witness's Name

FIN/NRIC No.

Address

Please return to:
General Claims Department
QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay
#29-10 South Tower
Singapore 048583
Fax: 6533 3270

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02
SINGAPORE 486443
TEL:65446671 FAX:62141511
CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6990S/GS

WITHOUT PREJUDICE

22nd May 2018

(By Email Only)

Attn: The Motor Claims Department

QBE Insurance (S) Pte Ltd
1 Raffles Quay
#29-10 South Tower
Singapore 048583

Dear Sir/Madam

ACCIDENT INVOLVING SHC6990S & WC4483A ALONG TAMPINES AVE 10 / TAMPINES AVE 12 ON 23.04.18

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6990S, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: WC4483A at the material time of the accident with the driver of our client's vehicle, Ms Sarifah Bte Md Zain

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: WC4483A, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$	2193.50 (Incl. GST)
(2) Loss of Rental - 3Days @\$108.93per day	\$	326.79
(3) Loss of Income - 3Days @\$100.00per day	\$	300.00
(4) GIA search fee	\$	2.00
	\$	<u>2822.29</u>

A copy of each of the following supporting documents is enclosed:

- (1) Final Repair Bill, GIA report & sketch plan of SHC6990S
- (2) Driver's I/C and Driving Licence
- (3) Vehicle Registration card, Certificate of Insurance
- (4) Check In/Out Voucher, GIA search

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02

SINGAPORE 486443

TEL:65446671 FAX:62141511

CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6990S/GS

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,



Claims Department – Gary Shi

Email: gary.shi@premiertaxi.com

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client – Premier Taxis Pte Ltd



PREMIER AUTOMOTIVE SERVICES PTE LTD
OFFICE: 23 Changi South Avenue 2 #01-02 S(486443)
TEL: 65436676 / 65436689 FAX: 62141511
CO. REG NO.: 200707743D GST REG. NO.: 200707743D

PREMIER TAXIS PTE LTD
23 CHANGI SOUTH AVENUE 2 #03-02
SINGAPORE 486443

TAX INVOICE

DATE 22-May-2018
PAGE 1 OF 1

ITEM	Description	QTY	U.PRICE	AMOUNT
	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S			\$ 2,050.00
TOTAL LUMP SUM REPAIR COSTS AS RECOMMENDED BY SURVEYOR				\$ 2,050.00
GST @ 7%				\$ 143.50
GRAND TOTAL				\$ 2,193.50



for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

AUTHORISATION TO ACT

I/We, **PREMIER TAXIS PTE LTD** ("the third party claimant") of **23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443** (address), owner of **SHC 6990S** (vehicle no.) hereby authorize **PREMIER AUTOMOTIVE SERVICES PTE LTD** ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. **SHC 6990S** that was damaged pursuant to the accident which occurred on **23/04/2018** (date) along **TAMPINES AVE 10/TAMPINES AVE 12** (location) involving vehicle no/s **SHC 6990S** ("the accident").


I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of "the workshop".

I/We further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 4 (day) of June (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/QBE18007568/K1j3n2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 07-06-2018	
		Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 4483A	Veh. Inspected	SHC 6990S
Policy No.	8-V0008896-MVA-R003	Coverage (\$)	0.00
Claim No.	VC011416	Excess (\$)	0.00
Assign From		Assign Date	23/04/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5657643	Colour	SILVER
Odometer	311297	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/04/2018	Inspection Date	23/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6990S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	SERVICEABLE	206.00	-
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S @\$53.00	SERVICEABLE	106.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER O/S & N/S REFLECTOR @\$46.00	SERVICEABLE	92.00	-
1	BOOTLID	DENTED	1,119.00	1,119.00
1	BOOTLID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
	LESS 10% DISCOUNT		-341.60	-117.50
			3,074.40	1,057.50
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			558.00	418.00
LABOUR				
	TO DISMANTLE/REPLACE/TEST REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	60.00

Report Ref No. CC3/QBE18007568/K1jb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, BOOTLID LOWER GARNISH. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND BOOTLID LOWER GARNISH.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON END PANEL, REAR BUMPER, BOOTLID LOWER GARNISH, BOOTLID.		800.00	600.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		200.00	30.00
			2,150.00	1,090.00
	GRAND TOTAL		5,782.40	2,565.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CC3/QBE18007568/K1jb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.