

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6990 S

1 pc	Rear bumper <i>X repair</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper inner sponge <i>X</i>	\$	114.00
1 pc	Rear bumper reinforcement <i>X</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X</i>	\$	36.00
2 pcs	Rear bumper ns & o/s reflector @ \$46.00 <i>X</i>	\$	92.00
1 pc	Bootlid <i>✓</i>	\$	1,119.00
1 pc	Bootlid lower garnish <i>X repair</i>	\$	290.00
1 pc	Bootlid cRdi <i>✓</i>	\$	29.00
1 pc	Bootlid emblem <i>✓</i>	\$	27.00
		\$	3,416.00
		Less 10%	\$ 341.60
		\$	3,074.40

S/NETT

1 set	Rear bumper clips <i>✓</i>	\$	48.00
1 set	Reverse sensor <i>✓</i>	\$	280.00 <i>200</i>
1 set	Bootlid stickers <i>✓</i>	\$	100.00
1 pc	Rear bumper top protector <i>✓</i>	\$	80.00
	Sundry	\$	50.00 <i>20</i>
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	120.00 <i>0X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, bootlid lower garnish	\$	400
	To putty and spray painting on end panel, rear bumper, bootlid lower garnish, bootlid	\$	850.00
	To apply rustproofing on the repaired and replaced panels.	\$	600
		\$	800.00
		\$	200.00 <i>20</i>
		\$	5,782.40

Kahin 12/11/18
23/4/18 16:04.
3 Lys.
PIP
Before Paint p/L

LKK Auto Consultants hence notify the accident of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.