

INS. CASE OWNER:

CC 3/CTI1800 7571 /K1j 6302

LKK:

IDAC:

Surveyor:

Faluin

DOI:

ASSIGNMENT

m/4/18

Date / Time:

m/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGN 457AP

Name of Insured:

TAN HUN MING PETER.

Insured Tel No.:

HP:

9015568

Excess Sec II :S\$

D.O.A.:

m/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM1870067007

Policy No.:

DMP15N1678791701

Make / Model:

MINDA

Place of Accident:

RUE AVE 3 B4 JTE TO UTY.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJS 247A

SGN 457AP

SHB 8256X



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01



INSRS:

WSP:

Tel:

Liability:

RMKS:

Premier

TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
20/4/18	SHB 8256X - X	SGN 457AP - X
30-4-18	115 PM - CALLED - NO ANS.	
	203 OI RETURNED CALLED	
	CONFIRMED ACC.	
	AGREED & AWARENCD	
	ISSUE.	
25-5-18	FOR MANDATE	
	RECEIVED 25 MAY 2018	
	RECEIVED 16 AUG 2018	
	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	JOY 30-4-18
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 20/4/18 Sent By: me

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 10-8-18	Confirm with: GARY	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 28		If NO or B 28, Ass. Lia: 0
Repair Cost:	S\$ 4,853.31		
Loss of Rental (LOR):	S\$ 528.60 5 days 105.72		
Loss of Use (LOU):	S\$ - (\$ x days)		
Loss of Income (LOI):	S\$ - (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	S\$ 2. x x		
Medical:	S\$ -		
Disbursement:	S\$ - (e.g. Tow/ Independent)		
Legal Cost	S\$ -		
Total:	S\$ 5,383.91	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ 5,383.91	Name 1: PREMIER AUTOMOTIVE SERVICES PTE LTD	
Payee 2: (Strike if N.A.)	S\$ x	Name 2: x	
Payee 3: (Strike if N.A.)	S\$	Name 3: x	

3 x C
COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18007571/K1jb3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 24-04-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGN 4579P	Veh. Inspected	SHB 8256X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/04/2018	Inspection Date	23/04/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI18007571/K1jb3

Date: 24.04.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB8256X


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.04.2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	8,874.20
Revised Estimate Amount	: S\$	4,234.60
"Check" Items Amount	: S\$	383.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAuto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 27 April 2018 2:00 PM
To: Shu Pei (LKKAuto)
Subject: FW: Direct Settlement - Accident Involving SGN4579P (OI : CTI - SNM18D02067C02) and SHB8256X (TP : LKK REF - CC3/CTI18007571/K1jb3) on 21.04.2018
Attachments: MLHM18053546-SGN4579P.pdf

Dear Mei Kwan,

I have missed out the OI GIA report for the previous reply, we enclosed herewith the OI GIA on the above attachment fyi.

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Lucas Lee
Sent: Friday, 27 April, 2018 1:54 PM
To: 'Shu Pei (LKKAuto)'
Subject: RE: Direct Settlement - Accident Involving SGN4579P (OI : CTI - SNM18D02067C02) and SHB8256X (TP : LKK REF - CC3/CTI18007571/K1jb3) on 21.04.2018

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Adeline Chng

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [<mailto:shupe@lkkauto.com>]

Sent: Tuesday, 24 April, 2018 5:40 PM

To: Claims Dept of CTI

Cc: Lucas Lee; Sharon Han; Admin A; Joy Irene (LKKAUTO)

Subject: Direct Settlement - Accident Involving SGN4579P (OI : CTI - TBA) and SHB8256X (TP : LKK REF - CC3/CTI18007571/K1jb3) on 21.04.2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 8256X at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409 .

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02067/C02/6**

Date : **27 APRIL 2018**

via Ordinary & Registered Mail

**TAN HUA MONG
BLK 203 BISHAN ST 23
#04-443
SINGAPORE 570203**

Dear Sir / Madam

**ACCIDENT INVOLVING SGN4579P AND SHB8256X ON 21 APRIL 2018
ALONG ANG MO KIO AVE 3 BEFORE CTE TO CITY**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB8256X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd
Attn : JOY
Ref : CC3/CTI18007571/K1JB3
Contact No : 68412409
via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0044A) - CHOO WOON YIT

F01/LKKDS-2013

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Aug 2015 / 07:52:04	Receipt No.:	AACCK001-AX239-150820-000022
Asset Type:	Vehicle	Transaction Amount:	\$72,061.00
Asset ID:	SHB8256X	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150820075204152189		

Vehicle No.:	SHB8256X
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	20 Aug 2015
Original Registration Date:	20 Aug 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5603357
Engine No.:	D4FDEH313597
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$21,203.00
Minimum PARF Benefit:	\$13,011.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	20 Aug 2015 07:52:04
COE No.:	2015082001003038M
COE Expiry Date:	19 Aug 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$50,236.00
Lifespan Expiry Date:	19 Aug 2023

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

1 pc	Boot lid <i>x repair</i>	\$ 1,119.00
1 pc	Boot lid lock <i>x</i>	\$ 99.00
1 pc	Bootlid striker <i>x</i>	\$ 21.00
1 pc	Bootlid emblem <i>/</i>	\$ 27.00
1 pc	Bootlid CRDi <i>/</i>	\$ 29.00
1 pc	Boot lid rubber weatherstrip <i>x</i>	\$ 96.00
1 pc	Boot lid lower garnish <i>x repair</i>	\$ 290.00
2 pcs	Bootlid hinge @ \$66.00 <i>x</i>	\$ 132.00
1 pc	Bootlid inner trim <i>x</i>	\$ 190.00
1 pc	End panel <i>x repair</i>	\$ 250.00
1 pc	End panel garnish <i>?</i>	\$ 74.00
1 pc	Rear muffler assy <i>/</i>	\$ 1,009.00
1 pc	Rear exhaust pipe hanger <i>x</i>	\$ 49.00
1 pc	Rear bumper <i>/</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>/</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>?</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>?</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>/</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>?</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>?</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>?</i>	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>x</i>	\$ 92.00
		<hr/>
		\$ 5,338.00
		Less 10%
		<hr/>
		\$ 4,804.20

S/NETT

1 set	Rear bumper clips <i>/</i>	\$ 48.00
1 set	End panel inner garnish clips <i>x</i>	\$ 30.00
1 set	Bootlid inner trim clips <i>x</i>	\$ 52.00
1 set	Bootlid lower garnish clips <i>x</i>	\$ 60.00
1 pc	Spare tyre <i>x</i>	\$ 280.00
1 set	Bootlid stickers <i>/</i>	\$ 100.00
1 set	Reverse sensor <i>/</i>	\$ 280.00
1 pc	Rear bumper top protector <i>/</i>	\$ 80.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

Towing Fee	\$ 50.00
Sundry	\$ 50.00 20
To dismantle / replace exhaust pipe	\$ 120.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc	\$ 1,200.00 600
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel.	\$ 1,250.00 800
To apply rustproofing on the repaired and replaced panels.	\$ 250.00 X
	\$ 8,874.20
	<u>8954.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahiri / Alka
 23/4/18 1600 hrs
 4 Dgs.
 PIP
 Before PM PL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Witness and Induce" basis
- No illegal modification(s) is a
- Supplementary repairs must be approved and is subject to final approval from the insurance company.

Acknowledged by Repairer
 Signature:
 Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

1 pc	Boot lid <i>x repair</i>	\$ 1,119.00
1 pc	Boot lid lock <i>x su</i>	\$ 99.00
1 pc	Bootlid striker <i>x su</i>	\$ 21.00
1 pc	Bootlid emblem <i>— ne</i>	\$ 27.00
1 pc	Bootlid CRDi <i>— ne</i>	\$ 29.00
1 pc	Boot lid rubber weatherstrip <i>x su</i>	\$ 96.00
1 pc	Boot lid lower garnish <i>x repair</i>	\$ 290.00
2 pcs	Bootlid hinge @ \$66.00 <i>x su</i>	\$ 132.00
1 pc	Bootlid inner trim <i>x su</i>	\$ 190.00
1 pc	End panel <i>x repair</i>	\$ 250.00
1 pc	End panel garnish <i>✓ cm</i>	\$ 74.00
1 pc	Rear muffler assy <i>✓ Bent</i>	\$ 1,009.00
1 pc	Rear exhaust pipe hanger <i>x su</i>	\$ 49.00
1 pc	Rear bumper <i>✓ Bent</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>— cm</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>x su</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>✓ torn</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>— cm</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>✓ Bent</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>✓ cm</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>✓ cm</i>	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>x su</i>	\$ 92.00
		<hr/>
		\$ 5,338.00
		<hr/>
		Less 10%
		\$ 533.80
		<hr/>
		\$ 4,804.20

S/NETT

1 set	Rear bumper clips <i>— ne</i>	\$ 48.00
1 set	End panel inner garnish clips <i>x "</i>	\$ 30.00
1 set	Bootlid inner trim clips <i>x "</i>	\$ 52.00
1 set	Bootlid lower garnish clips <i>x "</i>	\$ 60.00
1 pc	Spare tyre <i>x su</i>	\$ 280.00
1 set	Bootlid stickers <i>— ne</i>	\$ 100.00
1 set	Reverse sensor <i>— shok</i>	\$ 280.00
1 pc	Rear bumper top protector <i>— ne</i>	\$ 20.00
		<hr/>
		50

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

Towing Fee	\$ 50.00
Sundry	\$ 50.00 20
To dismantle / replace exhaust pipe	\$ 120.00 X 11
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X 11
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc	\$ 1,200.00 600
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel.	\$ 1,250.00 800
To apply rustproofing on the repaired and replaced panels.	\$ 250.00 X 11
	<u>\$ 8,874.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin / Alka
 23/4/8 1600
 4 Bp.
 PIP
 Before P4 p4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without prejudice" basis
- No illegal modifications
- Supplementary repairs are subject to final approval by the company

Acknowledged by Repairer:
 Signature:
 Date:

17/5/8 PIP \$4535-80
 Alka
 4 Bp.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18007571/K1jb3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGN 4579P	Veh. Inspected	SHB 8256X
Policy No.	DMPCSN1678791701	Coverage (\$)	0.00
Claim No.	SNM18D02067/C02/6	Excess (\$)	0.00
Assign From		Assign Date	23/04/2018

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5603357	Colour	SILVER
Odometer	351896	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	MAXXIS	7 mm
L/H Front Tyre	205/65 R16	MAXXIS	7 mm
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/04/2018	Inspection Date	23/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8256X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	TO REPAIR SEE LABOUR	1,119.00	-
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	-
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	-
2	BOOTLID HINGE @\$66.00	SERVICEABLE	132.00	-
1	BOOTLID INNER TRIM	SERVICEABLE	190.00	-
1	END PANEL	TO REPAIR SEE LABOUR	250.00	-
1	END PANEL GARNISH	CRACKED	74.00	74.00
1	REAR MUFFLER ASSY	BENT	1,009.00	1,009.00
1	REAR EXHAUST PIPE HANGER	SERVICEABLE	49.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S	BENT	108.00	108.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-533.80	-294.20
			4,804.20	2,647.80
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CC3/CTI18007571/K1jb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	52.00	-
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-
1	SPARE TYRE (SN)	SERVICEABLE	280.00	-
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			980.00	418.00
	LABOUR			
	TOWING FEE.		50.00	50.00
	TO DISMANTLE /REPLACE EXHAUST PIPE.	NOT NECESSARY	120.00	-
	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		120.00	20.00
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT ,CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO BEAT/WELD ,CUT -OFF THE END PANEL .INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE FLOORBOARD COMPARTMENT,ETC.INCLUSIVE OF THE REPAIR OF BOOT LID,BOOT LID LOWER GARNISH AND END PANEL.		1,200.00	600.00
	TO PUTTY AND SPRAY PAINTING ON BOOTLID ,BOOTLID LOWER GARNISH,REAR BUMPER ,FLOORBOARD COMPARTMENT ,END PANEL.		1,250.00	800.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	250.00	-
			3,170.00	1,470.00
GRAND TOTAL			8,954.20	4,535.80
RECOMMENDED COST OF REPAIRS				4,535.80

Report Ref No. CC3/CTI18007571/K1jb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.