

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

23-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

1 pc	Boot lid <i>x repair</i>	\$ 1,119.00
1 pc	Boot lid lock <i>x</i>	\$ 99.00
1 pc	Bootlid striker <i>x</i>	\$ 21.00
1 pc	Bootlid emblem <i>/</i>	\$ 27.00
1 pc	Bootlid CRDi <i>/</i>	\$ 29.00
1 pc	Boot lid rubber weatherstrip <i>x</i>	\$ 96.00
1 pc	Boot lid lower garnish <i>x repair</i>	\$ 290.00
2 pcs	Bootlid hinge @ \$66.00 <i>x</i>	\$ 132.00
1 pc	Bootlid inner trim <i>x</i>	\$ 190.00
1 pc	End panel <i>x repair</i>	\$ 250.00
1 pc	End panel garnish <i>?</i>	\$ 74.00
1 pc	Rear muffler assy <i>/</i>	\$ 1,009.00
1 pc	Rear exhaust pipe hanger <i>x</i>	\$ 49.00
1 pc	Rear bumper <i>/</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>/</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>?</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>?</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>/</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>?</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>?</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>?</i>	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>x</i>	\$ 92.00
		<hr/>
		\$ 5,338.00
		<hr/>
		Less 10%
		\$ 533.80
		<hr/>
		\$ 4,804.20

S/NETT

1 set	Rear bumper clips <i>/</i>	\$ 48.00
1 set	End panel inner garnish clips <i>x</i>	\$ 30.00
1 set	Bootlid inner trim clips <i>x</i>	\$ 52.00
1 set	Bootlid lower garnish clips <i>x</i>	\$ 60.00
1 pc	Spare tyre <i>x</i>	\$ 280.00
1 set	Bootlid stickers <i>/</i>	\$ 100.00
1 set	Reverse sensor <i>/</i>	\$ 280.00
1 pc	Rear bumper top protector <i>/</i>	\$ 80.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8256 X

Towing Fee	\$ 50.00
Sundry	\$ 50.00 20
To dismantle / replace exhaust pipe	\$ 120.00 X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, etc	\$ 1,200.00 600
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel.	\$ 1,250.00 800
To apply rustproofing on the repaired and replaced panels.	\$ 250.00 X
	<u>\$ 8,874.20</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahir (AKA)
 23/4/8 1600
 4 Dgs.
 PIP
 Before Part p4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is a
- Supplementary items must be and is subject to final approval from the repair company

Acknowledged by Repairer

Signature:

Date: