

ASS. REC. BY:

REF: C8/FCL18007575/Klwb n2 Special Instruction:

Surveyor: Kevin ASSIGNMENT (Office)

From (Person): W/S Eileen Lee of FCL Date/Time: 24/04/2018 4:38pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6416J Insured: SHA 4428Z

at Workshop m/s Premier Tel: 6544 6671

of 23 Chungi South Ave 2 #03-02

Policy No: \_\_\_\_\_ Claim No: D18003172MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WDS' 25.04.2018 H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 24/04/2018 5:07pm Person Contacted: Kevin Vehicle  IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6416J - C8 / INV (09011551) / Tipn DCA 130309
	SHA 4428Z - C8 / ALH 18003220 / Klwb3gp DCA: 010218
<u>26/4/18 @ 2:01pm</u>	<u>raised to Eileen Lee by email.</u>

Kaluh

REF: FCL

ASSIGNMENT

From: \_\_\_\_\_ Date: 25042018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 6416J

at Workshop m/s: Premier

of: 23 Chungi South Ave 2 #18-02

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS: \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 6416J Yr Regn: 19 Mar, 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: KIA optima c.c 1681

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 2905B T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KN AHM 414 MF 55 88221

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / SD A/Rim or

Tyre Size: F: 205/65 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Achilles

Front	Rear
R/Bal. 7 mm	R/Bal. 7 mm
L/Bal. 7 mm	L/Bal. 7 mm

D.O.A. 22/4/08 D.O.I. 25/4/08

Survey held at: Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
2/5/08	Collected 4/5 \$600/2 Pys. (Red @ 3053.90, 84%)	4/5

RECEIVED 04 MAY 2018

Date/Time, File Pass to?  Prel. Report

1) 03/5 [Signature]  Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.F. (\$) 600

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: 130

Transportation: 50

S + PS, SI: 50

Photos: 17

Others: \_\_\_\_\_

TOTAL: 247



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003172MFSH

Date: 26 April 2018

Our Ref: CS/FC118007575/K1qb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6416J**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/04/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,653.90</u>
Revised Estimate Amount	: S\$ <u>765.40</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

Kalvin Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	23-04-2018	<b>Our Ref No.</b> D18003172MFSH
<b>Accident Date</b>	22-04-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA4428Z	<b>Third Party Vehicle.</b> SHC6416J
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	GARY SHI	
<b>Contact No.</b>	62148880/ 65446671	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE; WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	EILEEN LEE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 26 April 2018 2:01 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18003172MFSH/1  
**Attachments:** CSFCI18007575K1qb.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHC 6416J.

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 24 April 2018 5:08 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18003172MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin  
**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 24 April, 2018 4:58 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18003172MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited

Text size + -

### Enquire Transaction History

#### Transaction History Details

Log Date/Time:	19 Mar 2015 / 09:18:19	Receipt No.:	AACCK001-AX239-150319-000006
Asset Type:	Vehicle	Transaction Amount:	\$65,621.00
Asset ID:	SHC6416J	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150319091819121291		

Vehicle No.:	SHC6416J
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	19 Mar 2015
Original Registration Date:	19 Mar 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5588221
Engine No.:	D4FDEH313630
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2014
Open Market Value:	\$21,349.00
Minimum PARF Benefit:	\$8,633.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	19 Mar 2015 09:18:19
COE No.:	2015031901002266C
COE Expiry Date:	18 Mar 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$51,092.00
Lifespan Expiry Date:	18 Mar 2023

PREMIER TAXIS	HIREY RELIEF / SUPER RELIEF
VEHICLE NO.	SHC 6415J
CONTACT NO.	8378 4648
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S6816958E



Name  
CHONG VOON KEE IVAN



钟文基  
Race  
CHINESE  
Date of Birth 01-05-1968 Sex M  
Country of Birth SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

License No. S6816958E



Name  
CHONG VOON KEE IVAN

Birth Date 01 May 1968  
Issue Date 04 Jul 2012

002002949C



006000



NRIC No. S6816958E



Blood Group B+ Date of Issue 27-08-1991

APT BLK 677A YISHUN RING ROAD #03-1982  
SINGAPORE 761877  
NRIC No: S6816958E Date: 09/10/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

EFFECTIVE DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver, and other motor vehicles =<2500kg 17 Jul 1990

NP 428A

002002949C



Land Transport Authority


VOCATIONAL LICENCE



License No. S6816958E  
Name CHONG VOON KEE IVAN  
Issue Date 11/10/2012

Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHC6416J

B: SHIA 4428Z

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

X 

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

23 APR 2019

S6816958E



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 22/04/2018 @ 2155HRS, I WAS DRIVING MY TAXI ( SHC 6416 J ) ALONG THE TAXI QUEUE @ CHANGI AIRPORT T2, IN THE MIDDLE LANE.

I STOPPED MY TAXI AS VEHICLES AHEAD OF ME STOPPED - IN THE QUEUE.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.

WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( SHA 4428 Z - COMFORT TAXI ) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.


DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION AND I WAS NOT AWARE OF DAMAGES TO VEHICLE B.

AS A RESULT, I FELT UNWELL AND WILL SEEK FOR MEDICAL TREATMENT SOON. NO AMBULANCE AT SCENE.


NO PASSENGERS ONBOARD BOTH VEHICLES.

\*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER TAXI



THIRD PARTY VEHICLE



S6816958E

Driver's Signature & NRIC Number  
@ 10:39:00 AM

(attended by )

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

23-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6416 J

1 pc	Rear bumper <i>X new</i>	\$ 696.00
1 pc	Rear bumper lower cover <i>1</i>	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X su</i>	\$ 58.00
1 pc	Rear bumper inner sponge <i>X su</i>	\$ 114.00
1 pc	Rear bumper reinforcement <i>X su</i>	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 <i>X su</i>	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>X su</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>X su</i>	\$ 36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 <i>X su</i>	\$ 92.00
		<hr/>
		\$ 1,951.00
		Less 10%
		<hr/>
		\$ 1,755.90

### S/NETT

1 set	Rear bumper clips <i>X</i>	\$ 48.00
1 set	Reverse sensor <i>SLH</i>	\$ <del>280.00</del> 200
Sundry		\$ <del>50.00</del> <i>X 11</i>
To dismantle / replace reverse sensor to new bumper and reset to the same		\$ <del>120.00</del> <i>X 11</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$ <del>180.00</del> <i>X 11</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.		\$ <del>550.00</del> 200
To putty and spray painting on rear bumper, end panel <i>X</i>		\$ <del>550.00</del> 150
To apply rustproofing on the repaired and replaced panels.		\$ <del>120.00</del> <i>X 11</i>
		<hr/>
		\$ 3,653.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST.)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kalvin LKK*  
*25/4/18 10:50h*  
*2 Rys*  
*4/*  
*After Repair*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007575/K1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 4428Z	Veh. Inspected	SHC 6416J
Policy No.		Coverage (\$)	0.00
Claim No.	D18003172MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5588221	Colour	SILVER
Odometer	290513	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	7 mm
L/H Front Tyre	205/65 R16	ACHILLES	7 mm
R/H Rear Tyre	205/65 R16	ACHILLES	7 mm
L/H Rear Tyre	205/65 R16	ACHILLES	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/04/2018	Inspection Date	25/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6416J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	SERVICEABLE	58.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	607.00	-
2	REAR BUMPER STAY O/S & N/S @\$53.00	SERVICEABLE	106.00	-
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	-
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	SERVICEABLE	92.00	-
	LESS 10% DISCOUNT		-195.10	-20.60
			1,755.90	185.40
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SUNDRY (SN)	NOT NECESSARY	50.00	-
			378.00	200.00
<b>LABOUR</b>				
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	NOT NECESSARY	120.00	-
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL, ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		550.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL.		550.00	180.00

Report Ref No. CS/FCI18007575/K1qbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,520.00	380.00
<b>GRAND TOTAL</b>			<b>3,653.90</b>	<b>765.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>600.00</b>

Report Ref No. CS/FCI18007575/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.