

INS. CASE OWNER:

CC 3 / AIG1800

7584, P1 UA352

LKK:
IDAC:

Surveyor:

LAW

DOI:

ASSIGNMENT

28/4/18

Date / Time:

28/4/18

Registered in Merimen:

28/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

6258M

Name of Insured:

TAN BINH CHUAN

Insured Tel No.:

HP:

Claim No.:

Policy No.:

2100504841

Make / Model:

Aston C4

Excess Sec II :SS

D.O.A:

28/4/18

Place of Accident:

Junction of Stennis Whitley & Duquane Rd

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

HONG CHENG HUBE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

4380151

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SKL 10250



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

26/4
19H

SKL 10250 - x ; 6258M - x

Liability unclear,

RECEIVED 18 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Signature: *[Signature]*

REF:

Alt

Rma3

3151A

(W)

ASSIGNMENT

From: _____ Date: 27042018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 1025D

at Workshop m/s: Performance

of: 303 Alexandra Rd

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Han.

10am - 10:30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: PIP % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKL 1025D Yr Regt: 2013 / SEP

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 320I C.C: 1997

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 30607 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA3B120405398015

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or CONTINENTAL

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/04/18 D.O.I. 27/04/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Not finalise
	B 9507.80 (Red: 3598.90 / 27%).
	check item 1519.40

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S+RS. \$I

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18007584/ua3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 24-04-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	EZ 58M	Veh. Inspected	SKL 1025D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	24/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/04/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Friday 27/04 (10-10.30am) SKL 1025D
80

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

24 APR 2018

Estimate No. : b1 46697
Date Estimated : 23/04/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ng Siew Moi
25 Margoliouth Road

Singapore 258551

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1025D	J396015	30/09/2013	320iA/4	0

DESCRIPTION

To replace front bumper & attachments, front left fender and left headlight inner support including to knock out dented area caused by the accident

2550 ~~3400.00~~

To respray front bumper, front left fender and bonnet

2899 3,221.00

To carry out body cavity preservation.
(Per panel).

X 118.00

To replace left headlight including program and conduct tests for proper function.

451 ~~531.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

Sundries.

? 150.00

Total Labour 1: 7,597.00

DESCRIPTION

SHEET METAL NUT SELF-LOCKING
FRT LH SIDE PANEL
FRT LH 2 SIDE PANEL BRACKET
RIVET
FRT LH TOP SUPPORT SIDE PANEL
FRONT SHOCK ABSORBER
INSERT AIR INTAKE CENTER
FRT LH LOWER DEFORMATION ELEMENT
FRT RH LOWER DEFORMATION ELE
LH SUPPORT FOGLAMP
FRT LH BOTTOM MOUNTING SIDE PANEL
FRT BUMPER PANEL TRIM (LINES
LH COVER SPRAY NOZZLE PRIMED
FINISHER ROD LH (SPORT)
PARTIALLY OPEN GRID LH (LINE
FRT LH GRILLE (SPORT)

QTY	PRIC
10	1.00
1	682.50
1	32.15
10	0.50
1	18.00
1	41.15
1	97.90
1	82.65
1	82.65
1	37.60
1	18.00
1	982.75
1	42.20
1	21.05
1	70.05
1	115.65

VALUE
? 10.00
R. 682.50
? 32.15
? 5.00
? 18.00
? 41.15
? 97.90
? 82.65
? 82.65
? 37.60
? 18.00
DE 982.75
ML 42.20
? 21.05
ML 70.05
? 115.65

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46697
Date Estimated : 23/04/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKL1025D	J396015	30/09/2013	320iA/4	0

DESCRIPTION	QTY	PRIC	VALUE
GROMMET	2	0.75	1.50
LH SUPPORT	1	53.95	53.95
FRT BUMPER LOWER MOUNT	1	128.00	128.00
LH HEADLIGHT BRACKET	1	9.50	9.50
CLIP	10	1.30	13.00
LH COVER BOTTOM	1	115.60	115.60
DEFLECTOR LIP LH	1	51.50	51.50
AIR DUCT RADIATOR	1	56.65	56.65
AIR DUCT BOTTOM	1	51.50	51.50
# AIR DUCT BRAKE LH	1	51.50	51.50
PLAQUE 82MM	1	69.50	69.50
TELESCOPING NOZZLE LH	1	155.95	155.95
LH HEADLIGHT (XENON)	1	2,135.85	2,135.85
LH FOG LIGHT	1	276.40	276.40

Total Parts : 5,509.70

Claims OD / Third Party Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 27/04/18 @ 1040 Excess \$

Surveyor's Name R. Han Sign

Surveyor's Tel 900 10068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommended 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	7,597.00
Parts	:	5,509.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	917.47
Grand Total	:	14,024.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)
Sent: Tuesday, 17 July 2018 7:17 PM
To: Md Noor, Norsiah
Subject: ACCIDENT ON 21/04/2018 INVOLVING VEHICLES EZ 58M AND SKL 1025D

Your Ref: 3089532283SG
Our Ref: CC3/AIG18007584/R1ua3

Dear Norsiah,

ACCIDENT ON 21/04/2018 INVOLVING VEHICLES EZ 58M AND SKL 1025D

We refer to the above matter.

Please be inform that we have inspected the vehicle SKL 1025Don 27/04/2018, at Performance Motors Limited and up-to-date there was no response from TP repairer due to liability inclear.

In view of the above, we are intending to temporary close our file and submit W/P report to your good office.

If there are any new developments in future, kindly inform us and we will follow up if necessary.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	24 Apr 2018 Edit Reg		27 Apr 2018 00:00 Edit Adj Rpt	S\$9,507.80 Edit Estimates	S\$9,507.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	TAN BIEN CHUAN, ID: S1163505I		
Main Claimant:	NG SIEW MOI, ID: S1633151A		
Vehicle Reg. No.:	SKL1025D	Date of Loss:	21/04/2018 15:00 - :59 [54 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3089532283SG	Policy/Cover Note No.:	2100504841
Vehicle Reg. No. (Insured):	EZ58M	Policy No. (Claimant):	SD17V10946/VPC/R03/E00
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/05/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKL1025D (3089532283SG)**
[EZ58M]
TP
NG SIEW MOI
Apr 21 2018 3:00PM
[TAN BIEN CHUAN]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page					
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print				
1	25/04/18 10:14		Accident Statement From: SC - Reg. No: EZ58M, Claimant: TAN BIEN CHUAN													Load HTM				
Photos/Images															3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print				
1	17/07/18 19:19		General View													Load JPG				
2	17/07/18 19:19		General View													Load JPG				
3	17/07/18 19:19		General View													Load JPG				
4	17/07/18 19:19		General View													Load JPG				
5	17/07/18 19:19		General View													Load JPG				
6	17/07/18 19:19		General View													Load JPG				
7	17/07/18 19:19		General View													Load JPG				
8	17/07/18 19:19		General View													Load JPG				
9	17/07/18 19:19		General View													Load JPG				
10	17/07/18 19:19		General View													Load JPG				
11	17/07/18 19:19		General View													Load JPG				
12	17/07/18 19:19		General View													Load JPG				
13	17/07/18 19:19		General View													Load JPG				
14	17/07/18 19:19		General View													Load JPG				
15	17/07/18 19:19		General View													Load JPG				
16	17/07/18 19:19		General View													Load JPG				
17	17/07/18 19:19		General View													Load JPG				
18	17/07/18 19:19		General View													Load JPG				
19	17/07/18 19:19		General View													Load JPG				
20	17/07/18 19:19		General View													Load JPG				
21	17/07/18 19:19		General View													Load JPG				
22	17/07/18 19:19		General View													Load JPG				
23	17/07/18 19:19		General View													Load JPG				
24	17/07/18 19:19		General View													Load JPG				
25	17/07/18 19:19		General View													Load JPG				
26	17/07/18 19:19		General View													Load JPG				
27	17/07/18 19:19		General View													Load JPG				
28	17/07/18 19:19		General View													Load JPG				
29	17/07/18 19:19		General View													Load JPG				
30	17/07/18 19:19		General View													Load JPG				
31	17/07/18 19:19		General View													Load JPG				

Assessment Reports				✓
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)	Thumbnail	Print
32	17/07/18 19:19	General View	 Load JPG	✓
33	17/07/18 19:19	General View	 Load JPG	✓
34	17/07/18 19:19	General View	 Load JPG	✓
35	17/07/18 19:19	General View	 Load JPG	✓
36	17/07/18 19:19	General View	 Load JPG	✓
37	17/07/18 19:19	General View	 Load JPG	✓
38	17/07/18 19:19	General View	 Load JPG	✓
39	17/07/18 19:19	General View	 Load JPG	✓
40	17/07/18 19:19	General View	 Load JPG	✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/04/18 21:42	TP GIA REPORT	 Load PDF	
2	24/04/18 21:42	TP ESTIMATE	 Load TIF	
3	30/04/18 18:32	TP ESTIMATE- MARKED	 Load PDF	
4	17/07/18 19:17	email to AIG	 Load PDF	
5	19/07/18 14:41	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18007584/R1UA3S2
Date: 19/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100504841
Claimant Vehicle No: SKL1025D Insured Vehicle No: EZ58M
Date of Loss: 21/04/2018 Nature of Claim: TP Claim No: 3089532283SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL1025D Engine No: B3870564N20B20B
Make & Model: BMW 320I, 2.0 (A) Chassis No: WBA3B12040J396015
Reg. Date: 30/09/2013 (Man. Year: 2013) Odometer: 30607 km
Colour: Black
Engine Capacity: 1997 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 Rear Tyre Size: 225/50R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,659.70	3,457.80	2,201.90	38.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,447.00	6,050.00	1,397.00	18.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,106.70	9,507.80	3,598.90	27.46
+ GST 7.00/7.00% (S\$)	917.47	665.55	251.92	27.46
Nett Amount (S\$)	14,024.17	10,173.35	3,850.82	27.46

INSPECTION

Date of Assignment: 27/04/2018
Date Inspected: 27/04/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,519.40 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*SHEET METAL NUT SELF-LOCKING	*Check	10.00 FS	*- FS
2	1		*FRT LH SIDE PANEL	Repair	682.50 FS	*- FS
3	1		*FRT LH 2 SIDE PANEL BRACKET	*Check	32.15 FS	*- FS
4	10		*RIVET	*Check	5.00 FS	*- FS
5	1		*FRT LH TOP SUPPORT SIDE PANEL	*Check	18.00 FS	*- FS
6	1		*FRONT SHOCK ABSORBER	*Check	41.15 FS	*- FS
7	1		*INSERT AIR INTAKE CENTER	*Check	97.90 FS	*- FS
8	1		*FRT LH LOWER DEFORMATION ELEMENT	*Check	82.65 FS	*- FS
9	1		*FRT RH LOWER DEFORMATION ELE	*Check	82.65 FS	*- FS
10	1		*LH SUPPORT FOGLAMP	*Check	37.60 FS	*- FS
11	1		*FRT LH BOTTOM MOUNTING SIDE PANEL	*Check	18.00 FS	*- FS
12	1		*FRT BUMPER PANEL TRIM (LINES)	Deformed	982.75 FS	*982.75 FS
13	1		*LH COVER SPRAY NOZZLE PRIMED	Missing	42.20 FS	*42.20 FS
14	1		*FINISHER ROD LH (SPORT)	*Check	21.05 FS	*- FS
15	1		*PARTIALLY OPEN GRID LH (LINE)	Missing	70.05 FS	*70.05 FS
16	1		*FRT LH GRILLE (SPORT)	*Check	115.65 FS	*- FS
17	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
18	1		*LH SUPPORT	*Check	53.95 FS	*- FS
19	1		*FRT BUMPER LOWER MOUNT	*Check	128.00 FS	*- FS
20	1		*LH HEADLIGHT BRACKET	*Check	9.50 FS	*- FS
21	10		*CLIP	*Check	13.00 FS	*- FS
22	1		*LH COVER BOTTOM	*Check	115.60 FS	*- FS
23	1		*DEFLECTOR LIP LH	*Check	51.50 FS	*- FS
24	1		*AIR DUCT RADIATOR	*Check	56.65 FS	*- FS
25	1		*AIR DUCT BOTTOM	*Check	51.50 FS	*- FS
26	1		*AIR DUCT BRAKE LH	*Check	51.50 FS	*- FS
27	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
28	1		*TELESCOPING NOZZLE LH	Cracked	155.95 FS	*155.95 FS
29	1		*LH HEADLIGHT (XENON)	Scratched	2,135.85 FS	*2,135.85 FS
30	1		*LH FOG LIGHT	*Check	276.40 FS	*- FS
31	1		*SUNDRIES	*Check	150.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					5,659.70	3,457.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS, FRONT LEFT FENDER AND LEFT HEADLIGHT INNER SUPPORT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	3,400.00	2,550.00
2	TO RESPRAY FRONT BUMPER, FRONT LEFT FENDER AND BONNET.	New	3,221.00	2,899.00
3	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	0.00
4	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.	New	531.00	451.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.	New	177.00	150.00
Gross Labour Cost (S\$)			7,447.00	6,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >