

15/02/10

INS. CASE OWNER:

Jaclyn

CC<sup>3</sup> / AIG1800

XSK

11

UA39

LKK: IDAC:

Surveyor:

MMH

DOI:

28/6/18

Date / Time:

24/4/18

Registered in Merimen:

24/4/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SJY 446Y  
 Name of Insured : Wong Pak Inc  
 Insured Tel No. : \_\_\_\_\_ HP: 96363024  
 Excess Sec II :SS \_\_\_\_\_ D.O.A : 28/4/18  
 Is driver the owner? ( YES /  ) Nature of Accident : \_\_\_\_\_

Claim No. : 599256740856  
 Policy No. : 210022561  
 Make / Model : Kia Cerato  
 Place of Accident : Entrance to blk 613 BT Binjeng Ring Road.

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO )

Insured Liability: %

Final ? Yes / No

SKV 383Z



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: mm  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
 WSP: \_\_\_\_\_  
 Tel: \_\_\_\_\_  
 Liability: \_\_\_\_\_  
 RMKS: \_\_\_\_\_

Date/ Time		STAGE	DATE / PIC
26/4	SKV 383Z, SJY 446Y	Non-Reporting ltr (1st):	
1PM		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
26/4	OMP. sent out first letter.	Call OI:	> IMM By Email
		After call ltr to OI:	2315
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

Spoke to OI, he confirmed the accident details. He let insurance to handle the matter.

RECEIVED 30 AUG 2018  
RECEIVED 11 JUL 2018

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS ( days) Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b>	Date/Time: <u>30/8/18</u>	Confirm with <u>Caroline</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% <u>100</u> (Agreed/ Assessed)	BOLA S/N No. : <u>9</u>	If NO or B 28, Ass. Lia :
Repair Cost:	SS <u>7855.30</u>		
Loss of Rental (LOR):	SS ( days)		
Loss of Use (LOU):	SS <u>200.00</u> (\$ <u>50</u> x <u>4</u> days)		
Loss of Income (LOI):	SS (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search:	SS <u>2.00</u>		
Medical:	SS		
Disbursement:	SS (e.g. Tow/ Independent )		
Legal Cost:	SS		
<b>Total:</b>	SS <u>8057.30</u>	Global Sum SS:	
<b>FINAL PAYMENT</b>	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS <u>7857.30</u>	Name 1: <u>PERFORMANCE MOTORS LIMITED</u>	
Payee 2: (Strike if N.A.)	SS <u>200.00</u>	Name 2: <u>YONG MYET YAN</u>	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPIES SENT 30/8/18





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18007585/ua3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 24-04-2018	
Code : AIG			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 446Y	Veh. Inspected	SKV 383Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/04/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401539W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159943  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Tampong Arany Road  
East Coast Centre  
Singapore 438180  
Tel. 63180888 (AfterSales)  
Fax. 43449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63150318 (AfterSales)  
63190333/330 (Motorrad)  
Fax. 64776511 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

24 APR 2018

Estimate No. : b1 46715 Page No. : 1 of 2  
Date Estimated : 24/04/2018  
Prepared By : Kevin Leong Wai Kit

**- ESTIMATE REPAIR FOR -**

Yong Nyet Yan  
101 Lentor Street

Singapore 786811

**- ACCOUNT - 40000**

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV383Z	5C06696	14/08/2015	116d	0

DESCRIPTION

To repair on front right side panel  
To replace front bumper assembly and all attachments  
cause by accident.

VALUE

1700 2,550.00

Painting on front bumper & front right side panel

1730 1,923.00

To check electrical wiring systems at the front section  
for proper function.

150 177.00

To replace right headlight including program and conduct  
tests for proper function.

451 531.00

Sundries. *hew*

*net* 80.00

Total Labour 1: 5,261.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
CLAMP	10	3.20	
FRT BUMPER TOP MOUNT	1	361.65	
RH CLOSED GRID (BASIS)	1	93.20	
IMPACT ABSORNER TOP	1	42.45	
GRILLE MIDDLE BOTTOM	1	115.50	
FRT BUMPER LH INSERT	1	32.15	
FRT BUMPER RH INSERT	1	32.15	
FRT BUMPER PANEL PRIMED	1	786.20	
SET PDC HOLDER FRONT	1	23.10	
SET PMA HOLDERS FRT/REAR	1	21.25	
EMBLEM GROMMET	1	0.80	
PLAQUE 82MM	1	69.50	
RH HEADLIGHT LED TECHNOLOGY	1	2,263.60	
DECOUPLING RING PDC TORQUE CONVERTE	5	5.05	
(DG/SL) ADHESIVE SET K6	1	53.05	

QTY PRIC

VALUE

*net* 8.20  
~~361.65~~  
~~93.20~~  
~~42.45~~  
~~115.50~~  
~~32.15~~  
~~32.15~~  
~~786.20~~  
~~23.10~~  
~~21.25~~  
~~0.80~~  
~~69.50~~  
~~2,263.60~~  
~~25.25~~  
~~53.05~~

Total Parts : 3,923.05

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401159W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Tampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 63190878 (AfterSales)  
Fax: 63445773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No.	: b1 46715	Page No. :	2 of 2
Date Estimated	: 24/04/2018		
Prepared By	: Kevin Leong Wai Kit		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV383Z	5C06696	14/08/2015	116d	0

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

0

28/5/18 @ MS  
Tanjinh  
97198349

Tanjinh @ lkkauto.com  
4 days

Labour 1	:	5,261.00
Parts	:	3,923.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	642.88
<b>Grand Total</b>	:	<b>9,826.93</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## FINAL REPORT

Estimate No. : b1 46715  
Date Estimated : 24/04/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Yong Nyet Yan  
101 Lentor Street

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 786811

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKV383Z	5C06696	14/08/2015	116d	0

  

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include making good the front RH fender and knocking out dents caused by the accident.	1700.00		1,700.00
To spray painting front bumper and front RH fender	1730.00		1,730.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
To replace RH LED technology headlight include programming and conducting tests for proper function	451.00		451.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
CLAMP	3.20	10.00		32.00
FRT BUMPER PANEL PRIMED	786.20	1.00		786.20
EMBLEM GROMMET	0.80	1.00		0.80
PLAQUE 82MM	69.50	1.00		69.50
RH HEADLIGHT LED TECHNOLOGY	2,263.60	1.00		2,263.60
DECOUPLING RING PDC TORQUE CONVERTE	5.05	5.00		25.25
(DG/SL) ADHESIVE SET K6	53.05	1.00		53.05

### # SUPPLEMENTARY ITEMS

Total Labour :	4,111.00
Total Parts :	3,230.40
Total Labour & Parts :	7,341.40
Deduction for Excess :	
Total Repair Costs less Excess:	7,341.40
GST @7%:	513.90
<b>Grand Total :</b>	<b>7,855.30</b>



### View Received Message

This mail is associated with 1:

**\*SKV383Z (59925674085G)  
[5JY446Y]  
TP  
YONG NYET YAN  
Apr 23 2018 6:00PM  
[Wong Pak Lue]  
Performance Motors Limited**

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 21/08/2018 16:40 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8057.30) - SKV383Z - Claim Handler: Kesaval, Jaclyn-M

Approved:8057.30:COR - S\$7,855.30 LOU - S\$200.00 LTA/GIA - S\$2.00

#### DOCUMENTS SUMMARY

There are no documents.



**REPUBLIC OF SINGAPORE DRIVING LICENCE**

Licence Number: **S9230872C**

Name: **CELINE CHAN QI BIN**

Birth Date: **26 Aug 1992**

Issue Date: **13 Aug 2013**

002212603C




**SINGAPORE ARMED FORCES**

**IDENTITY CARD**

Name: **CELINE CHAN QI BIN**

NRIC No: **S9230872C**



The card is the property of the Singapore Armed Forces. Any person finding this card is requested to bring it without delay to Central Manpower Base or any Police Station.

**REPUBLIC OF SINGAPORE**

**IDENTITY CARD NO. S1717202F**

Name: **YONG NYET YAN**

**楊月圓**

Race: **CHINESE**

Date of Birth: **18-07-1965** Sex: **F**

Country of Birth: **SINGAPORE**





**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class	Vehicle Description	Effective Date
Class 3	Motor Cars =< 3000kg with =< 7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg	06 Apr 2011

NP 428A

Licence No: S9230872C



00000060304007

NRIC No/Colour: **S9230872C/ PINK**

Race: **CHINESE**

Date of Birth: **26/08/1992**

Service Status: **REGULAR**

Address: **101 LENTOR STREET SINGAPORE 786811**

Blood Group: **B (+)**

Country Of Birth: **SINGAPORE**

Military Rank Status: **OFFICER**

Sex: **F**



221207

NRIC No: **S1717202F**

Blood Group: **B+** Date of Issue: **21-07-1994**

**101 LENTOR STREET SINGAPORE 786811**

NRIC No: **S1717202F** Date: **08/01/2013** No: **7181544**




**Thin Thin (LKKAuto)**

---

**From:** Thin Thin (LKKAuto)  
**Sent:** Wednesday, 23 May 2018 6:39 PM  
**To:** 'davidwongpl@yahoo.com.sg'  
**Subject:** ACCIDENT INVOLVING SJY 446Y & SKV 383Z ON 23/04/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18007585/ua3

24 MAY 2018

**WONG PAK LUE**

Dear Sir/Madam,

**ACCIDENT INVOLVING SJY 446Y & SKV 383Z ON 23/04/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, Yong Nyet Yan (the third party claimant) of 101 Lentor Street SC 786811 (address), owner of SKV383Z (vehicle no.) hereby authorize Performance Motors Limited ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SKV383Z that was damaged pursuant to the accident which occurred on 23/4/18 (date) along Entrance to BIK 613 BT Panjyang Ring Rd (location) involving vehicle no/s SJK 446Y <sup>HDB Cluster</sup> ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 28 (day) of 05 (month) 2018 (year)

  
\_\_\_\_\_ α

Signed by "the third party claimant"  
(with chop if applicable)

  
\_\_\_\_\_

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941
---

Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKE AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 785530 (repair costs), S\$ 200.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SKV3832 that was damaged pursuant to the accident which occurred on 23.4.18 (date) along Entrance to Blk 613 BT Panjang Ring Road HDB (location) involving vehicle no/s SIY446Y cluster.

This is pursuant to the inspection conducted on 28.5.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Yang Nyet Yan ("third party claimant") of vehicle no. SKV3832 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKV3832 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 30 day of 08 (month) 2018 (year)



MTH

Signed by AIG appointed surveyor

**PERFORMANCE MOTORS LIMITED**  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (AfterSales)

HL

Chopped & Signed by "the workshop"

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 61190888 (AfterSales)  
Fax. 61449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

(1)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1270879</b>	Page No. : <b>1 of 2</b>
Date IN : <b>28/05/2018</b>	Invoice Number : <b>1978258 / WSB</b>
Cust. Svc. Advisor: <b>Kevin Leong Wai Kit</b>	Invoice Date : <b>21/06/2018</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

**- CUSTOMER INFORMATION -**Mdm Yong Nyet Yan  
101 Lentor Street

Singapore 786811

**- INVOICE TO - 121**AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. <b>SKV383Z</b>	CHASSIS NO. <b>5C06696</b>	REGN. DATE <b>14/08/2015</b>	MODEL <b>116D</b>	MILEAGE <b>29987</b>
-----------------------------	-------------------------------	---------------------------------	----------------------	-------------------------

**--- LABOUR 1 ---**

	<u>NETT</u>
To replace front bumper including to make good the front right fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	1,700.00
To respray front bumper and front right fender.	1,730.00
To check electrical wiring systems at the front section for proper function.	150.00
To replace right Technology LED headlight including program and conduct tests for proper function.	451.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 23.4.2018. 3RD PARTY CAR : SJY446Y.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 28.5.2018 AT 11.15 AM. AUTHORISED REPAIR BY MS THIN THIN HLAING FROM LKK ON 9.5.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$50X4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: **4,111.00****--- PARTS ---**

	Qty	Retail Price	NETT
FRT BUMPER PANEL PRIMED	1	786.20	786.20
EMBLEM GROMMET	1	0.80	0.80
PLAQUE 82MM	1	69.50	69.50
DECOUPLING RING PDC TORQUE CONVERTE	5	5.05	25.25
RH HEADLIGHT LED TECHNOLOGY	1	2,263.60	2,263.60
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
CLAMP	10	3.20	32.00

Total Parts : **3,230.40**

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63180888 (AfterSales)  
Fax. 63449773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)**SERVICE TAX INVOICE**Repair Order No. : **B1 1270879**Date IN : **28/05/2018**Cust. Svc. Advisor: **Kevin Leong Wai Kit**Page No. : **2 of 2**Invoice Number : **1978258 / WSB**Invoice Date : **21/06/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**

Labour Charges	: 4,031.00	Total Labour & Parts Charges	: S\$ 7,341.40
Parts Charges	: 3,230.40	Less Insurance Excess	: S\$ 0.00
Lubricant/Misc	: 80.00	Invoice Total Amount Exclude GST	: S\$ 7,341.40
		GST @ 7%	: S\$ 513.90
		Invoice Total Amount Include GST	: S\$ 7,855.30

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 7,855.30**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-062006

Date of Request: 24/04/2018

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 24/04/2018  
Enquiry By Vivi  
TP Vehicle No. SJY446Y  
Accident Date 23/04/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJY446Y	AIG Asia Pacific Insurance Pte. Ltd.	30/07/2017-29/07/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

 6 Raffles Quay #18-00, Singapore 048580  
 Phone: +65 6224 0010 Fax: +65 6224 0030  
 Operating Hours: Monday to Friday 9am to 5pm  
 GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-062006

Date of Request: 24/04/2018

Your Ref No: Online Purchase

 Performance Motors Limited  
 303 Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941

Dear Sir/Madam,

 Enquiry Date 24/04/2018  
 Enquiry By Vivi  
 TP Vehicle No. SJY446Y  
 Accident Date 23/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO
  Cash
  Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Apr 2018 <a href="#">Edit Reg</a>		28 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$7,341.40</b> <a href="#">Edit Estimates</a>	<b>S\$7,341.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>Wong Pak Lue</b> , ID: S03390031								
Main Claimant:	<b>YONG NYET YAN</b> , ID: S1717202F								
Vehicle Reg. No.:	<b>SKV383Z</b>	Date of Loss:	23/04/2018 18:00 - :59 [32 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5992567408SG</b>	Policy/Cover Note No.:	2100221561 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SJY446Y</b>	Policy No. (Claimant):	VPA/P1641188						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	<b>AXA Insurance Pte Ltd (HQ)</b> - Tel: 6338 7288								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 04/05/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (21/08/2018): <b>Alert - Adj Mandate Approved (S\$8057.30) - SKV383Z - Claim Handler: Kesaval, Jac...</b></li> <li>AIG_SG (25/04/2018): <b>NO OI GIA REPORT</b></li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SKV383Z (5992567408SG)  
[SJY446Y]  
TP  
YONG NYET YAN  
Apr 23 2018 6:00PM  
[Wong Pak Lue]  
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser <input type="button" value="v"/></span>	
<b>Letters/Correspondences</b>										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>							Edit		
<b>Assessment Reports</b>										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	04/05/18 12:13	<b>Accident Statement</b> <small>From: SC - Reg. No: SJY446Y, Claimant: WONG PAK LUE</small>							Load HTM		
<b>Photos/Images</b>										3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
2	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
3	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
4	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	20/08/18 14:16	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>										1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	24/04/18 21:54	<b>TP ESTIMATE</b>							Load TIF		
2	24/04/18 21:54	<b>TP GIA REPORT</b>							Load PDF		
3	26/04/18 09:04	<b>Non reporting letter</b>							Load PDF		
4	02/06/18 13:20	<b>TP ESTIMATE-MARKED</b>							Load PDF		
5	01/08/18 14:14	<b>LETTER TO OI</b>							Load PDF		
6	01/08/18 14:14	<b>GIA SEARCH</b>							Load PDF		
7	03/09/18 14:19	<b>WORKSHOP INVOICE</b>							Load PDF		
8	03/09/18 14:19	<b>AUTHORISATION TO ACT FORM</b>							Load PDF		
9	03/09/18 14:19	<b>Release Voucher</b>							Load PDF		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	SJY446Y (Insd veh)	<b>Model:</b>	BMW 116D 1.5 (A)
	SKV383Z (TP veh)		
<b>Date of Accident:</b>	23/04/2018		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	:\$		9,857.75	
Final Repair Cost	:\$		7,855.30	
Loss of Use	:\$		200.00	4.00 days at \$50.00 per day
Rental (if any)	:\$		0.00	days
LTA / GIA Search Fee	:\$		2.00	
Others:	:\$		0.00	
	:\$			
<b>Final Settlement Sum</b>	<b>:\$</b>		<b>8,057.30</b>	

**Is Third Party Workshop GIA Registered?** [ X ] YES [ ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 9

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:\$	7,857.30
2)	Yong Nyet Yan	:\$	200.00
3)		:\$	

JOANNE LEE KHANG MIN  
\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

03 Sep  
2018  
\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG18007585/T1UA3Q2  
**Date:** 03/09/2018

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2100221561	
<b>Claimant Vehicle No :</b> SKV383Z	<b>Insured Vehicle No :</b> SJY446Y	
Date of Loss: 23/04/2018	Nature of Claim: TP	Claim No: 5992567408SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SKV383Z</b>		Engine No: 32409287B37D15A
Make & Model: BMW 116D, 1.5 (A)		Chassis No: WBA1V720805C06696
Reg. Date: 14/08/2015 (Man. Year: 2015)		Odometer: 29987 km
Colour: White		
Engine Capacity: 1496 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 205/55 R16	Rear Tyre Size: 205/55 R16	
Front Left Side: Goodyear 6 mm	Rear Left Side: Goodyear 6 mm	
Front Right Side: Goodyear 6 mm	Rear Right Side: Goodyear 6 mm	

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,031.85	3,310.40	721.45	17.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,181.00	4,031.00	1,150.00	22.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,212.85</b>	<b>7,341.40</b>	<b>1,871.45</b>	<b>20.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>644.90</b>	<b>513.90</b>	<b>131.00</b>	<b>20.31</b>
<b>Nett Amount (S\$)</b>	<b>9,857.75</b>	<b>7,855.30</b>	<b>2,002.45</b>	<b>20.31</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
	<b>Nett Liability (S\$)</b>	<b>8,057.30</b>		

#### INSPECTION

Date of Assignment: 28/05/2018		
Date Inspected: 28/05/2018	Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair: 4.0 days		

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*CLAMP	Necessary	32.00 FS	*32.00 FS
3	1		*FRT BUMPER TOP MOUNT	Not Necessary	361.65 FS	*- FS
4	1		*RH CLOSED GRID (BASIS)	Not Necessary	93.20 FS	*- FS
5	1		*IMPACT ABSORNER TOP	Not Necessary	42.45 FS	*- FS
6	1		*GRILLE MIDDLE BOTTOM	Not Necessary	115.50 FS	*- FS
7	1		*FRT BUMPER LH INSERT	Not Necessary	32.15 FS	*- FS
8	1		*FRT BUMPER RH INSERT	Not Necessary	32.15 FS	*- FS
9	1		*FRT BUMPER PANEL PRIMED	Deformed	786.20 FS	*786.20 FS
10	1		*SET PDC HOLDER FRONT	Not Necessary	23.10 FS	*- FS
11	1		*SET PMA HOLDERS FRT/REAR	Not Necessary	21.25 FS	*- FS
12	1		*EMBLEM GROMMET	Necessary	0.80 FS	*0.80 FS
13	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
14	1		*RH HEADLIGHT LED TECHNOLOGY	Cut	2,263.60 FS	*2,263.60 FS
15	5		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	25.25 FS	*25.25 FS
16	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)      4,031.85      3,310.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR ON FRONT RIGHT SIDE PANEL TO REPLACE FRONT BUMPER ASSEMBLY AND ALL ATTACHMENTS CAUSE BY ACCIDENT	New	2,550.00	1,700.00
2	PAINTING ON FRONT BUMPER & FRONT RIGHT SIDE PANEL	New	1,923.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
<b>Gross Labour Cost (S\$)</b>			<b>5,181.00</b>	<b>4,031.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >