

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

24 APR 2018

Estimate No. : b1 46715	Page No. : 1 of 2
Date Estimated : 24/04/2018	
Prepared By : Kevin Leong Wai Kit	

- ESTIMATE REPAIR FOR - Yong Nyet Yan 101 Lentor Street Singapore 786811	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV383Z	5C06696	14/08/2015	116d	0

DESCRIPTION	VALUE
To repair on front right side panel To replace front bumper assembly and all attachments cause by accident.	1700 2,550.00
Painting on front bumper & front right side panel	1730 1,923.00
To check electrical wiring systems at the front section for proper function.	150 177.00
To replace right headlight including program and conduct tests for proper function.	451 531.00
Sundries.	80.00

Total Labour 1: **5,261.00**

DESCRIPTION	QTY	PRIC	VALUE
CLAMP	1	3.20	? 3.20
FRT BUMPER TOP MOUNT	1	361.65	? 361.65
RH CLOSED GRID (BASIS)	1	93.20	? 93.20
IMPACT ABSORNER TOP	1	42.45	? 42.45
GRILLE MIDDLE BOTTOM	1	115.50	? 115.50
FRT BUMPER LH INSERT	1	32.15	x 32.15
FRT BUMPER RH INSERT	1	32.15	? 32.15
FRT BUMPER PANEL PRIMED	1	786.20	del 786.20
SET PDC HOLDER FRONT	1	23.10	? 23.10
SET PMA HOLDERS FRT/REAR	1	21.25	? 21.25
EMBLEM GROMMET	1	0.80	nei 0.80
PLAQUE 82MM	1	69.50	nei 69.50
RH HEADLIGHT LED TECHNOLOGY	1	2,263.60	cut 2,263.60
DECOUPLING RING PDC TORQUE CONVERTE	5	5.05	nei 25.25
(DG/SL) ADHESIVE SET K6	1	53.05	53.05

Total Parts : **3,923.05**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46715
Date Estimated : 24/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV383Z	5C06696	14/08/2015	116d	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 28/5/18 @ 14:5 Excess S\$ _____

Surveyor's Name Tan Jiah Sign Tan Jiah

Surveyor's Tel 97298719 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommended 4 days

Labour 1	:	5,261.00
Parts	:	3,923.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	642.88
Grand Total	:	<u>9,826.93</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **