

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

88 SOUTH BRIDGE ROAD
SINGAPORE 058716

TEL: 65322888

ATTN: Motor Claim Department

Estimate No: EST1800109

Date: 23 Apr 2018

Veh Reg No: SFR992X

Make/Model: HYUNDAI HD AVANTE
1.6A

Chasis No: KMHDU41BR9U679810

Reg. Date: 11/02/2009

Your Ref No: SJW9857X

Claim Type: Third Party

Accident Date: 22/04/2018

TP Veh Reg No: SFR992X

Estimate Repair Cost to Vehicle No :SFR992X

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC FRT DOOR RH <i>Distorted</i>	1,641.00 ¹²⁵⁸	
2	1 PC FRT DOOR OUTER HANDLE RH <i>Dist</i>	48.00	
3	1 PC FRT DOOR KEY LOCK COVER RH <i>new</i>	16.00	
4	1 PC FRT RH DOOR LOCK <i>Dist</i>	368.00	
5	1 PC FRT DOOR RUBBER RH <i>new</i>	197.00	
6	1 PC FRT DOOR REGULATOR ASSEMBLY RH <i>Damaged</i>	457.00	
7	1 PC FRT DOOR GLASS CHANNEL RH <i>new</i>	120.00	
8	1 PC FRT DOOR OUTER MOULDING RH <i>new</i>	45.00	
9	1 PC FRT DOOR FRAME BLACK STICKER RH <i>new</i>	36.00	
10	1 PC REAR DOOR RH <i>Distorted</i>	1,744.00 ^{3201.60}	
11	2 PCS REAR DOOR HINGE RH <i>Best</i>	144.00	
12	1 PC REAR DOOR RUBBER RH <i>new</i>	134.00	
13	1 PC REAR DOOR REGULATOR ASSY RH <i>Not new</i>	433.00	
14	1 PC REAR DOOR GLASS CHANNEL RH <i>new</i>	129.00	
15	1 PC REAR DOOR OUTER MOULDING RH <i>new</i>	46.00	
16	1 PC REAR DOOR FRAME BLACK STICKER RH <i>new</i>	45.00	
2 PC	Door Visor <i>new</i>	5,603.00	
	Less 20%	1,120.60	4,482.40
	Labour		
17	1 TO REMOVE AND REFIX DOOR TRIM	100.00 ⁸⁰	
18	1 TO REMOVE AND REFIT FRT DOOR GLASS RH	100.00 ⁴⁰	
19	1 TO REMOVE AND REFIX REAR DOOR GLASS RH	100.00 ⁴⁰	
20	1 TO SPRAY UNDERSEAL	80.00 ²	
21	1 TO SPRAY PAINTING	1,200.00 ⁸⁰⁰	
22	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,200.00 ⁷⁰⁰	
23	1 TO CHECK WIRING	60.00 ³⁰	
		2,840.00	2,840.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD

88 SOUTH BRIDGE ROAD

SINGAPORE 058716

TEL: 65322888

ATTN: Motor Claim Department

Estimate No: EST1800109

Date: 23 Apr 2018

Veh Reg No: SFR992X

Make/Model: HYUNDAI HD AVANTE
1.6A

Chasis No: KMH DU41BR9U679810

Reg. Date: 11/02/2009

Your Ref No: SJW9857X

Claim Type: Third Party

Accident Date: 22/04/2018

TP Veh Reg No: SFR992X

Estimate Repair Cost to Vehicle No :SFR992X

Quantity	Description	List Price S\$	Amount S\$
		Total	SS 7,322.40
		Add GST @ 7%	512.57
		Total Amount Payable	SS 7,834.97

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED THIRTY FOUR AND CENTS NINETY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adnan hij
23/04/18.
L/s.

total 5011.60

L/s A.K.

LKK Auto Consultants hereby certify that the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- its prices are subject to confirmation
- and party survey is on a "Without Prejudice" basis
- any modification(s) is allowed
- any supplementary item(s) must be resurveyed and
- subject to final approval from Insurance Company

Witnessed by Reparer

ATC

OShyr