

REF: CS/EGU8007601/Uvb n2 | Special Instruction:

Suvajoy

ASSIGNMENT (Office)

From (Person): Yee Pei Li of ECN Date/Time: 15/04/2018 12:26pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 94 953ST Insured: SJQ 5343U

at Workshop m/s E-phuz Tel: 8822 8339

of 30 Bukit Batok Crescent

Policy No: _____ Claim No: STW534311 / SL/01

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 21042018
(Client's Record)

CA / REV / REP. / REV 24 HRS 1401.2019 @ Tampines H.O.D. Endorsement:

Date/Time: 5/04/2018 1:35pm Person Contacted: Le Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SID 9538T - X
	SJR 5343U - CS/INCL10116TH/T16b3 DCA: B1220.10
17/1/19	Email preli revised to ERGO

REF: EOL

ASSIGNMENT

From: Date: 14-01-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 9568T

at Workshop m/s

Ethos

of

22 Tampines St 92.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD 9538T Yr Regn: 6.16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (4/

Make: Mazda 3

c.c. 1496

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 188995

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 2.1/4/18

D.O.I. 14/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 49870

21/1/19. L/S \$1600
 confirmed 1/5 \$1600 with J. my (Red 1188.60, 4390)

RECEIVED 21 FEB 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/2 - typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS: SI

Photos

Others

Report Format:

Lump Sum / I.B.I.: (\$

TP
1600/-

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SJQ 5343U/SL/pl

Our Ref: CS/EGI18007601/Uvb

Date: 17/1/2019

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLD 9538T

We thank you for your instruction on 25/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14/1/2019 at the premises of M/s ETHOZ GROUP LTD and have the following to report:-

Workshop Estimate Amount	: S\$2,788.60
Revised Estimate Amount	: S\$1,556.88
"Check" Items Amount	: S\$429.60
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 17 January 2019 11:30 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SJQ5343U / TP : SLD9538T/LKK / DOA : 21/04/2018
Attachments: SLD 9538T PRELI REVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLD 9538T
Date of survey: 14/1/2019
Number of days : 2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 25 April 2018 1:37 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: SJQ5343U / TP : SLD9538T/LKK / DOA : 21/04/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 25 April, 2018 12:26 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SJQ5343U / TP : SLD9538T/LKK / DOA : 21/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ETHOZ GROUP LTD.**

ADDRESS : 30 BUKIT BATOK CRESCENT
SINGAPORE 658075

PERSON TO CONTACT : LEE CHEN SIN @ 8822 8339 / 6654 7520

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 25 April, 2018 12:26 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SJQ5343U / TP : SLD9538T/LKK / DOA : 21/04/2018
Attachments: SJQ5343U - SAS.pdf; SLD9538T - SAS.pdf; SLD9538T - PRS FORM.pdf; SLD9538T - ESTIMATE.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ETHOZ GROUP LTD.**

ADDRESS : 30 BUKIT BATOK CRESCENT
SINGAPORE 658075

PERSON TO CONTACT : LEE CHEN SIN @ 8822 8339 / 6654 7520

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 25.04.2018
Our Reference: SJQ 5343U/SL/pl
Your Reference: SLD 9538T

To: ETHOZ GROUP LTD

Sent via Fax ☐
or
Email ☐ ChenSin.Lee@ethozgroup.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLD 9538T
Insured's Vehicle: SJQ 5343U
Date Of Accident: 21.04.2018


We acknowledge receipt of your request for PRS on: 25.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____

Time: _____

Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

ERGO

Date: 25.04.2018
Our Reference: SJQ 5343U/SL/pl
Your Reference: SLD 9538T

To: ETHOZ GROUP LTD

Sent via Fax ☐
or ☐
Email ☐ ChenSin.Lee@ethozgroup.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLD 9538T
Insured's Vehicle: SJQ 5343U
Date Of Accident: 21.04.2018


We acknowledge receipt of your request for PRS on: 25.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4531H
Vehicle Details	
Vehicle No.:	SLD9538T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	P520374200
Chassis No.:	JM6BM42A8G0345947
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,622.00
Original Registration Date:	30 Jun 2016
First Registration Date:	30 Jun 2016
Transfer Count:	1
Actual ARF Paid:	\$11,622.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jun 2026
PARF Rebate Amount:	\$8,716.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jun 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,200.00
COE Rebate Amount:	\$41,154.00
Total Rebate Amount:	\$49,870.00

The information contained herein is correct as at 15 Jan 2019

OK

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 25/04/2018
To : ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
	RESTORE R		
1	REAR BOOTLID	74.00	X
1	REAR BOOTLID EMBLEM CENTRE	53.40	X
1	REAR BOOTLID EMBLEM "MAZDA 3"	63.60	X
1	REAR BOOTLID EMBLEM "SKYACTIV"	1,074.60	
1	REAR BUMPER	59.00	
10	REAR BUMPER CLIPS	36.10	X
1	REAR BUMPER SIDE RETAINER LH	36.10	X
1	REAR BUMPER SIDE RETAINER RH	16.20	X
1	REAR BUMPER TOWING COVER LH		

Date : 25/04/2018
 To : ERGO INSURANCE PTE. LTD.
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
 Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER TOWING COVER RH	17 16.20	X
1	REAR BUMPER REFLECTOR LH	17 50.40	X
1	REAR BUMPER REFLECTOR RH	17 50.40	X
1	REAR BUMPER REINFORCEMENT	50 537.00	X
1	REAR END PANEL	RESTORE 2	X
Sub Total		2067.00	
Discount 20% On Parts		(413.40)	
<u>Special Nett Item</u>			
1	REVERSE SENSOR	SVL 200.00	X

1670.6

Date : 25/04/2018
To : **ERGO INSURANCE PTE. LTD.**

ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	200.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	400.00	280
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	20
	TO SPRAY PAINTING ON REAR AFFECTED AREA	400.00	320
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	X
	TO DETACH & RENEW REVERSE SENSOR	60.00	50

Date : 25/04/2018
 To : ERGO INSURANCE PTE. LTD.
 Attn : Motor Claim Department

ESTIMATION

FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
 Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	935.00	

Let's Make It Official! It's hence notify the Repairer of the following:

- To survey & inspect the damaged vehicle
- To display damaged parts during survey
- To place all damaged parts in a safe place
- Third party survey is not a "Without Prejudice" basis
- No illegal modification is allowed
- Survey report is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2,788.60

Remarks:

not Authorized

SUB TOTAL

GST 7.0 % 195.20

TOTAL 2,983.80

Surveyor's name:

mercus Hahr

Principal's name:

ETHOZ Group Ltd

Survey Date & Time:

4/5 1602/-
 Telephone Address
 24/4/19

PAGE : 4



Date : 17/01/2019

To : ERGO INSURANCE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTRENT000064 Accident Date : 21/04/2018

Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

FINAL ESTIMATED REPAIR COST DETAIL. Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	REAR BOOTLID RESTORE	0.00	0.00
1	REAR BOOTLID EMBLEM CENTRE	74.00	0.00
1	REAR BOOTLID EMBLEM "MAZDA 3"	53.40	0.00
1	REAR BOOTLID EMBLEM "SKYACTIV"	63.60	0.00
1	REAR BUMPER	1074.60	1074.60
10	REAR BUMPER CLIPS	55.00	55.00
1	REAR BUMPER SIDE RETAINER LH	36.10	0.00
1	REAR BUMPER SIDE RETAINER RH	36.10	0.00
1	REAR BUMPER TOWING COVER LH	16.20	0.00
1	REAR BUMPER TOWING COVER RH	16.20	0.00
1	REAR BUMPER REFLECTOR LH	50.40	0.00
1	REAR BUMPER REFLECTOR RH	50.40	0.00
1	REAR BUMPER REINFORCEMENT	537.00	537.00
1	REAR END PANEL RESTORE	0.00	0.00

Repair days: 02. P = \$1666.60 - 20% = \$1333.28

L = \$650.00

\$1983.28 - 20% = COR = \$1600.62 ✓

PAGE: 1




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18007601/Uvbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 21-02-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 5343U	Veh. Inspected	SLD 9538T	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJQ5343U/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	25/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0345947	Colour	GREY	
Odometer	188995	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	FALKEN	6 mm	
L/H Front Tyre	205/60 R16	FALKEN	6 mm	
R/H Rear Tyre	205/60 R16	FALKEN	6 mm	
L/H Rear Tyre	205/60 R16	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/04/2018	Inspection Date	14/01/2019	
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 9538T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR BOOTLID EMBLEM CENTRE	NOT NECESSARY	74.00	-
1	REAR BOOTLID EMBLEM "MAZDA 3"	NOT NECESSARY	53.40	-
1	REAR BOOTLID EMBLEM "SKYACTIV"	NOT NECESSARY	63.60	-
1	REAR BUMPER	DENTED / DEFORMED	1,074.60	1,074.60
10	REAR BUMPER CLIPS	NECESSARY	59.00	59.00
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	36.10	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	36.10	-
1	REAR BUMPER TOWING COVER LH	NOT NECESSARY	16.20	-
1	REAR BUMPER TOWING COVER RH	NOT NECESSARY	16.20	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	50.40	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	50.40	-
1	REAR BUMPER REINFORCEMENT	DENTED	537.00	537.00
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-413.40	-334.12
			1,653.60	1,336.48
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-
LABOUR				
	LABOUR TO CARRY OUT REAR REPAIR. INCLUSIVE OF THE REPAIR OF REAR BOOTLID AND REAR END PANEL.		400.00	280.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		35.00	20.00
	TO SPRAY PAINTING ON REAR AFFECTED AREA.		400.00	320.00
	SPRAY RUST PROOF ON AFFECTED AREA.	NOT NECESSARY	40.00	-
	TO DETACH & RENEW REVERSE SENSOR.		60.00	50.00
			935.00	670.00



GRAND TOTAL		2,788.60	2,006.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/EG18007601/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.