

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 25/04/2018
To : ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
1	REAR BOOTLID	RESTORE	
1	REAR BOOTLID EMBLEM CENTRE	74.00	
1	REAR BOOTLID EMBLEM "MAZDA 3"	53.40	
1	REAR BOOTLID EMBLEM "SKYACTIV"	63.60	
1	REAR BUMPER	1,074.60	
10	REAR BUMPER CLIPS	59.00	
1	REAR BUMPER SIDE RETAINER LH	36.10	
1	REAR BUMPER SIDE RETAINER RH	36.10	
1	REAR BUMPER TOWING COVER LH	16.20	

Date : 25/04/2018
To : ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER TOWING COVER RH	16.20	
1	REAR BUMPER REFLECTOR LH	50.40	
1	REAR BUMPER REFLECTOR RH	50.40	
1	REAR BUMPER REINFORCEMENT	537.00	
1	REAR END PANEL	RESTORE	
	Sub Total	2067.00	
	Discount 20% On Parts	(413.40)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR	200.00	

Date : 25/04/2018
To : ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD
ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	200.00	
	<u>Labour & Misc</u>		
	LABOUR TO CARRY OUT REAR REPAIR	400.00	
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	
	TO SPRAY PAINTING ON REAR AFFECTED AREA	400.00	
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	
	TO DETACH & RENEW REVERSE SENSOR	60.00	

Date : 25/04/2018
To : ERGO INSURANCE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.
Certificate No : D17MTRENT000064 Accident Date : 21/04/2018
Vehicle No : SLD-9538-T Make & Model : MAZDA 3 1.5 (A) SEDAN STANDARD

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	935.00	

2,788.60

Remarks:

SUB TOTAL

GST 7.0 % 195.20

TOTAL 2,983.80

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____