

ESTIMATE FOR SKG6985B

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 65073848 Vehicle & Document Information

23126

Reg No/Reg Date SKG6985B / 28/09/2012

Date In/Mileage 25/04/2018/-76184

Chassis No WDD2040312A741947

Engine No

Make/Model MB/C 180 CGI BlueEFFICIENCY

Colour/Trim 027 775 Iridium sil/ 042 228 Leather Alp

Account No	Terms	Date/Time Printed	CSE	Operator			
WF001862	Credit	22/06/2018/ 11:33	YK	395 / Yik Chan Hoe	,		
		Description of Goods /	Services	Qty	Unit Price	Disc%	Amount

WIP No

M. BPNSUN POLICY NO ACC DATE: D. 17088618MVPC X 29.04/2018 FCAL AX VOC

DATE IN/DATE SURVEY: 25/04/2018 @ 1635 // RASUL LKK BY/AUTHRIZED ON : 25/04/2018 @ 1635 // RASUL LKK

S BPNSUB
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM,
WHEEL BALANCE AND INSTALL NEW VALVE HEAD

X LEFT FRONT BUMPER CHROME MOULDING
X RIGHT FRONT BUMPER CHROME MOULDING

1.00 85.10 00.00 85.10 00.00 85.10 N

60.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 230.20 230.20 16.11

7% GST on

.

Authorized signatory and company stamp

Total Payable 246.31

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding 657. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring



the removal of the windscreen.

WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg