Sulveylor Milmun — From (Person	ASSIGNMENT OF C	(Onice)	Date/Time: 25-04-2018 11.10am
Estimated Co.	t:	Bill to:	
OD / TP/r W	STTP RESTOD RESTEVATING MYTCS SHIC 1600B		Insured: SJh 2700U
at Workshop	m/s Chunni mutch		Tel: 6511) 6119
of	BIK 10 AMK INd Park	2A #01	-05
Policy No:	F0F14281011829970	Claim No: _	9NM18D02093C02
Sum Insured:		Excess:	
Make of Veh (Client's Recor			D.O.A. 330112018
CA / REV Date/Time:	REP. / REV 24 HRS WP1 25042018 11-18 Um Person Contacted:	Film	H.O.D. Endorsement Vehicle OUT
Date/Time	Action/Instruction (🗸) Estimate		
	SHC 1600B- NA / TMIL12001293	/WI	DUAT: 18012012
	939 2700U - C9/C7216017945		Oca: 190916

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status		
Main	25 Apr 2018		25 Apr 2018 14:18 Assign				New Assignment Cancel Case	it	
	Main	Γ	Reference		Claim Details	Doc	uments	Show All	
CLAIM S	UBFOLDER DET	TAILS			AND DESCRIPTION OF TAXABLE PARTY.		Created by insur	er]	
Insured:		ANG	ENG HOE						
Main Clair	mant:	COM	FORT TRANSPOR	TATION PTE	LTD				
Vehicle Re	eg. No.:	SHO	1600B		Date of Loss:	1	23/04/2018 16:00 -	:59	
Claim Typ	e:	TP	SNM18D02093	C02	Policy/Cover Note No.	: 1	DMPCSN101854170	7	
Vehicle Re	eg. No. (Insured)	: SJG:	2700U		Policy No. (Claimant):				
					Excess:		S\$0.00		
Repairer:		Chu 6483	nni Motor Work P	te Ltd - Amk	(HQ) Blk 10 #01-05/0	06, AMK Autopoin	it, 568047 Ang Ma K	(lo - Tel:	
Handling)	Insurer:	Chin 6174		ice (Singapo	re) Pte. Ltd. (HQ) - 1	Tel: 6389 6111	. [Handled by Jowy	n Tay - 6389	
Adjuster:		17.000		Pte Ltd (HO) - Tel: 6256-3561	Final Rpt du	e 07/05/20181		
Adj Asg. R	Remarks:		R KALVIN, PLEASE S		PARTY, CHECK CONS			OUT PREJUDIO	
ASSOCIA	TED MAIL REC	EIVED				V	lew All Compo	se Case Mail	
There are	no mail for this o	case.							
8									
ALL ASS	OCIATED TASK	cs			View All S	Search Tasks	Create New Task	Complete	
Due Da		Type Tas	k Group Subje	ct Handle	er Assigned By	Completed	On Created		

Catherine Chong (LKK Auto)

From:

Angie Foo <angie.foo@sq.cntaiping.com>

Sent:

Wednesday, 25 April, 2018 11:10 AM

To:

Chunni Motor

Cc:

Jowyn Tay; Admin A; assignments@lkkauto.com; SUR

Subject:

RE: OUR REF: PRS/SNM18D02093C02/0 & YR REF: SHC1600B- TO CONDUCT PRE

REPAIR SURVEY - SHC1600B

Without Prejudice

Dear Lynn/Irene,

We refer to your email on even date.

We have appointed Kalvin Ang of M/S LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:

Dear Kalvin,

Please arrange to conduct survey, checking consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Jowyn Tay 63896174.

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Co.Reg.No.200208384E DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com Email: claimsdept@sg.cntaiping.com Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [mailto:chunnimotor@gmail.com]

Sent: Wednesday, 25 April, 2018 10:43 AM

To: Angie Foo Cc: Jowyn Tay

Subject: Re: OUR REF: PRS/SNM18D02093C02/0 & YR REF: SHC1600B- TO CONDUCT PRE REPAIR SURVEY -SHC1600B

92 OUT 80 g/92
Dear Angie,
We agree to appoint Kalvin Ang
Thank you
Regards, Chunni Motor Work P/L
On Tue, Apr 24, 2018 at 5:23 PM, Angie Foo <angie.foo@sg.cntaiping.com> wrote:</angie.foo@sg.cntaiping.com>
WITHOUT PREJUDICE
Dear Lynn/Irene,
We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.
We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.
TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Jowyn Tay 6389 6174

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping,com

Email: claimsdept@sq.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

MCD818053407 / ComforDelGro Engineering Pte Ltd - Loyang ENTRY DATE & TIME: 24/04/2018 11:04 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver,

- 3. Information provided must be as truthful and eccurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the Gondral Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesald,	, and the second
	ACCIDENT STATEMENT
Date Of Report	24/04/2018 11:04
Date Of Accident	23/04/2018 16:45
Exact Location Of Accident	ALONG CTE TWDS SLE NEAR UPP SERANGOON
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHC1600B
Insured/Policyholder	D 8
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)
Exact Purpose for which vehicle was being used a time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD

Name of Insurance Company THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

YES Fleet Policy

D-18088936MFSH Policy Number

Cover Note Number

Driver

PNG YEOW HUAT Name of Driver

S0181357I NRIC No 01/10/1951 Date Of Birth OUTDOOR Occupation 13/04/1972 Date Of Driving Pass

46 YEARS AND 0 MONTHS Driving Experience

MALE Gender

Mobile Number Fax Number Contact Number

NOEMAIL EMail Address

Address

BLK 181 BEDOK NORTH ROAD

#18-28

Postcode

460181 NO

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - TAXI DRIVER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

5

Was any body injured in the Accident?

YES

NO

Was any injured conveyed to hospital by

ambulance?

NO YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO 2

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJG2700U

Vehicle Make/Model/Colour

Details Of Properties

HONDA

Vehicle Category

PRIVATE CAR

Name of Driver

ANG ENG HOE

NRIC/Passport Number

S6837744G

Contact Number

90297854

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

Page 2 of 27

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLC6129R

Vehicle Make/Model/Colour

MERCEDES

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

UNSURE

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR UNKNOWN Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

UNSURE

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

PNG YEOW HUAT

Approximate Age

Injuries Sustain

NECK, SHOULDER AND CHEST

Injured person in which vehicle?

SHC1600B

Were seat belts worn?

YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

Page 3 of 27

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 2 4 APR 2018

Driver's Signature (If driver is not the policyholder)


Date & Time: 2 4 APR 2018

1015 hrs

Reporting Centre Personnel's Signature

LISA DIONG Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/04/2018 @ 16:4	45hrs,my taxi (A) SHC 1600B was travelling along CTE towards SLE near Upp Serango
with 1 female passeng	er on board.
I was on the extreme	ight lane 1,I saw the infront of me vehicle slow down and stopped,So I follow too.
There was a loud impa	act coming from the rear portion and caused my taxi (A) to lose control and surge
forward and colliding	onto the veh (C) rear portion.My taxi (A) front and rear portion was damaged.l assessed
the damages to my ta	xi (A) and come to know that there were 5 vehicles involved in the chain accident.
The parties involved i	n the accident are :
A-SHC 1600B.	
B-SJG 2700U-Mr And	g Eng Hoe.S 6837744G.Hp:9029 7854.
C-SLC 6129R-Mr Lin	Hiang Sek Alvin.S 7724706H.Hp:8418 7882.
D-Unknown	
E-Unknown	
After the accident,I fe	elt pain on neck,shoulder and chest,will see doctor later on.
81 91	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 2 4 APR 2018

Driver's Signature 2 4 APR 2018

(If driver is not the policyholder)

97

Reporting Centre Personnel's Signature Name: LISA DIONG

1018 hes

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

3821R

Vehicle Details

Vehicle No.:

SHC1600B

Vehicle to be

Yes

Exported:

Intended De-

24 Apr 2018

registration Date:

Vehicle Make:

HYUNDAI

Vehicle Model:

SONATA NF 2.0 CRDI

AT ABS 2WD 4DR

TURBO

Primary Colour:

Blue

Manufacturing Year:

2012

Engine No.:

D4EAC071039

Chassis No.:

KMHET41VMCA823218

Maximum Power

110.0 kW (147 bhp)

Output:

Open Market Value:

\$14,622.00

Original Registration

19 Apr 2012

Date:

First Registration

19 Apr 2012

Date:

Transfer Count:

0

Actual ARF Paid:

\$14,622.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry

18 Apr 2020

Date:

PARF Rebate Amount:

\$9,504.00

Intended COE Rebate Details

COE Expiry Date:

18 Apr 2020

A - Car (1600cc &

COE Category:

below)

COE Period(Years):

Q

PQP Paid:

\$42,384.00

COE Rebate Amount:

\$10,519.00

Total Rebate Amount:

\$20,023.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Apr 2018

4/24/2018, 9:46 A

of 2

CHUNNI MOTOR WORK PTE LTD

Soon Hock ;-

REPAIR ESTIMATE*

VEHICLE NO : SHC 1600B

DATE : 24.04.2018

MAKE

:

TEL : 6542 5119 FAX : 6542 6039

Qty Qty	: HYUNDAI SONATA Parts Description/ Labour	Type	Unit	Price		Amount	1
							1
	Bonnet True	7,00			\$	1,151.80	٠
	Bonnet Lock				S	48.80	-
	Radiator Grille by Ku				S	282.10	
	Radiator Grille U Moulding brikes				s	108.90	
	Front Bumper Cover				S	538.80	i
	Front Bumper Sponge		1		S	136.30	
	Front Bumper Reinforcement				S	504.10	
	Front Bumper Grille (LH/RH)		s	17.60	S	35.20	1
	Front Bumper Centre Grille		3	17.00	s	131.10	ľ
	Front Bumper Lip				S	59.90	L
	Headlamp Support Panel Assy broke				S	1,023.00	
	Headlamp (LH/RH)		s	797.90	S	1,595.80	
	Radiator		9	191.90	S	814.80	
	Aircon Condenser				S	1,089.90	1.
					S	771.50	1
	Inter Cooler				S	3,187.40	1.
	Wiring-Engine % NA				1000		
	Wiring-ECM HA		819	6.90 7.52	\$	3,107.80	
	SUB TOTAL				S	14,587.20	1
	LESS 20%		(55	7.52	S	2,917.44	
	DISCOUNTED TOTAL				\$	11,669.76	1
							1
	Art.						
							١
	Front Number Plate of what ye of				s	25.00	,
	Front No Plate Trim Cover by ken				100	5 30.00	
	Front No Flate Trim Cover SWAZA		401		1	-1 20.00	I.
					\$	55.00	1
	d d				-		1
/-	.4						
	Labour Charge					(00.05	
	Panel Beating				S	600.00	. 1
	Spray Painting Charge				S	500.00	- 1
	Wiring Charge				S	50.00	- 1
	Tuff Kote		00	1	S	-80.00	. 1
	Towing Charge		970	1-	S	50.00	
		10	1		1		ار

SHC 1600B

				SITE	, 1600B
Qty Parts Description/ Labour	Туре	Unit	Price		mount
Boot Lid Inc				S	1,349.50
Boot Lid Sonata Plate Place		1		S	43.60
Boot Lid Hyundai Plate Hec		1	1	\$	24.20
Boot Lid 'H' Emblem Haz		12		S	26.10
Boot Lid CRDI Plate Her				S	22.70
Boot Lid Lamp (LH/RH) Carole		S	230.20	S	460.40
Boot Lid Trimboard de Torman		109754	NORTH NEW YORK	S	165.40
Boot Lid Trimboard Clips (11pcs)				S	11.00
Rear Bumper			1	S	578.40
Rear Bumper Reinforcement				S	483.30
Rear Bumper Clip				S	22.00
Rear Bumper Bracket Sylv		s	49.00	S	98.00
		_	12.00	S	137.40
Rear Bumper Sponge				S	185.80
Rear Bumper Under Cover + 0 V		s	38.00	S	76.00
Rear Bumper Protector (LH/RH)		S	344.00	S	688.00
Tail Lamp (LH/RH) broken		3	344.00	1 3	
Rear Panel Krc		1		S	391.80 95.80
Rear Panel Garnish & Tomal				- 33	
Spare Tyre Holder SVC			217.40	S	27.60
Tail Lamp Panel Top (LH/RH) NS Kee als Cy		S	217.40	S	434.80
Spare Tyre Panel Fuc				S	863.00
Spare Tyre Panel Cushion				S	200.30
Rear Towing Hook				S	135.30
Member Assy- Rear Floor Centre (4)				S	163.60
Panel Assy-Rear Floor Side (LH/RH)		S	88.55	S	177.10
Rear Floor Chassis Member				S	1,280.50
Exhaust Pipe Insulator		1		S	56.10
Exhaust Silencer 1951		1		S	723.00
Exhaust Pipe Hanger				S	56.10
Rear Fender (LH/RH) Fine		S	1,935.90	885	3,871.80
Rear Fender Inner Panel (LH/RH)		S	1,255.00	S	2,510.00
Rear Fender Inner Lining (LH/RH)		S	74.10	S	148.20
Rear Fender Corner Hardboard Cover (LH)				S	204,30
Rear Tray Lugg Side (RH) 5				S	37.40
Rear Fender Air-Duct 3/		1		S	49.40
Rear Fender Trim Board (LH/RH)		S	180.90	S	361.80
Rear Windscreen Moulding		130	05.50	s	60.00
SUB TOTAL		104	04.40	S	16,219.70
LESS 20%		109	01.70	S	3,243.94
DISCOUNTED TOTAL				S	12,975.76
DISCOULTED TOTAL					
Boot Lid Comfort Logo & Tel No. Sticker 14				\$	
Rear No.Plate Charle			0	\$	25.00
Rear Bumper Reverse Sensor				S	135.70
Rear Bumper Advertisement Logo				S	50.00
Rear Fender Advertisement Logo (LH/RH) Nec		S	100.00	S	200.00
Rear Windscreen Sealant NC		35	1.00	S	46.00
	l	1		S	486.70

SHC 1600B

	Parts Description/ Labour	Type.	Unit Price	Amount
Qty	Labour Charge	Type:	Cinc a like	
	Panel Beating			\$ 1,600.00
	Spray Painting Charge			\$ 950.00
	- [1.5	\$ 50.00
	Wiring Charge			\$ 80.00
	Tuff Kote		- \	\$ 120.00
	Remove/Refix Rear Windscreen Glass		21501-	3 120.00
			750	\$ 2,800.00
	TOTAL LABOUR			3 2,800.00
	ESTIMATE TOTAL			\$ 29,267.22
				20472.92
	26/04/2018 @ 1100m			
	26/04/2018 @ 1100m NOT Avolumed HSrm 12 2 dgs.			4516000
	1/5×11/2			
	Try des.			
	1 KK Ado			
LKK Auto	Qui sultants hence notify			
mic wans	It ut the following:			
 IO resurvi 	ey before/after spray painting			
Per signer	damaged part(s) during resurvey es are subject to confirmation			
* 10 (d part)	y Survey is on a "Without Drainding" has in			
- MO INCOME				
* Suppleme is subject (intary item(s) must be resurveyed and to final approval from Insurance Company			
	The state of the s			
Signature:	ed by Repairer			
Date:				
	.6			
			1	
	9			
		1		
			1	
	This is an initial estimate based on a visual inspection of t	he above v	ehicle. The final rep	air quantum will
	be prepared after the vehicle is surveyed by a motor Surveyed	eyor appoi	nted by the insurance	e company.

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI18007609/DTBN2 Our File No:

31/05/2018 Date:

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMPCSN1018541707

Claimant

SHC1600B

Insured Vehicle No:

SJG2700U

TP

Vehicle No: Date of Loss: 23/04/2018

Nature of Claim:

Claim No:

SNM18D02093C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHC1600B

Make & Model:

HYUNDAI SONATA, 2.0 (A)

Engine No: Chassis No: D4EAC071039 KMHET41VMCA823218

Reg. Date: Colour:

19/04/2012 (Man. Year: 2012) Blue

Odometer:

256658 km

Engine Capacity:

1991 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes

Yes Footbrake (Serviceable): Steering (Serviceable): General Condition:

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

No Pre-accident Condition:

Front Tyre Size: Front Left Side:

215/60R16 West Lake 5 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60R16 West Lake 5 mm West Lake 5 mm

Front Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 25,187.22	Adjuster's 17,352.92	Difference 7.834.30	Diff % 31.10
Miscellaneous Items	0.00	0.00	0.00	
Labour Paintwork Labour	4,080.00 0.00	3,120.00 0.00	960.00 0.00	23.53
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	29,267.22	20,472.92 16,000.00	8,794.30	30.05
(S\$)	29,267.22	16,000.00	13,267.22	45.33
+ GST 7.00/7.00% (S\$)	2,048.71	1,120.00	928.71	45.33
Nett Amount (S\$)	31,315.93	17,120.00	14,195.93	45.33

INSPECTION

Date of Assignment:

25/04/2018

Date Inspected:

26/04/2018 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint

Singapore 568047

Estimated Period of Repair:

12.0 days

Manager: DENISE TAY KWEE CHENG Adjuster: BRYAN TANI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 31 May 2018)

Parts:

143

HYUNDAI SONATA 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC1600B)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled		*1,151.80 FL
2	1		*BONNET LOCK	Bent	48.80 FL	
3	1		*RADIATOR GRILLE	Broken	282.10 FL	
4	1		*RADIATOR GRILLE U MOULDING	Broken	108.90 FL	
5	1		*FRONT BUMPER COVER	Buckled	538.80 FL	
3	1		*FRONT BUMPER SPONGE	Torn	136.30 FL	
7	1		*FRONT BUMPER REINFORCEMENT	Bent	504.10 FL	
3	2		*FRONT BUMPER GRILLE LH/RH	Serviceable	35.20 FL	
9	1		*FRONT BUMPER CENTRE GRILLE	Deformed	131.10 FL	
10	1		*FRONT BUMPER LIP	Serviceable	59.90 FL	
11	1		*HEADLAMP SUPPORT PANEL ASSY	Broken		*1,023.00 FL
12	2		*HEADLAMP (LH/RH)	Broken		*1,595.80 FL
13	1		*RADIATOR	Bent		*814.80 FL
14	1		*AIRCON CONDENSER	Punctured	1,089.90 FL	*1,089.90 FL
15	1		*INTER COOLER	Bent	771.50 FL	
16	1		*WIRING-ENGINE	Not Necessary	3,187.40 FL	
17	1		*WIRING-ECM	Not Necessary	3,107.80 FL	
18	1		*BOOT LID	Buckled	1,349.50 FL	*1,349.50 FL
19	1		*BOOT LID SONATA PLATE	Necessary	43.60 FL	
20	1		*BOOT LID HYUNDAI PLATE	Necessary	24.20 FL	*24.20 FL
21	1		*BOOT LID H EMBLEM	Necessary	26.10 FL	
22	1		*BOOT LID CRDI PLATE	Necessary	22.70 FL	*22.70 FL
23	2		*BOOT LID LAMP (LH/RH)	Cracked	460.40 FL	*460.40 FL
24	1		*BOOT LID TRIMBOARD	Deformed	165.40 FL	*165.40 FL
25	11		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	
26	1		*REAR BUMPER	Buckled	578.40 FL	*578.40 FL
27	1		*REAR BUMPER REINFORCEMENT	Broken	483.30 FL	
28	10		*REAR BUMPER CLIP	Necessary	22.00 FL	
29	2		*REAR BUMPER BRACKET	Serviceable	98.00 FL	
30	1		*REAR BUMPER SPONGE	Torn	137.40 FL	. *137.40 FL
31	1		*REAR BUMPER UNDER COVER	Torn	185.80 FL	*185.80 FL
32	2		*REAR BUMPER PROTECTOR (LH/RH)	Bent	76.00 FL	*76.00 FL
33	2		*TAIL LAMP (LH/RH)	Broken	688.00 FL	*688.00 FI
34	1		*REAR PANEL	Buckled	391.80 FL	*391.80 FI
35	1		*REAR PANEL GARNISH	Deformed	95.80 FI	*95.80 FI
36	1		*SPARE TYRE HOLDER	Serviceable	27.60 Fl	
37	1		*TAIL LAMP PANEL TOP (LH/RH)	N/s Buckled/O/s Repair	434.80 FI	
38	1		*SPARE TYRE PANEL	Buckled	863.00 FI	*863.00 FI
39	1		*SPARE TYRE PANEL CUSHION	Bent	200.30 FI	
40	1		*REAR TOWING HOOK	Bent	135.30 FI	*135.30 F
	- 13		*MEMBER ASSY-REAR FLOOR CENTRE	Repair	163.60 FI	- *-F
41 42	1 2		*PANEL ASSY-REAR FLOOR SIDE (LH/RH)	Buckled	177.10 F	

No.	Qty	Part No.	Particulars	Condition F	Repairer's	Amount
43	1		*REAR FLOOR CHASSIS MEMBER	Buckled		*1,280.50 FL
44	1		*EXHAUST PIPE INSULATOR	Bent	56.10 FL	
45	1		*EXHAUST SILENCER	Bent	723.00 FL	
46	1		*EXHAUST PIPE HANGER	Torn	56.10 FL	*56.10 FL
47	2		*REAR FENDER (LH/RH)	Buckled		*3,871.80 FL
48	2		*REAR FENDER INNER PANEL (LH/RH)	Repair	2,510.00 FL	*-FL
49	2		*REAR FENDER INNER LINING (LH/RH)	Serviceable	148.20 FL	
50	1		*REAR FENDER CORNER HARDBOARD COVER (LH)	Bent	204.30 FL	
51	1		*REAR TRAY LUGG SIDE (RH)	Bent	37.40 FL	
52	1		*REAR FENDER AIR-DUCT	Serviceable	49.40 FL	
53	2		*REAR FENDER TRIM BOARD (LH/RH)	Deformed	361.80 FL	
54	1		*REAR WINDSCREEN MOULDING	Necessary	60.00 FL	
55	1		*FRONT NUMBER PLATE	Dislodged	25.00 FS	
56	1		*FRONT NO PLATE TRIM COVER	Broken	30.00 FS	
57	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	
58	1		*REAR NO PLATE	Cracked	25.00 FS	
59	1		*REAR BUMPER REVERSE SENSOR	Not fitted	135.70 FS	
60	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	
61	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	
62	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
F=Fr	anchise	part. S=	SpcNett. L=ListItemDisc.		L. Copperate	ALL AND
				Sub Total (S\$)	31,348.60	21,593.40
			- List Item Discount on L	Items 20.00/20.00% (S\$)	6,161.38	4,240.48
				Total Parts (S\$)	25,187.22	17,352.92
	_		Report was unsubmitted during	ng this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	2,200.00	1,700.00
2	SPRAY PAINTING CHARGE	New	1,450.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	160.00	80.00
5	TOWING CHARGE	New	50.00	19
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
	Gross I	Gross Labour Cost (S\$)		3,120.00
	Report was unsubmitte	d during this print out		

< END OF ESTIMATES >