

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB340M
 Ref. No : TAX/04/18/2115
 Reg. Date : 19/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : CHENG WAI YIP
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 23/04/2018 12:22:00 PM
 Accident Reported Date / Time : 23/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095696
 Special Instruction to ARC, if any :
 SJJ2862U
 Prepared Date : 23/04/2018 03:34:15 PM



Sebastian.
 24/4/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405750591

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	845.00	0.00
Total Spray Painting Charges :	936.00	0.00
Total Material Charges :	2,417.78	2,417.78
Other Charges :	1,351.88	0.00
TOTAL :	5,550.66	0.00
Lum Sum Total :	5,550.00	0.00
No. of Repair Days :	5.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sing Off Date :	23/04/2018 05:53:32 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/04/2018 05:53:32 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	845.00	0.00 300
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 X
TO RESPRAY REAR PANEL	180.00	0.00 100
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00 150
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
Total Other Costs	1,351.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ☒ CRK
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ☒ DT
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No ☒ ?
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ☒ ?
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No ☒ X
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ☒ X
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ☒ NRC
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ☒ ?
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace	No ☒ ?
31604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	☒ No ☒ ?
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ☒ X
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ☒ X
32710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No ☒ X
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ☒ X
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No ☒ ?
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ☒ ?
TOTAL MATERIALS							3,022.25	3,022.22		
TOTAL MATERIALS(Discounted)							2,417.78	2,417.78		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									