

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Li Zi Rong

Date: 24 May 2018

## **Preliminary Advice**

Insured Vehicle No	: SJS5009A	Accident Date	: 23/04/2018
TP Vehicle No	: SJY9388Y	Assignment Date	: 25/04/2018
Make	: TOYOTA ALLION	Est. Duration of Repair	: 6DAYS
Date of Inspection	: 25/04/2018		
Inspection At	: JOO HAK KEE AUTO PTE LTD		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...REAR.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,086.73
Revised Amount	:S\$	4,654.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,654.08
Lump Sum Repair	:S\$	3,700.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.