

A: REC. BY:

REF:

CS/FCL18007619/8vbn2

Special Instruction:

Survivor:

Sebastian

ASSIGNMENT (Office)

From (Person):

CWS May Chui

of

FCL

Date/Time:

25/04/2018 9:17am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 8218A

Insured:

SHC 1470J

at Workshop m/s

World Auto

Tel:

6362 1776

of

No. 1 Kranji Loop

Policy No:

Claim No:

D18003179MTRSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/04/2018

CA / REV / REP. / REV 24 HRS wpe

H.O.D. Endorsement:

Date/Time:

25/04/2018 10:05am

Person Contacted:

Daniel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 8218A - X
	SHC 1470J - CS/FCL11000857 / UPR
	DA: 30122010
27/4/18	Email preli revised to FCI
27/4/18	Final fig \$ 17,192.64 confirmed by email (Ref 6308.40, 27/4)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lump Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Sebastian,

P/S see my remarks.

RECEIVED @ 2 JUL 2018

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

1/1 - typist

Report Format:

Lump Sum / I.B.L. (\$)

CWS

17,192.64

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Handy Shuttle

Colour

White

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

13x15 = 195

170+195

50

50

98

563



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18003179MFSH
Our ref: CS/FCI18007619/Svb

Date: 27/4/18

The Motor Claims Department
M/s First Capital Insurance Limited

Without Prejudice

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 8218A


We thank for your instruction on 25/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 25/4/2018 at the premises of M/s WORLD AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$23,501.04
Revised Estimate Amount	: S\$17,192.64
"Check" Items Amount	: S\$3,390.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front n/s portion and n/s front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

YEANG WAI KEEN
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	23-04-2018	Our Ref No. D18003179MFSH
Accident Date	21-04-2018	Claim Type. Third Party
Insured Vehicle	SHC1470J	Third Party Vehicle. SLR8218A
Survey Location	NO.1, KRANJI LOOP	
Contact Person.	DANIEL	
Contact No.	63621776/ 0	Fax No. 64557576
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 April 2018 12:21 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003179MFSH/1, SLR 8218A
Attachments: SLR 8218A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLR 8218A
Date of survey: 25/4/2018
Number of days: 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 25 April 2018 10:10 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003179MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 25 April, 2018 9:17 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003179MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 2 July 2018 2:52 PM
To: 'tggtan@worldauto.com.sg'
Cc: SUR
Subject: RE: PENDING FINALIZE

Dear Sophia,

Noted with thanks.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: tggtan@worldauto.com.sg [mailto:tggtan@worldauto.com.sg]
Sent: Monday, 2 July 2018 2:45 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: PENDING FINALIZE

Hi Veron

Finalised COR @ \$17192.64 and 10 days of repairs.

Rdgs
Sophia Tan
World Auto Pte Ltd (Kranji)

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Friday, 29 June 2018 3:50 PM
To: tggtan@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: PENDING FINALIZE

Dear Sophia,

WITHOUT PREJUDICE

Finalize amount \$17,192.64 before GST @ 10 working days

Kindly confirmed.

Best Regards,

Veron.Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 25 June 2018 5:34 PM

To: tggtan@worldauto.com.sg

Subject: PENDING FINALIZE

Dear Sophia,

Kindly advise vehicle status.

If vehicle has been repaired, please forward us resurvey photos for finalize.

- 1) SLR 8218A-DOA: 21/4/2018
- 2) SLE 9188P-DOA: 14/5/2018

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Sketch Plan #6





Reg No: 52977287 J

CASH SALE/WORK ORDER

迅速拖車服務

SPEEDWAY RECOVERY SERVICE

Singapore Post Centre Post Office P.O. Box 201 Singapore 914007

Tel: 6841 0080

No: C 22424

Date: 24/4/18

Name/Company World Motos

Vehicle No. SLR 8218A Model Shuttle

From 517 T.P. Pond

To 1 karnji loop

Remarks _____

Time: : - : - :

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

vl
Tow Truck

24 HRS TOWING SERVICE
6841 0080

www.speedwayrecovery.com
Email: speedwaytowing@gmail.com

- ☐ Jump Start
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo Payment
- ☐ Trips

Amount \$ 60h

Khang
Received By

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201856

Date : 24/04/2018

Vehicle Num. : SLR 8218A (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 21/04/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT BUMPER ✓ CRK 1200		1,100.00 ✓ CRK
2.	1	FRONT BUMPER REINFORCEMENT ✓ DT		485.80 ✓ DT
3.	1	FRONT BUMPER UNDERDUST COVER ✓ Deform		175.00 ✓ Deform
4.	2	FRONT BUMPER SIDE RETAINER ✓ MS	78.00	156.00 ✓ MS
5.	1	FRONT BUMPER LOWER GRILLE ✓ CH		122.00 ✓ CH
6.	1	FRONT FENDER LH ✓ DT		489.90 ✓ DT
7.	1	FRONT FENDER BRACKET LH ?		60.00 X NN
8.	1	FRONT FENDER UNDER DUST COVER LH ✓ Deform		192.00 ✓ Deform
9.	1	FRONT FENDER HYBRID EMBLEM LH ✓ NEC		88.60 ✓ NEC
10.	1	FRONT WHEELHOUSE INNER PANEL LH ✓ Deform ?		198.00 X } NN
11.	1	FRONT WHEELHOUSE OUTER PANEL LH ✓ Deform ?		215.00 X } NN
12.	1	FRONT WHEELHOUSE EXTENSION INNER PANEL LH ✓ Deform		85.00 ✓ Deform
13.	1	FRONT WHEELHOUSE EXTENSION OUTER PANEL LH ✓ Deform		95.00 ✓ Deform
14.	1	FRONT GRILLE BASE ✓ CRK		248.00 ✓ CRK
15.	1	FRONT GRILLE CHROME MOULDING ✓ NEC		228.00 ✓ NEC
16.	1	FRONT GRILLE LOWER CHROME MOULDING ✓ NEC		198.00 ✓ NEC
17.	1	FRONT GRILLE CENTRE LOCK BRACKET X		118.00 X NN
18.	2	HEADLAMP ASSY RH/LH LH SCR RH NN @3625	780.00	1,560.00 780
19.	2	HEADLAMP LOWER BRACKET LH CRK RH NN	64.00	128.00 64
20.	1	SIDE MIRROR LH X		420.00 X NN
21.	1	SIDE MIRROR COVER - LH R		60.00 R
22.	1	ENGINE CROSSMEMBER SUBFRAME ?		980.00 X
23.	1	ENGINE CROSSMEMBER SUBFRAME BRACKET LH ?		160.00 X
24.	1	FRONT SHOCK ABSORBER - LH ?		450.00 X
25.	1	FRONT LOWER ARM - LH ?		268.00 X } NN
26.	1	FRONT KNUCKLE - LH ?		326.00 X
27.	1	FRONT WHEEL HUB LH ?		220.00 X
28.	1	FRONT WHEEL BEARING - LH ?		190.00 X
29.	1	FRONT STABILIZER LINK LH ?		188.00 X
30.	1	FRONT STABILIZER BAR ?		360.00 X
31.	1	AUDIBLE SENSOR ✓ CRK		180.00 ✓ CRK
32.	1	DASHBOARD ✓ NEC		2,152.00 ✓ NEC
33.	1	DRIVER AIRBAG ✓ Activated		2,380.00 ✓ Activated
34.	1	FRONT PASSENGER AIRBAG ✓ Activated		2,480.00 ✓ Activated

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201856

Date : 24/04/2018

Vehicle Num. : SLR 8218A (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 21/04/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
35.	1	STEERING AIRBAG SLIP RING ✓ NEC } photo		648.00 ✓ NEC
36.	1	STEERING ANGLE SENSOR ✓ NEC		310.00 ✓ NEC
37.	2	FRONT AIRBAG IMPACT SENSOR ✓ NEC	185.00	370.00 ✓ NEC
38.	1	FRONT SEATBELT RH ✓ JM		1,298.00 ✓ JM
39.	1	FRONT SEATBELT BUCKLE RH X		328.00 X NN
40.	1	FRONT SEATBELT LH ✓ JM		1,298.00 ✓ JM
41.	1	FRONT SEATBELT BUCKLE RH X		328.00 X } NN
42.	1	STEERING TIE ROD LH ?		90.00 X }
43.	1	STEERING TIE ROD END LH ?		120.00 X }
44.	1	AIRBAG CONTROL MODULE ✓ NEC — photo		1,580.00 ✓ NEC
List Total S\$:				23,126.30
20.00% Discount S\$:				4,625.26
				18,501.04
SPECIAL NETT ITEMS :				
1.	1	FRONT BUMPER CLIP	30	30.00 ✓ NEC
2.	1	FRONT BUMPER UNDERDUST COVER CLIPS		30.00 ✓ NEC
3.	1	FRONT FENDER UNDER DUST COVER CLIPS		30.00 ✓ NEC
4.	1	WHEEL RIM ?		150.00 X } NN
5.	1	TYRE ?		180.00 X }
6.	1	TOWING CHARGE ✓		60.00 ✓
Special Nett Total S\$:				480.00
LABOUR :				
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			30	180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS			1250	1,600.00
UNDERCARRIAGE REPAIRS INCLUDING REPLACING ABOVE UNDERCARRIAGE PARTS			250	380.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

FIRST CAPITAL INSSURANCE LIMITED

80 ROBINSON RD #09-02/03

068898

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES201856

Date : 24/04/2018

Vehicle Num. : SLR 8218A (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 21/04/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND REPLACE SRS SYSTEM COMPONENTS INCLUDING DASHBOARD, SEATBELTS, ETC	300	480.00
		PERFORM WHOLE VEHICLE DIAGNOSTIC CHECK INCLUDING RESETTNG SRS SYSTEM AND CLEARING FAULT CODES DUE TO COLLISION	250	280.00
		PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER, PEARL WHITE)	1200	1,600.00
		Labour Total S\$:		4,520.00

10 days.

Sebastian
25/4/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint

90030121

sebastianyeng@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O.E.**Total S\$: 23,501.04**

=====



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18007619/Vvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1470J	Veh. Inspected	SLR 8218A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003179MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	25/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71046138	Colour	WHITE	
Odometer	31177	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	PIRELLI	6 mm	
L/H Front Tyre	185/60 R15	PIRELLI	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/04/2018	Inspection Date	25/04/2018	
Survey held at	NO 1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8218A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CRACKED	1,100.00	1,100.00
1	FRONT BUMPER REINFORCEMENT	DENTED	485.80	485.80
1	FRONT BUMPER UNDERDUST COVER	DEFORMED	175.00	175.00
2	FRONT BUMPER SIDE RETAINER @\$78.00	MISSING	156.00	156.00
1	FRONT BUMPER LOWER GRILLE	CUT	122.00	122.00
1	FRONT FENDER LH	DENTED	489.90	489.90
1	FRONT FENDER BRACKET LH	NOT NECESSARY	60.00	-
1	FRONT FENDER UNDER DUST COVER LH	DEFORMED	192.00	192.00
1	FRONT FENDER HYBRID EMBLEM LH	NECESSARY	88.60	88.60
1	FRONT WHEELHOUSE INNER PANEL LH	NOT NECESSARY	198.00	-
1	FRONT WHEELHOUSE OUTER PANEL LH	NOT NECESSARY	215.00	-
1	FRONT WHEELHOUSE EXTENSION INNER PANEL LH	DEFORMED	85.00	85.00
1	FRONT WHEELHOUSE EXTENSION OUTER PANEL LH	DEFORMED	95.00	95.00
1	FRONT GRILLE BASE	CRACKED	248.00	248.00
1	FRONT GRILLE CHROME MOULDING	NECESSARY	228.00	228.00
1	FRONT GRILLE LOWER CHROME MOULDING	NECESSARY	198.00	198.00
1	FRONT GRILLE CENTRE LOCK BRACKET	NOT NECESSARY	118.00	-
2	HEADLAMP ASSY RH/LH @\$780.00	N/S SCRATCHED / O/S NOT NECESSARY	1,560.00	780.00
2	HEADLAMP LOWER BRACKET @\$64.00	N/S CRACKED / O/S NOT NECESSARY	128.00	64.00
1	SIDE MIRROR LH	NOT NECESSARY	420.00	-
1	SIDE MIRROR COVER-LH	TO REPAIR SEE LABOUR	60.00	-
1	ENGINE CROSSMEMBER SUBFRAME	NOT NECESSARY	980.00	-
1	ENGINE CROSSMEMBER SUBFRAME BRACKET LH	NOT NECESSARY	160.00	-
1	FRONT SHOCK ABSORBER-LH	NOT NECESSARY	450.00	-
1	FRONT LOWER ARM-LH	NOT NECESSARY	268.00	-
1	FRONT KNUCKLE-LH	NOT NECESSARY	326.00	-
1	FRONT WHEEL HUB LH	NOT NECESSARY	220.00	-
1	FRONT WHEEL BEARING-LH	NOT NECESSARY	190.00	-

Report Ref No. CS/FCI18007619/Vvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER LINK LH	NOT NECESSARY	188.00	-
1	FRONT STABILIZER BAR	NOT NECESSARY	360.00	-
1	AUDIBLE SENSOR	CRACKED	180.00	180.00
1	DASHBOARD	NECESSARY	2,152.00	2,152.00
1	DRIVER AIRBAG	ACTIVATED	2,380.00	2,380.00
1	FRONT PASSENGER AIRBAG	ACTIVATED	2,480.00	2,480.00
1	STEERING AIRBAG SLIP RING	NECESSARY	648.00	648.00
1	STEERING ANGLE SENSOR	NECESSARY	310.00	310.00
2	FRONT AIRBAG IMPACT SENSOR @\$185.00	NECESSARY	370.00	370.00
1	FRONT SEATBELT RH	JAMMED	1,298.00	1,298.00
1	FRONT SEATBELT BUCKLE RH	NOT NECESSARY	328.00	-
1	FRONT SEATBELT LH	JAMMED	1,298.00	1,298.00
1	FRONT SEATBELT BUCKLE RH	NOT NECESSARY	328.00	-
1	STEERING TIE ROD LH	NOT NECESSARY	90.00	-
1	STEERING TIE ROD END LH	NOT NECESSARY	120.00	-
1	AIRBAG CONTROL MODULE	NECESSARY	1,580.00	1,580.00
	LESS 20% DISCOUNT		-4,625.26	-3,440.66
			18,501.04	13,762.64
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	FRONT BUMPER UNDERDUST COVER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT FENDER UNDER DUST COVER CLIPS (SN)	NECESSARY	30.00	30.00
1	WHEEL RIM (SN)	NOT NECESSARY	150.00	-
1	TYRE (SN)	NOT NECESSARY	180.00	-
			420.00	90.00
	<u>LABOUR</u>			
	TOWING CHARGE.		60.00	60.00
	WIRING CHECK AND RECTIFY WHERE NECESSARY.		180.00	30.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF SIDE MIRROR COVER-LH.		1,600.00	1,250.00

Report Ref No. CS/FCI18007619/Vvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	UNDERCARRIAGE REPAIRS INCLUDING REPLACING ABOVE UNDERCARRIAGE PARTS.		380.00	250.00
	REMOVE AND REPLACE SRS SYSTEM COMPONENTS INCLUDING DASHBOARD, SEATBELTS, ETC.		480.00	300.00
	PERFORM WHOLE VEHICLE DIAGNOSTIC CHECK INCLUDING RESETTING SRS SYSTEM AND CLEARING FAULT CODES DUE TO COLLISION.		280.00	250.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER, PEARL WHITE).		1,600.00	1,200.00
			4,580.00	3,340.00
GRAND TOTAL			23,501.04	17,192.64
RECOMMENDED COST OF REPAIRS				17,192.64

Report Ref No. CS/FCI18007619/Vvbn2

SATHYA SAI KATHIRASEN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.