

ASS. REC. BY:

REF: CS/CTU8007620/RHB 52

Special Instruction:

SURVAYOR

Resul.

ASSIGNMENT (Office)

From (Person): Irene Tay of CTL Date/Time: 24/04/2018 5:04pm

Estimated Cost: Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SLH 8901T Insured: GT 547B

at Workshop m/s Ding Auto Tel:

of Blk 10 Simming Ind Est #01-20

Policy No: DMCVSN1529101702 Claim No: SUMISD02074C02

Sum Insured: Excess:

Make of Veh: D.O.A. 21042018

(Client's Record)

CA / REV / REP. / REV 24 HRS up 249 Jln Boon Lay H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle - IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH 8901T - x
	GT 547B - x
	Part by Part \$1995.25. 4 days
	(Red: 4099.50; 67%)

Signature: *[Signature]*
Name: *Surinder Malhi*

REF: *CTI*

4597K

ASSIGNMENT

From: _____ Date: *25012018*

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLG 8901T*

at Workshop m/s: *Ding Auto*

of: *249 Jln Boon Lay*

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLG 8901T* Yr Regn: *2016 / 6CT*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *TOYOTA COROLLA ALTIS 1.6 c.c 1598*

Colour: *grey* A/C: ☒ Insured / Std / NI / NA

Sp. Reading: *146474* T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: *MR053RKH104558040*

Gen. Cond: Good ☒ Fair / Poor / Burnt

Steering: ☒ Jammed / Leaked / Burnt or

Brake: ☒ Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim or

Tyre Size: F: *205/55R16*
R: *-*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / *YOKO* or

Front: *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *21/04/18* D.O.I. *26/04/18*

Survey held at: *Ding Auto*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 JUL 2018

Date/Time, File Pass to?

1) *9A Typist* ☐ : Preli. Report

☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee: *220*

Transportation

☐ S + RS ☐ SI

☐ Photos

☐ Others

TOTAL

Report Format: *TP*

Lump Sum / I.E.I. (\$) *1995.25*

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Apr 2018		24 Apr 2018 17:04 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:		LEE HIANG FOODSTUFF SUPPLIER, Co. Reg. No.: -		[Created by insurer]
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K			
Vehicle Reg. No.:	SLG8901T	Date of Loss:	21/04/2018 22:00 - :59	
Claim Type:	TP / SNM18D02074C02	Policy/Cover Note No.:	DMCVSN1529101702 (Third Party Only)	
Vehicle Reg. No. (Insured):	GT547B	Policy No. (Claimant):	999995061	
		Excess:	S\$0.00	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/05/2018]			
Driver/Custodian (Insured):	KANG YOUN HONG (46 / Male), NRIC: S7117106Z, Tel: +6598479272			
Adj Asg. Remarks:	NO EST, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/04/2018 17:24
Date Of Accident	21/04/2018 22:00
Exact Location Of Accident	352 ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG8901T
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995061
Cover Note Number	

Driver

Name of Driver	CHUA TONG TECK ALANTERRY
NRIC No	S7424099B
Date Of Birth	05/08/1974
Occupation	OUTDOOR
Date Of Driving Pass	22/11/1995
Driving Experience	22 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90077674
Fax Number	
Contact Number	
Email Address	NOEMAIL

Postcode 560649
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GT547B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

→ 352 ALEXANDRA RD

Source of Evidence → Photo from my phone
Photo Date: 21/4/18 Saturday 2200

SKETCH PLAN

QUEEN'S
CONDO



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

B HIT A VEHICLE

- AS A UBER DRIVER @ 2149 HRS ON 21/04/18 SATURDAY I GOT A REQUESTED BY UBER RIDER FROM: 10 STIRLING RD S'148954 (QUEEN'S CONDO) GOING TO 20 UPPER CIRCULAR RD S'058416
- WHILE TRAVELLING TOWARDS QUEEN'S CONDO, AT 352 ALEXANDRA RD TURN RIGHT TO COMMERWEALTH AVE, BUT THERE WAS 3-4 CAR MOVING IN-TURN, SO I GOT TO WAIT FOR THE U-TURN CAR CLEAR BEFORE I CAN TURN OUT, BUT SUDDENLY A VAN ~~BE~~ TURN OUT FROM ^{THE} REAR OF MY CAR & HIT MY R-H-R BUMPER AREA! BUT DIDN'T STOP & ^{DRIVER} OFF & SUDDENLY STOP AT THE ROAD SIDE OF COMMERWEALTH AVE! (INITIAL INTENTION- HIT & RUN) WHEN I CAME OUT OF MY CAR HE HAD TURNED & STOP ONE SIDE

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

23/4/18
150040

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

24/04/2018 10:20

JOB-NO: 85008272

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLG8901T

TRANS: AUTO

CHASSIS: MR053REH104558040

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY332975

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,400.00	0.00	1,400.00		Y	<u>3004.00</u>
2 TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS,REAR BUMPER,REAR FENDER RHS,REAR REINFORCEMENT & ARM,END PANEL	1.00	1,200.00	0.00	1,200.00		Y	<u>400</u>
3 TO CHECK & REPAIR REAR TAIL LAMP & WIRING SYSTEM	1.00	120.00	0.00	120.00		Y	<u>30</u>
4 RUST PROOFING	1.00	180.00	0.00	180.00		Y	<u>20</u>
5 R & R REVERSE SENSOR & WIRING SYSTEM	1.00	150.00	0.00	150.00		Y	<u>60</u>
TOTAL:		3,050.00	0.00	3,050.00			

MATERIALS

1 REAR BUMPER	1.00	490.00	122.50	367.50	L	Y	<u>15</u>
2 REAR BUMPER SIDE RETAINER LONG RHS	1.00	105.00	26.25	78.75	L	Y	<u>7.50</u>
3 REAR BUMPER SIDE RETAINER SHORT RHS	1.00	80.00	20.00	60.00	L	Y	<u>7.50</u>
4 REAR BUMPER CLIP	1.00	35.00	8.75	26.25	L	Y	<u>10</u>
5 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	<u>X</u> <u>300</u>
6 REAR BUMPER REINFORCEMENT ARM RHS	1.00	105.00	26.25	78.75	L	Y	<u>X</u> <u>300</u>
7 REAR BUMPER REFLECTOR RHS	1.00	65.00	16.25	48.75	L	Y	<u>50</u>
8 TAIL LAMP INNER RHS	1.00	294.00	73.50	220.50	L	Y	<u>100</u>
9 TAIL LAMP OUTER RHS	1.00	378.00	94.50	283.50	L	Y	<u>100</u>
10 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	L	Y	<u>Repair</u>
11 REAR FENDER INNER SHIELD RHS	1.00	68.00	17.00	51.00	L	Y	<u>X</u> <u>300</u>
12 REAR FENDER INNER SHIELD CLIP	1.00	35.00	8.75	26.25	L	Y	<u>X</u> <u>300</u>
13 REAR FENDER AIR VENT	1.00	168.00	42.00	126.00	L	Y	<u>X</u> <u>300</u>
14 REAR FENDER INNER PANEL TRIM RHS	1.00	390.00	97.50	292.50	L	Y	<u>X</u> <u>300</u>
15 REAR FENDER INNER PANEL TRIM CLIPS RHS	1.00	35.00	8.75	26.25	L	Y	<u>X</u> <u>300</u>
16 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	<u>X</u>
TOTAL:		3,973.00	928.25	3,044.75			

TOTAL PARTS & LABOUR: 7,023.00 928.25 6,094.75

EXCESS/LOADING: S\$ 0.00

No. Of Day: 4 days

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
RE-SURVEY BEFORE AFTER PAINTING							
PART-BY-PART OR LUMP SUM \$							
DATE OF SURVEY:	26	04	18 @ 0900				
SURVEYED BY:		RASUL (LKK)					
CONTACT NO:	90010068	FAX NO:					

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DING AUTO PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

24/04/2018 10:20

OWNER'S PARTICULARS

JOB-NO: 85008272

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLG8901T

TRANS: AUTO

CHASSIS: MR053REH104558040

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY332975

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,400.00	0.00	1,400.00		Y	<u>300</u> 400
2 TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS,REAR BUMPER,REAR FENDER RHS,REAR REINFORCEMENT & ARM,END PANEL	1.00	1,200.00	0.00	1,200.00		Y	<u>400</u>
3 TO CHECK & REPAIR REAR TAIL LAMP & WIRING SYSTEM	1.00	120.00	0.00	120.00		Y	<u>30</u>
4 RUST PROOFING	1.00	180.00	0.00	180.00		Y	<u>20</u>
5 R & R REVERSE SENSOR & WIRING SYSTEM	1.00	150.00	0.00	150.00	910	Y	<u>60</u>
TOTAL:		3,050.00	0.00	3,050.00			

MATERIALS

1 REAR BUMPER	1.00	490.00	122.50	367.50	L	Y	<u>15</u>
2 REAR BUMPER SIDE RETAINER LONG RHS	1.00	105.00	26.25	78.75	L	Y	<u>2</u>
3 REAR BUMPER SIDE RETAINER SHORT RHS	1.00	80.00	20.00	60.00	L	Y	<u>2</u>
4 REAR BUMPER CLIP	1.00	35.00	8.75	26.25	L	Y	<u>1</u>
5 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	<u>X</u>
6 REAR BUMPER REINFORCEMENT ARM RHS	1.00	105.00	26.25	78.75	L	Y	<u>X</u>
7 REAR BUMPER REFLECTOR RHS	1.00	65.00	16.25	48.75	L	Y	<u>SEA</u>
8 TAIL LAMP INNER RHS	1.00	294.00	73.50	220.50	L	Y	<u>CR</u>
9 TAIL LAMP OUTER RHS	1.00	378.00	94.50	283.50	L	Y	<u>CR</u>
10 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	L	Y	<u>Repair</u>
11 REAR FENDER INNER SHIELD RHS	1.00	68.00	17.00	51.00	L	Y	<u>X</u>
12 REAR FENDER INNER SHIELD CLIP	1.00	35.00	8.75	26.25	L	Y	<u>X</u>
13 REAR FENDER AIR VENT	1.00	168.00	42.00	126.00	L	Y	<u>3</u>
14 REAR FENDER INNER PANEL TRIM RHS	1.00	390.00	97.50	292.50	L	Y	<u>X</u>
15 REAR FENDER INNER PANEL TRIM CLIPS RHS	1.00	35.00	8.75	26.25	L	Y	<u>X</u>
16 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	<u>X</u>
TOTAL:		3,973.00	928.25	3,044.75			

TOTAL PARTS & LABOUR :

7,023.00 P/P 928.25 6,094.75

EXCESS/LOADING:SS 0.00

No. Of Day:

4 days

Parts: 1085.25

S/N: 0

Labour: 910

Total: 1995.25

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
RE-SURVEY BEFORE AFTER PAINTING							
PART-BY-PART OR LUMP SUM \$							
DATE OF SURVEY:	26	104	18	0900			
SURVEYED BY:	RASUL (LKK)						
CONTACT NO:	90010068	FAX NO:					

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	24 Apr 2018		24 Apr 2018 17:04 Edit Adj Rpt	S\$1,995.25 Edit Estimates	S\$1,995.25 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE HIANG FOODSTUFF SUPPLIER, Co. Reg. No.: -		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLG8901T	Date of Loss:	21/04/2018 22:00 - :59 [18 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D02074C02	Policy/Cover Note No.:	DMCVSN1529101702 (Third Party Only)
Vehicle Reg. No. (Insured):	GT547B	Policy No. (Claimant):	999995061
		Excess:	S\$0.00
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/05/2018]		
Driver/Custodian (Insured):	KANG YOUN HONG (46 / Male), NRIC: S7117106Z, Tel: +6598479272		
Adj. Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















Claim Documents

***SLG8901T (SNM18D02074C02)**
[GT547B]
TP
LCRF PTE LTD
Apr 21 2018 10:00PM
[LEE HIANG FOODSTUFF SUPPLIER]
Ding Auto Pte Ltd












[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 17:35	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	23/04/18 17:34	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/07/18 16:53	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/07/18 16:54	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
16	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/07/18 16:54	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	09/07/18 16:54	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/04/18 17:04	PRS	 Load PDF	
2	24/04/18 17:04	OI GIA REPORT	 Load PDF	
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	23/04/18 17:35	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	23/04/18 17:35	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print	
1	23/04/18 17:35	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print	
1	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
6	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
7	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
8	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
9	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
10	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
11	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
12	23/04/18 17:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports					<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	23/04/18 17:35	Sketch Plan		Load TIF	
2	23/04/18 17:35	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18007620/R1TBS2

Date: 12/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSN1529101702

Claimant Vehicle No: SLG8901T

Insured Vehicle No: GT547B

Date of Loss: 21/04/2018

Nature of Claim: TP

Claim No: SNM18D02074C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG8901T

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)

Engine No: 1ZRY332975

Reg. Date: 17/10/2016 (Man. Year: 2016)

Chassis No: MR053REH104558040

Colour: Grey

Odometer: 146474 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,044.75	1,085.25	1,959.50	64.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	910.00	2,140.00	70.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,094.75	1,995.25	4,099.50	67.26
+ GST 7.00/7.00% (S\$)	426.63	139.67	286.96	67.26
Nett Amount (S\$)	6,521.38	2,134.92	4,386.46	67.26

INSPECTION

Date of Assignment: 24/04/2018

Date Inspected: 26/04/2018

Inspected At:

249 JLN BOON LAY
Repairer: Ding Auto Pte Ltd

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jul 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG8901T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	490.00 FL	*490.00 FL
2	1		*REAR BUMPER SIDE RETAINER LONG RHS	Necessary	105.00 FL	*105.00 FL
3	1		*REAR BUMPER SIDE RETAINER SHORT RHS	Necessary	80.00 FL	*80.00 FL
4	1		*REAR BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Serviceable	380.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT ARM RHS	Serviceable	105.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RHS	Scratched	65.00 FL	*65.00 FL
8	1		*TAIL LAMP INNER RHS	Cracked	294.00 FL	*294.00 FL
9	1		*TAIL LAMP OUTER RHS	Cracked	378.00 FL	*378.00 FL
10	1		*REAR FENDER RHS	Repair	1,085.00 FL	*- FL
11	1		*REAR FENDER INNER SHIELD RHS	Serviceable	68.00 FL	*- FL
12	1		*REAR FENDER INNER SHIELD CLIP	Serviceable	35.00 FL	*- FL
13	1		*REAR FENDER AIR VENT	Serviceable	168.00 FL	*- FL
14	1		*REAR FENDER INNER PANEL TRIM RHS	Not Necessary	390.00 FL	*- FL
15	1		*REAR FENDER INNER PANEL TRIM CLIPS RHS	Not Necessary	35.00 FL	*- FL
16	1		*REAR REVERSE SENSOR	Not Necessary	260.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	3,973.00	1,447.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	928.25	361.75
Total Parts (\$\$)	3,044.75	1,085.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED DAMAGED BODY PARTS, REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS.	New	1,400.00	400.00
2	TO PUTTY & SPRAY PAINTING ON THE AFFECTED AREAS, REAR BUMPER, REAR FENDER RHS, REAR REINFORCEMENT & ARM, END PANEL.	New	1,200.00	400.00
3	TO CHECK & REPAIR REAR TAIL LAMP & WIRING SYSTEM.	New	120.00	30.00
4	RUST PROOFING.	New	180.00	20.00
5	R&R REVERSE SENSOR & WIRING SYSTEM.	New	150.00	60.00
Gross Labour Cost (S\$)			3,050.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >